

DOE/WIPP 05-3177  
Volume 1

**Geotechnical Analysis  
Report  
For  
July 2003 – June 2004**

March 2005



Waste Isolation Pilot Plant

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

This document has been submitted as required to:

Office of Scientific and Technical Information  
P.O. Box 62  
Oak Ridge, TN 37831  
(615) 576-8401

Additional information about this document may be obtained by calling (800) 336-9477.  
Copies may be obtained by contacting the National Technical Information Service,  
U.S. Department of Commerce, 5285 Port Royal Road, Springfield, VA 22161

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

## **Foreword and Acknowledgments**

---

This report contains an assessment of the geotechnical status of the Waste Isolation Pilot Plant (WIPP). During the excavation of the principal underground access and experimental areas, the status was reported quarterly. Since 1987, when the initial construction phase was completed, reports have been published annually. This report presents and analyzes data collected from July 1, 2003, to June 30, 2004.

This Geotechnical Analysis Report (GAR) was written to meet the needs of several audiences. This report satisfies the requirements presented in the WIPP Hazardous Waste Permit<sup>1</sup> and the Certification of Compliance<sup>2</sup> with Subparts Band C, Title 40 *Code of Federal Regulations* (CFR) Part 191, "Environmental Radiation Protection Standards for Management and Disposal of Spent Nuclear Fuel, High-Level and Transuranic Radioactive Wastes." It focuses on the geotechnical performance of the various components of the underground facility, including the shafts, shaft stations, access drifts, and waste disposal areas. The results of investigations of excavation effects and other geologic studies are also included. The report compares the geotechnical performance of the repository to the design criteria. It describes the techniques that were used to acquire the data and the performance history of the instruments. The depth and breadth of the evaluation of the different components of the underground facility vary according to the types and quantities of data available and the complexity of the recorded geotechnical responses. Graphic documentation of data and tabular documentation of instrument history can be provided upon request.

This GAR was prepared by Washington TRU Solutions LLC (WTS) for the U.S. Department of Energy (DOE), Carlsbad Field Office (CBFO), Carlsbad, New Mexico. Work was supported by the DOE under Contract No. DE-AC29-01AL66444.

---

<sup>1</sup> New Mexico Environment Department (NMED), 1999, "Waste Isolation Pilot Plant Hazardous Waste Facility Permit," NM4890139088-TSDF, Santa Fe, New Mexico

<sup>2</sup> Federal Register, Vol. 63, No. 95, pp. 27354, May 18, 1998

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

This Page Intentionally  
Left Blank

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

## Table of Contents

---

Acronyms and Abbreviations .....	v
1.0 Introduction .....	1-1
1.1 Location and Description .....	1-1
1.2 Mission .....	1-4
1.3 Development Status .....	1-4
1.4 Purpose and Scope of Geomechanical Monitoring Program .....	1-6
1.4.1 Instrumentation .....	1-7
1.4.2 Data Acquisition .....	1-7
1.4.3 Data Evaluation .....	1-8
1.4.4 Data Errors .....	1-9
2.0 Geology .....	2-1
2.1 Regional Stratigraphy .....	2-1
2.1.1 Castile Formation .....	2-1
2.1.2 Salado Formation .....	2-3
2.1.3 Rustler Formation .....	2-3
2.1.4 Dewey Lake Redbeds .....	2-4
2.1.5 Dockum Group .....	2-4
2.1.6 Gatuña Formation, Mescalero Caliche, and Surficial Sediments .....	2-4
2.2 Underground Facility Stratigraphy .....	2-5
2.2.1 Disposal Horizon Stratigraphy (Panels 1, 2, 7, and 8) .....	2-5
2.2.2 Disposal Horizon Stratigraphy (Panels 3, 4, 5, and 6) .....	2-6
2.2.3 Northeast Area Stratigraphy .....	2-8
3.0 Performance of Shafts and Keys .....	3-1
3.1 Salt Handling Shaft .....	3-1
3.1.1 Shaft Observations .....	3-3
3.1.2 Instrumentation .....	3-3
3.2 Waste Shaft .....	3-7
3.2.1 Shaft Observations .....	3-9
3.2.2 Instrumentation .....	3-9
3.3 Exhaust Shaft .....	3-12
3.3.1 Exhaust Shaft Observations .....	3-12
3.3.1.1 Video Camera .....	3-12
3.3.1.2 Shaft Inspection Observations .....	3-13
3.3.2 Instrumentation .....	3-22
3.4 Air Intake Shaft .....	3-25
3.4.1 Shaft Performance .....	3-25
3.4.2 Instrumentation .....	3-25
4.0 Performance of Shaft Stations .....	4-1
4.1 Salt Handling Shaft Station .....	4-1
4.1.1 Modifications to Excavation and Ground Control Activities .....	4-1
4.1.2 Instrumentation .....	4-1

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

4.2	Waste Shaft Station.....	4-4
4.2.1	Modifications to Excavation and Ground Control Activities .....	4-4
4.2.2	Instrumentation .....	4-6
4.3	Air Intake Shaft Station .....	4-10
4.3.1	Modifications to Excavation and Ground Control Activities .....	4-10
4.3.2	Instrumentation .....	4-10
5.0	Performance of Access Drifts.....	5-1
5.1	Modifications to Excavation and Ground Control Activities .....	5-1
5.2	Instrumentation .....	5-1
5.2.1	Borehole Extensometers .....	5-1
5.2.2	Convergence Points .....	5-1
5.3	Analysis of Convergence Point and Extensometer Data .....	5-3
5.4	Excavation Performance .....	5-8
6.0	Performance of Waste Disposal Area .....	6-1
6.1	Modifications to Excavations and Ground Control Activities.....	6-1
6.2	Instrumentation .....	6-2
6.3	Excavation Performance .....	6-9
6.4	Analysis of Extensometer and Convergence Point Data .....	6-12
7.0	Geoscience Program.....	7-1
7.1	Borehole Inspections.....	7-1
7.2	Fracture Mapping.....	7-3
8.0	Summary .....	8-1
9.0	References and Bibliography .....	9-1

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**List of Tables**

Table 1-1 Geomechanical Instrumentation System .....	1-8
Table 3-1 Water Removed from the Exhaust Shaft Catch Basin.....	3-19
Table 3-2 Collar Displacement at the Exhaust Shaft Extensometers .....	3-22
Table 4-1 Vertical Closure Rates in the Salt Handling Shaft Station .....	4-4
Table 4-2 Summary of Roof Extensometers in Waste Shaft Station.....	4-6
Table 4-3 Horizontal Closure Rates in the Waste Shaft Station.....	4-10
Table 5-1 Summary of Modifications and Ground Control Activities in the Access Drifts July 1, 2003, through June 30, 2004 .....	5-2
Table 5-2 New and Replaced Convergence Points Installed in the Access Drifts July 1, 2003, through June 30, 2004 .....	5-3
Table 5-3 Increases in Annual Vertical Convergence Rates Greater than 10 Percent in the Access Drifts .....	5-8
Table 6-1 Summary of Modifications and Ground Control Activities in the Waste Disposal Area from July 1, 2003, to June 30, 2004 .....	6-2
Table 6-2 New and Replaced Convergence Points in the Panel 1 Entries from July 1, 2003, to June 30, 2004 .....	6-6
Table 6-3 New and Replaced Convergence Points in Panel 2 from July 1, 2003, to June 30, 2004 .....	6-6
Table 6-4 New and Replaced Convergence Points in Panel 3 from July 1, 2003, to June 30, 2004 .....	6-7
Table 6-5 Annual Convergence Rates in the S1600 Panel 1 Entry .....	6-10
Table 6-6 Annual Convergence Rates in the S1950 Panel 1 Entry .....	6-10
Table 6-7 Annual Vertical Convergence Rates at the Center of Panel 2 Rooms .....	6-11
Table 6-8 Annual Horizontal Convergence Rates at the Center of Panel 2 Rooms (Mid-Rib) .....	6-11
Table 8-1 Comparison of Excavation Performance to System Design Requirements .....	8-3

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**List of Figures**

Figure 1-1 WIPP Location.....	1-2
Figure 1-2 Underground Mining and Waste Disposal Configuration as of 6/30/04.....	1-3
Figure 2-1 Regional Geology.....	2-2
Figure 2-2 Repository Level Stratigraphy (Panels 1, 2, 7 and 8) .....	2-7
Figure 2-3 Repository Level Stratigraphy (Panels 3, 4, 5 and 6) .....	2-9
Figure 3-1 Salt Handling Shaft Stratigraphy .....	3-2
Figure 3-2 Salt Handling Shaft Instrumentation (Without Shaft Key) .....	3-4
Figure 3-3 Salt Handing Shaft Key Instrumentation .....	3-5
Figure 3-4 Waste Shaft Stratigraphy.....	3-8
Figure 3-5 Waste Shaft Instrumentation (Without Shaft Key) .....	3-11
Figure 3-6 Waste Shaft Key Instrumentation .....	3-12
Figure 3-7 Exhaust Shaft Stratigraphy.....	3-15
Figure 3-8 Sample Exhaust Shaft Intake Air Monitoring System .....	3-16
Figure 3-9 Diagram of Exhaust Shaft Fixtures (200 ft Upper Portion) .....	3-17
Figure 3-10 Exhaust Shaft Instrumentation (Without Shaft Key) .....	3-23
Figure 3-11 Exhaust Shaft Key Instrumentation .....	3-24
Figure 3-12 Air Intake Shaft Stratigraphy .....	3-27
Figure 4-1 Salt Handling Shaft Station Stratigraphy .....	4-2
Figure 4-2 Salt Handling Shaft Station Instrumentation After Roof Beam Excavation.....	4-3
Figure 4-3 Waste Shaft Station Stratigraphy .....	4-5
Figure 4-4 Waste Shaft Station Instrumentation After Wall Trimming .....	4-8
Figure 5-1 Typical Convergence Point Array Configurations Showing Anchor Designations .....	5-6
Figure 6-1 Location of Panel 1 Entry Geotechnical Instruments .....	6-3
Figure 6-2 Location of Panel 2 Geotechnical Instruments .....	6-4
Figure 6-3 Location of Panel 3 Geotechnical Instruments .....	6-5
Figure 7-1 Examples of Observation Borehole Layouts .....	7-2
Figure 7-2 Generalized Fracture Pattern at Lower Horizon .....	7-2

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

## **Acronyms and Abbreviations**

---

b.p.	before present
bsc	below shaft collar
CAO	Carlsbad Area Office
CBFO	Carlsbad Field Office
CFR	Code of Federal Regulations
CH	contact-handled
cm	centimeter(s)
DOE	U.S. Department of Energy
EPA	U.S. Environmental Protection Agency
ft	foot (feet)
GAR	Geotechnical Analysis Report
GIS	geomechanical instrumentation system
HWFP	Hazardous Waste Facility Permit
in.	inch(es)
Km	kilometer(s)
kPa	kilopascal(s)
kVA	kilovolt amp(s)
LANL	Los Alamos National Laboratory
lb	pound(s)
m	meter(s)
Ma	million years ago
MB	marker bed
NMED	New Mexico Environment Department
OMB	orange marker bed
psi	pound(s) per square inch
RH	remote-handled
SDD	system design description
SNL/NM	Sandia National Laboratories/New Mexico
SPDV	Site and Preliminary Design Validation

**Geotechnical Analysis Report for July 2003 – June 2004  
DOE/WIPP 05-3177, Vol. 1**

TRU transuranic  
WIPP Waste Isolation Pilot Plant  
WTS Washington TRU Solutions LLC  
yr(s) year(s)

## **1.0 Introduction**

---


This Geotechnical Analysis Report (GAR) presents and interprets the geotechnical data from the underground excavations at the Waste Isolation Pilot Plant (WIPP). The data, which are obtained as part of a regular monitoring program, are used to characterize conditions, to compare actual performance to the design assumptions, and to evaluate and forecast the performance of the underground excavations.

GARs have been available to the public since 1983. During the Site and Preliminary Design Validation (SPDV) Program, the architect/engineer for the project produced these reports on a quarterly basis to document the geomechanical performance during and immediately after excavation of the underground facility. Since the completion of the construction phase of the project in 1987, the management and operating contractor for the facility has prepared these reports annually. This report describes the performance and condition of selected areas from July 1, 2003, to June 30, 2004. It is divided into nine chapters. Chapter 1 provides background information on WIPP, its mission, and the purpose and scope of the Geomechanical Monitoring Program. Chapter 2 describes the local and regional geology of the WIPP site. Chapters 3 and 4 describe the geomechanical instrumentation located in the shafts and shaft stations, present the data collected by that instrumentation, and provide interpretation of these data. Chapters 5 and 6 present the results of geomechanical monitoring in the two main portions of the WIPP underground facility (the access drifts and the Waste Disposal Area). Chapter 7 discusses the results of the Geoscience Program, which include fracture mapping and borehole observations. Chapter 8 summarizes the results of the geomechanical monitoring and compares the current excavation performance to the design requirements. Chapter 9 lists the references and bibliography.

### **1.1 Location and Description**


WIPP is located in southeastern New Mexico, 26 miles (42 kilometers [km]) east of Carlsbad (Figure 1-1). The surface facilities were built on the flat to gently rolling hills that are characteristic of the Los Medaños area. The underground facility is being excavated approximately 2,150 feet [ft] (655 meters [m]) beneath the surface in the Salado Formation. Figure 1-2 shows a plan view of the underground configuration of WIPP as of June 30, 2004.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 1-1 WIPP Location**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 1-2 Underground Mining and Waste Disposal Configuration as of 6/30/04**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

## **1.2      Mission**

In 1979 Congress authorized WIPP (Public Law 96-164, National Security and Military Applications of Nuclear Energy Authorization Act of 1980) to provide ". . . a research and development facility to demonstrate the safe disposal of radioactive wastes resulting from the defense activities and programs of the United States exempted from regulation by the Nuclear Regulatory Commission." WIPP is intended to receive, handle, and permanently dispose of transuranic (TRU) waste and TRU mixed waste. To fulfill this mission, the U.S. Department of Energy (DOE) constructed a full-scale facility to demonstrate both technical and operational principles of the permanent disposal of TRU and TRU mixed wastes. Technical aspects are those concerned with the design, construction, and performance of the subsurface excavations. Operational aspects refer to the receiving, handling, and emplacement of TRU wastes in the facility. The facility was also used for *in situ* studies and experiments without the use of radioactive waste.

## **1.3      Development Status**

To fulfill its mission, the DOE developed WIPP in a phased manner. The goal of the SPDV phase, begun in 1980, was to characterize the site and obtain *in situ* geotechnical data from underground excavations to determine whether site characteristics and the *in situ* conditions were suitable for a permanent disposal facility. During this phase, the Salt Handling Shaft, a ventilation shaft, a drift to the southernmost extent of the proposed waste disposal area, a four-room experimental panel, and access drifts were excavated. Surface-based geological and hydrological investigations were also conducted. The data obtained from the SPDV investigations were reported in the "Summary of the Results of the Evaluation of the WIPP Site and Preliminary Design Validation Program" (DOE, 1983).

Based upon the favorable results of the SPDV investigations, additional activities were initiated in 1983. These included the construction of surface structures, conversion of the ventilation shaft for use as the waste shaft, excavation of the Exhaust Shaft, development of additional access drifts to the waste disposal area, excavation of the Air Intake Shaft, and excavation of additional experimental rooms to support research and development activities. Geotechnical data acquired during this phase were used to evaluate the performance of the excavations in the context of established design criteria (DOE, 1984). Results of these evaluations were reported in Geotechnical Field Data Reports (DOE, 1985; DOE, 1986a) and were summarized in the Design Validation Final Report (DOE, 1986b).

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

The Design Validation Final Report concluded that the facility, including waste disposal areas, could be developed and operated to fulfill the long-term mission of WIPP (DOE, 1986b). However, some modifications to the reference design were proposed so that the requirements could be met for the anticipated life of the waste disposal rooms and the demonstration phase while the waste remained retrievable. The information from these studies validated the design of underground openings to safely accommodate the permanent disposal of waste under routine operating conditions.

Panel 1 mining began in 1986 and was completed in 1988. Panel 1 was intended to receive waste for an initial operations demonstration and pilot plant phase that was scheduled to start in October 1988. However, the demonstration and pilot plant phase didn't happen because waste disposal operation had to wait until permits were acquired.

In October 1996, the DOE submitted to the U.S. Environmental Protection Agency (EPA) a compliance certification application in accordance with Title 40 CFR Parts 191 and 194, which addressed the long-term (10,000-year) performance criterion for the disposal system. On May 18, 1998, the EPA published final certification that allowed for the receipt of TRU waste at WIPP. Immediately prior to this certification, the DOE Carlsbad Area Office (CAO) completed the WIPP Operational Readiness Review, which was required before the start-up of a nuclear waste repository. As a result of the review, the CAO notified the Energy Secretary on April 1, 1998, that WIPP was operationally ready to receive waste. On October 27, 1999, WIPP received the Hazardous Waste Facility Permit (HWFP). On March 26, 1999, the first shipment of TRU waste was received from Los Alamos National Laboratory (LANL). By the end of June 2004, shipments of TRU waste were received at the WIPP site from LANL, Savannah River Site, Hanford Site, Rocky Flats Environmental Technology Site, Idaho National Engineering and Environmental Laboratory, Argonne National Lab-East and the Nevada Test Site.

Waste disposal operations in Panel 1 are complete and panel closures have been constructed in the Panel entries. Mining of Panel 2 began in September 1999 and was completed in August 2000. Mining of Panel 3 began on January 2003 and was completed by the end of March 2004. Mining of the south mains (entry drifts) for Panel 4 was initiated during this reporting period.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

#### **1.4 Purpose and Scope of Geomechanical Monitoring Program**

As specified in the WIPP HWFP (NMED, 1999), the purpose of the geomechanical monitoring program is to obtain *in situ* data to support the continuous assessment of the design for underground facilities.

Specifically, the program provides for:

- Early detection of conditions that could affect operational safety.
- Evaluation of disposal room closure that ensures adequate access.
- Guidance for design modifications and remedial actions.
- Data for interpreting the behavior of underground openings, in comparison with established design criteria.

Polling of the geomechanical instrumentation is performed at least monthly. Data taken by the geomechanical instrumentation system (GIS) are evaluated and reported in this GAR. This annual report fulfills the requirements set forth in Section IV.F.1 and Attachment M2, Section M2-5b(2) of the WIPP Hazardous Waste Facility Permit (NMED, 1999), and 40 CFR §191.14, "Assurance Requirements," implemented through the certification criteria, 40 CFR Part 194.

The Geomechanical Monitoring Program generates the data for four of the compliance monitoring parameters:

- Creep closure and stresses
- Extent of deformation
- Initiation of brittle deformation
- Displacement of deformation features.

Convergence measurements and borehole extensometers provide data on salt creep closure induced by rock excavation. Data on the extent of deformation are generated through borehole extensometers and borehole observations. Fracture mapping of the excavation surface and borehole observations is used to provide data on the initiation of brittle deformation. Displacement of deformation features in the underground facility is monitored by comparing the results of geologic mapping in newly mined areas to the expected stratigraphy.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

The GIS provides data that are collected, processed, and stored for analysis. The following subsections briefly describe the major components of the GIS.

#### **1.4.1    Instrumentation**

Instrumentation installed for measuring the geomechanical response of the shafts, drifts, and other underground openings include convergence points, convergence meters, extensometers, rock bolt load cells, pressure cells, strain gauges, piezometers, and joint meters. Table 1-1 lists a summary of the geomechanical instrumentation specifications.

#### **1.4.2    Data Acquisition**

The individual geomechanical instruments are read either manually using portable devices or remotely by electronically polling the stations from the surface in accordance with approved operating procedures. Remotely read instruments are connected to one of the data loggers located underground and readings are collected by initiating the appropriate polling routine. Upon completion of a verification process, the data are transferred to a computer database. The manual readout devices are taken to the instrument locations underground. The data are recorded on a data sheet and later entered into an electronic database along with the remotely acquired data.

The underground data acquisition system consists of instruments, polling devices, and a communications network. One or more instruments are connected to a polling device. The polling devices are installed in electrical enclosures near the location of the instrument to facilitate queries of each individual instrument. Polling devices are connected by a datalink to a surface computer.

Whether acquired manually or remotely, geomechanical data are entered into the database files of the GIS data processing system. The data processing system consists of computer programs that are used to enter, reduce, and transfer the data to permanent storage files. Additional routines allow access to these permanent storage files for numerical analysis, tabular reporting, and graphical plotting. Copies of the instrumentation database and data plots are available upon request<sup>3</sup>.

---

<sup>3</sup> Instrumentation data and data plots are presented in "Geotechnical Analysis Report for July 2003-June 2004 Supporting Data." The document is available upon request from the National Technical Information Service. See the back side of this document's cover sheet for details and addresses.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**Table 1-1 Geomechanical Instrumentation System**

Instrument Type	Measures	Range <sup>a</sup>	Resolution <sup>a</sup>
Sonic probe borehole extensometer	Cumulative deformation	0–2 in.	0.001 in.
Convergence points (Tape Extensometer)	Cumulative deformation	2–50 ft	0.001 in.
Wire convergence meters	Cumulative deformation	0–3.5 ft	0.001 in.
Embedded strain gauges	Cumulative strain	0–3000 $\mu$ in./in.	1 $\mu$ in./in.
Spot-welded strain gauges	Cumulative strain	0–2500 $\mu$ in./in.	1 $\mu$ in./in.
Rock bolt load cells	Load	0–50 tons	40 lb
Earth pressure cells	Pressure	0–1000 psi	1 psi
Piezometers	Fluid pressure	0–500 psi	0.5 psi
Joint Meters	Cumulative deformation	0–4 in.	0.001 in.
Vibrating wire borehole extensometer	Cumulative deformation	0–4 in.	0.001 in.
Wire borehole extensometer	Cumulative deformation	0–20 in.	0.001 in.
Linear potentiometric borehole extensometer	Cumulative deformation	0–6 in.	0.001 in.

<sup>a</sup> Manual readout boxes for the instruments were manufactured to output measurements in English units. Range and resolution measurement units have not been converted to metric units. Measurements from these instruments have been converted for presentation elsewhere in this report.

ft = foot (feet)

in. = inch(es)

$\mu$ in. =  $10^{-6}$  inch(es)

psi = pound(s) per square inch

lb = pound(s)

#### 1.4.3 Data Evaluation

Rounding and significant digits are used in the data tables of this document. The reference document that is used is E 29 – 02<sup>e1</sup>, "Standard Practice for Using Significant Digits in Test Data to Determine Conformance with Specification."<sup>4</sup>

Closure measurements are acquired manually from convergence point anchors and remotely from convergence meters. The data are presented in plots as closure versus time. Closure rate data are calculated and presented as part of the data analysis.

Borehole extensometers provide relative displacement data from instrumented rods anchored at various depths in the rock strata. Displacement is measured relative to a fixed

---

<sup>4</sup> Copyright by ASTM Int'l

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

point. The deepest anchor is fixed in what is assumed to be undisturbed ground and is used as the reference point. Plots of displacement versus time for individual anchors relative to the reference point are presented. Typically, the plots show greater relative ground movement near the collar (i.e., the opening of the hole). Displacement rate data for the hole collar relative to the deepest anchor are presented in the data analysis.

The annualized closure rate is calculated as follows:

$$\text{rate(inches / year)} = (c\bar{f}_2 - c\bar{f}_1) / (\text{date}_2 - \text{date}_1) \times 365.25 \text{ days / year}$$

where  $c\bar{f}$  = the change from the initial reading (inches)

$c\bar{f}_1$  =  $c\bar{f}$  reading closest to the beginning of the reporting period

$c\bar{f}_2$  =  $c\bar{f}$  reading closest to the end of the reporting period

Rock bolt load cells are used to determine bolt loading. Plots show load versus time for each instrumented bolt.

Earth pressure cells and strain gages are used to determine the stresses and deformation in and around the shaft liners, and data are depicted in time-based plots.

Piezometers used to measure the gage pressure of groundwater are installed in the shafts at varying elevations to monitor the hydraulic head acting on the shaft liners. Data from piezometers are plotted as pressure versus time.

Joint meters, installed perpendicular to a crack, monitor the dilation of the crack with time. Data from these are typically presented as displacement versus time.

#### **1.4.4 Data Errors**

As described above, GIS data are processed through a comprehensive database management system. Whether acquired manually or remotely, GIS data are processed and permanently stored according to approved procedures. On occasion, erroneous readings can occur. There are several possible explanations for erroneous readings, including the following:

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

- The measuring device was misread.
- The reading was recorded incorrectly.
- The measuring device was not functioning within specifications.

When a reading is believed to be erroneous, an immediate evaluation of the previous reading is performed, and a second reading is collected. If the second reading falls in line with the instrument trend, the first reading is discarded and the second reading is entered in the database. If the second reading and subsequent readings remain out of the instrument trend, the ground conditions in the vicinity of the instrument are assessed to determine the reason for the discrepancy. In addition, reading frequency may be increased. This process to correct erroneous readings is documented and filed for future reference.

## **2.0 Geology**

---

This chapter provides a summary of the stratigraphy of the WIPP region and the facility stratigraphy. Readers desiring further geologic information may consult the "Geological Characterization Report, WIPP Site, Southeastern New Mexico" (Powers et al., 1978). This report was developed as a source document on the geology of the WIPP site for individuals, groups, or agencies seeking basic information on geologic history, hydrology, geochemistry, or detailed information, such as physical and chemical properties of repository rocks. A more recent survey of WIPP stratigraphy is included in Holt and Powers (1990).

### **2.1 Regional Stratigraphy**


The stratigraphy in the vicinity of the WIPP site includes rocks and sediments of Permian (286 to 245 million years ago [Ma]), Triassic (245 to 208 Ma), and Quaternary (1.6 Ma to present) ages. The generalized descriptions of formations provided in this section are given in order of deposition (oldest to youngest), beginning with the Castile Formation (Figure 2-1).

The Permian system in the United States is divided into four series. The last of these, the Ochoan Series, contains the host rock in which the WIPP facility is located. The Ochoan Series is of mostly marine origin and consists of four formations: three evaporite formations (the Castile, the Salado, and the Rustler) and one redbed formation (the Dewey Lake). The Ochoan evaporites overlie marine limestones and sandstones of the Guadalupian Series (Delaware Mountain Group). The younger redbeds represent a transition from the lower evaporite deposition to fluvial deposition on a broad, low-relief, fluvial plain. Fluvial deposits of the Triassic and Quaternary periods complete the stratigraphic column.

#### **2.1.1 Castile Formation**

The Castile Formation, lowermost of the four Ochoan formations, is approximately 1,250 ft (380 m) thick in the WIPP vicinity. Lithologically, the Castile is the least complex of the evaporite formations and is composed chiefly of interbedded anhydrite and halite, with limestone present in minor amounts.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 2-1 Regional Geology**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

### **2.1.2 Salado Formation**

The Salado Formation comprises nearly 2,000 ft (610 m) evaporites (primarily halite). The formation is subdivided into three informal members: the unnamed lower member, the McNutt potash zone, and the unnamed upper member. Each member contains similar amounts of halite, anhydrite, and polyhalite and is differentiated on the basis of soluble potassium and magnesium-bearing minerals. The WIPP disposal horizon is located within the unnamed lower member, 2,150 ft (655 m) below the surface.

### **2.1.3 Rustler Formation**

The Rustler Formation contains the largest proportion of clastic material of the four Ochoan evaporite formations. The Rustler is subdivided into five members as follows (from the base): the Los Medaños Member, the Culebra Dolomite Member, the Tamarisk Member, the Magenta Dolomite Member, and the Forty-niner Member.

In the vicinity of the WIPP site, the Rustler is approximately 310 ft (95 m) thick and thickens to the east. The lower portion (Los Medaños Member) contains primarily fine sandstone to mudstone with lesser amounts of anhydrite, polyhalite, and halite. Bedded and burrowed siliciclastic sedimentary rocks with cross-bedding and fossil remains signify the transition from the strongly evaporitic environments of the Salado to the brackish lagoonal environments of the Rustler (Holt and Powers, 1990).

The upper portion of the Rustler contains interbeds of anhydrite, dolomite, and mudstone. The Culebra Dolomite member is generally brown, finely crystalline and locally argillaceous. The Culebra contains rare to abundant vugs with variable gypsum and anhydrite filling and is the most transmissive hydrologic unit within the Rustler. The Tamarisk Member consists of lower and upper sulfate units separated by a unit that varies laterally from mudstone to mainly halite. The Magenta Dolomite Member is a gypsiferous dolomite with abundant primary sedimentary structures and well-developed algal features. The Forty-niner Member consists of lower and upper sulfate units separated by a mudstone that displays sedimentary features and bedding. East of the site area, halite correlates with the mudstone. The Culebra and Magenta Dolomite members are persistent and serve as important marker units.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

#### **2.1.4 Dewey Lake Redbeds**

The Dewey Lake Redbeds are the uppermost of the Ochoan Series formations in the WIPP vicinity. Within the series, the Dewey Lake represents a transition from the lower marine-influenced evaporite deposition to fluvial deposition on a broad, low-relief, fluvial plain. The redbeds, approximately 475 ft (145 m) thick, consist of predominantly reddish-brown interbedded fine-grained sandstone, siltstone, and claystone. The formation is differentiated from other formations by its lithology and distinctive color (both of which are remarkably uniform), and sedimentary structures, including horizontal- and cross-laminae and ripple marks. The redbeds also contain locally abundant greenish-gray reduction spots and gypsum-filled fractures. The formation thickens from west to east due to eastward dips and erosion to the west.

#### **2.1.5 Dockum Group**

The Dockum Group consists of fine-grained floodplain sediments and coarse alluvial debris of the Triassic age. At the WIPP site, the Dockum Group pinches out near the center of the site and thickens eastward as an erosional wedge. Local subdivisions of the Dockum Group are the Santa Rosa Sandstone and the Chinle Formation; however, only the Santa Rosa occurs in the vicinity of the site. The Santa Rosa consists primarily of poorly sorted sandstone with conglomerate lenses and thin mudstone partings and contains impressions and remnants of fossils. These rocks have more variegated hues than the underlying uniformly colored Dewey Lake.

#### **2.1.6 Galuña Formation, Mescalero Caliche, and Surficial Sediments**

Quaternary Period deposits include the Galuña Formation, Mescalero Caliche, and surficial sediments. The Galuña Formation (ranging in age from approximately 13 Ma to 600,000 years before present [b.p.] [Powers and Holt, 1993]) is a stream-laid deposit overlying the Dockum Group in the WIPP vicinity. At the site center the formation consists of approximately 13 ft (4 m) of poorly consolidated sand, gravel, and silty clay. The Galuña Formation is light red and mottled with dark stains. The unit contains abundant calcium carbonate, but is poorly cemented. Sedimentary structures are abundant (Powers and Holt, 1993, 1995).

The Mescalero Caliche (approximately 500,000 years b.p.) is approximately 4 ft (1.2 m) thick in the WIPP vicinity. The Mescalero is a hard, resistant soil horizon that lies beneath a cover of wind-blown sand. The horizon is petrocalcic, or very strongly cemented with

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

calcium carbonate. Petrocalcic horizons form slowly beneath a stable landscape at the average depth of infiltration of soil moisture and are an indicator of stability and integrity of the land surface. Many of the surface buildings at WIPP are founded on top of the Mescalero Caliche.

Surficial sediments include sandy soils developed from eolian material and active dune areas. The Berino Series (a soil type) covers about 50 percent of the site and consists of deep sandy soils that developed from wind-worked material of mixed origin. Based on sample analyses, the Berino soil from the WIPP site formed  $330,000 \pm 75,000$  years ago.

## **2.2 Underground Facility Stratigraphy**

The WIPP disposal horizon lies in the approximate center of the Salado Formation. The Salado was deposited in a shallow saline lagoon environment, which progressed through numerous inundation and desiccation cycles that are reflected in the formation. An "ideal" cycle progresses upward as follows: a basal layer consisting predominantly of claystone, followed by a layer of sulfate, which is in turn followed by a layer of halite. The entire sequence is capped by a bed of argillaceous (clay-rich) halite accumulated during a period of mainly subaerial exposure.

A regional system used for numbering the more significant sulfate beds within the Salado designates these beds as marker beds (MB) 100 (near the top of the formation) to MB144 (near the base). The repository is located between MB138 and MB139 (Figure 2-2) within a sequence of laterally continuous depositional cycles as described above. Within this sequence, layers of clay and anhydrite that are locally designated (as shown) can have a significant impact on the geomechanical performance of the excavations. Clay layers provide surfaces along which slip and separation can occur, whereas anhydrite acts as a brittle unit that does not deform plastically.

In the vicinity of the WIPP facility, the stratigraphy is fairly continuous and uniform. The stratigraphic beds generally dip towards the south-southeast at a slope of approximately 3 percent.

### **2.2.1 Disposal Horizon Stratigraphy (Panels 1, 2, 7, and 8)**

This disposal horizon contains panels 1, 2, 7, and 8, all the shaft areas, the shop areas, the SPDV areas (which are now closed to access), and all the access drifts to South 2620. The

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

four main entries that extend south ramp-up starting at South 2620 and complete at South 2740.

Most underground excavations are located within this disposal horizon (see Figure 2-2). In this horizon, the Orange Marker Bed (OMB) typically occurs near mid-rib. The OMB is a laterally consistent unit of moderate to light reddish-orange halite, typically about 6 in. (15 centimeters [cm]) thick, that is used as a point of reference for disposal area excavation.

MB139 typically lies approximately 5 ft (1.5 m) below the excavation floor. MB139 is a 20-to-32 in. (50-to-80 cm) thick layer of polyhalitic anhydrite. The top of the anhydrite undulates up to 15 in. (38 cm) while the bottom is sub-horizontal and is underlain by clay "E." Above MB139 is a unit of halite that terminates at the base of the OMB. Within this unit, polyhalite is locally abundant and decreases upward, while argillaceous material increases upward.


Above the OMB, a thin sequence of argillaceous halite gives way to a thick sequence of clear halite that becomes increasingly argillaceous upward and is capped by clay "F." Clay "F" occurs as a thin layer occasionally interrupted by partings and breaks and is readily visible in the upper ribs of disposal horizon excavations.

Above clay "F," another sequence of halite begins that, as in lower sequences, becomes increasingly argillaceous upward. This sequence terminates at the clay "G"/Anhydrite "b" interface, approximately 6.5 ft (2 m) above the roof of most disposal horizon excavations, forming a roof beam that typically acts as a unit. The roof of some disposal horizon excavations (e.g., East 140 drift between South 1000 and South 1950) has been excavated to the upper contact of Anhydrite "b." In this case, a roof beam is formed by the next depositional sequence beginning with Anhydrite "b" and progressing upward to the clay "H"/Anhydrite "a" interface, typically approximately 6.5 ft (2 m) above the upper contact of Anhydrite "b."

### **2.2.2 Disposal Horizon Stratigraphy (Panels 3, 4, 5, and 6)**

This disposal horizon contains Panels 3, 4, 5, 6, and all the access drifts south of South 2740. The rise in floor elevation from South 2620 to South 2740 is approximately 6 ft.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 2-2 Repository Level Stratigraphy (Panels 1, 2, 7 and 8)**


**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

In this horizon (see Figure 2-3), the OMB typically occurs at or below the floor. MB139 typically lies about 12 ft (3.7 m) below the excavation floor. This sequence terminates at the clay "G"/Anhydrite "b" interface. The roof is immediately above Anhydrite "b." Clay "G"/Anhydrite "b" is used as the mining reference at this disposal horizon.

### **2.2.3 Northeast Area Stratigraphy**

All of the Northeast Area, an experimental area, is now deactivated and closed to access. These excavations lie at a higher stratigraphic level than the disposal excavations. They typically have floors excavated at Anhydrite "b." As in the lower units, the halite intervals between the clay seams/anhydrite beds contain relatively pure halite that becomes increasingly argillaceous upward. Above clay "I," two more halite intervals complete the underground facility stratigraphy. Clay "J," at the top of the first of these intervals, may occur as a distinct seam or merely an argillaceous zone. Clay "K" tops the second interval and is overlain by anhydrite MB138.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 2-3 Repository Level Stratigraphy (Panels 3, 4, 5 and 6)**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

This Page Intentionally  
Left Blank

## **3.0 Performance of Shafts and Keys**

---

Four shafts connect the surface with the WIPP underground facility. The four shafts are: the Salt Handling Shaft, which is primarily used for removing excavated salt from the underground; the Waste Shaft, which is the primary shaft for transporting men and materials and is used for transporting TRU waste to the underground; the Exhaust Shaft, which is used to exhaust the ventilation air from the underground; and the Air Intake Shaft, which is the primary source of fresh air ventilation to the underground. This chapter describes the geomechanical performance of these shafts.


Although through the years some of the shaft instrumentation has failed, there are no plans to replace failed instrumentation installed in any of the shafts. The project currently has a good understanding of the expected movements in the shafts. The monitoring results, up to the point of instrument failure, did not indicate any unusual shaft movements or displacements. Continued periodic visual inspections confirm the expected shaft performance and provide necessary observations to evaluate shaft performance. It is anticipated that replacement of the failed instrumentation will not provide significant additional information.

### **3.1 Salt Handling Shaft**

The first construction activity undertaken during the SPDV Program was the excavation of the Exploratory Shaft. This shaft was subsequently referred to as the Construction and Salt Handling Shaft and is currently designated the Salt Handling Shaft (see Figure 1-2). The shaft was drilled from July 4 to October 24, 1981, and geologic mapping was conducted in the spring of 1982 (DOE, 1983). Figure 3-1 presents the stratigraphy at the Salt Handling Shaft.

The Salt Handling Shaft is lined with steel casing and has a 10-ft (3-m) inside diameter from the ground surface to a depth of 846 ft (257.9 m). The steel liner has a thickness of 0.62 in. (1.6 cm) at the top, increasing with depth to a thickness of 1.5 in. (3.8 cm), including external stiffener rings, at the key. Cement grout is placed between the liner and rock face. The 10-ft (3-m) diameter extends through the concrete shaft key to a depth of 880 ft (268.2 m). The shaft key is a 37.5-ft (11.4-m) long, reinforced-concrete structure that begins 3.5 ft (1.07 m) above the bottom of the steel liner. The shaft from the key to the bottom of the shaft, at a depth of 2,298 ft (700 m), has a nominal diameter of 12 ft (4 m).

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 3-1 Salt Handling Shaft Stratigraphy**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

Wire mesh anchored by rock bolts is installed in this portion as a safety screen to contain rock fragments that may become detached. The shaft extends approximately 140 ft (43 m) below the facility horizon in order to accommodate the skip loading equipment and to act as a sump.

### **3.1.1 Shaft Observations**

Underground operations personnel conduct weekly visual shaft inspections. These inspections are performed principally to assess the condition of the hoisting and mechanical systems, but they also include examining the shaft walls for water seepage, loose rock, or sloughing. The visual shaft inspections during this reporting period found that the Salt Handling Shaft was in satisfactory condition. Only routine ground control activities were required in the Salt Handling Shaft during this reporting period.


### **3.1.2 Instrumentation**

Geomechanical instruments (radial convergence points, extensometers, and piezometers) were installed at various levels in the Salt Handling Shaft from April through July of 1982 (Figure 3-2). In the shaft key, instruments included strain gages, pressure cells, and piezometers (Figure 3-3). The radial convergence points were installed prior to the outfitting of the Salt Handling Shaft. Upon completion of the outfitting, no more readings were taken. All of the extensometers in the Salt Handling Shaft are nonfunctional.

All 12 piezometers continue to provide data. The fluid pressures recorded at the end of this reporting period range from approximately 86 pounds per square inch (psi) (593 kilopascals [kPa]) at the 580-ft (177-m) level in the Forty-niner Member to 171 psi (1,130 kPa) at the 691-ft (211-m) level in the Tamarisk Member. The recorded pressure of 163 psi (1123 kPa) at the Magenta Dolomite Member represents a 73-psi increase; however, the installations at this level have historically exhibited large fluctuations. The recorded pressures of 143 psi (986 kPa) at the Culebra Dolomite Member represent no significant change from the recorded pressure in the same location at the end of the previous reporting period. The fluid pressure on the shaft liner will continue to be monitored on a regular basis.


Four earth pressure cells were installed in the key section of the Salt Handling Shaft during concrete emplacement at the 860-ft (262-m) level. These instruments measure the normal stress between the concrete key and the Salado Formation as the creep effects load on the key structure. Three of the four earth pressure cells continue to provide data. These

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 3-2 Salt Handling Shaft Instrumentation (Without Shaft Key)**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 3-3 Salt Handling Shaft Key Instrumentation**

**Geotechnical Analysis Report for July 2003 – June 2004  
DOE/WIPP 05-3177, Vol. 1**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

instruments have essentially indicated no contact pressure since their installation (readings resemble instrument drift at a zero pressure). The contact pressures recorded by the instruments for this reporting period ranged from -20 to 2 psi (-146 to 14 kPa).


Sixteen spot-welded and 24 embedment strain gages were installed on and in the shaft key concrete at both the 856.3-ft (261-m) level and at the 862.4-ft (262.9-m) level. There are four functioning spot-welded strain gages located at these levels. The reported strains at the 856.3-ft (261-m) level were 670 and 759 microstrain. The reported strains at the 862.4-ft (262.9-m) level were 565 and 837 microstrain. The strains reported for this reporting period from the 12 embedment strain gages located at the 856.3-ft (261-m) level range from -802 microstrain to 991 microstrain. The strains reported for this reporting period from the two embedment strain gages located at the 862.4-ft (262.9-m) level were 183 microstrain to 320 microstrain. The strains recorded from the spot-welded strain gages and the embedment strain gages are very similar to the recorded strains from these instruments at the end of the previous reporting period.

### **3.2      Waste Shaft**

As part of the SPDV Program, a 6-ft (2-m) diameter ventilation shaft, now referred to as the Waste Shaft, was excavated from December 1981 through February 1982 (see Figure 1-2). This shaft, in combination with the Salt Handling Shaft, provided a two-shaft underground air circulation system. From October 11, 1983, to June 11, 1984, the shaft was enlarged to a diameter of 20 to 23 ft (6 to 7 m) and lined above the key. Stratigraphic mapping (Figure 3-4) was conducted during shaft enlargement from December 9, 1983, to June 5, 1984 (Holt and Powers, 1984).

The Waste Shaft is lined with nonreinforced concrete and has a 19 ft (6 m) inside diameter from the ground surface to the top of the Waste Shaft key at 837 ft (255 m). Liner thickness increases with depth from 10 in. (25 cm) at the surface to 20 in. (51 cm) at the key. The Waste Shaft key is 63 ft (19 m) long and 4.25 ft (1.3 m) thick and is constructed of reinforced concrete. The bottom of the key is 900 ft (274 m) below the surface. The diameter of the shaft is 20 ft (6 m) at the point below the key and increases to 23 ft (7 m) just above the shaft station. The shaft below the key is lined with wire mesh anchored by rock bolts. The diameter of 23 ft (7 m) extends to a depth of approximately 2,286 ft (697 m) with the shaft sump comprising the lower 119 ft (36 m) of that interval.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 3-4 Waste Shaft Stratigraphy**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

### **3.2.1 Shaft Observations**

Underground operations personnel conduct weekly visual shaft inspections. These inspections are performed principally to assess the condition of the hoisting and mechanical systems, but also include observation of the shaft walls for water seepage, loose rock, or sloughing. The visual shaft inspections during this reporting period found that the Waste Shaft was in satisfactory condition. No ground control activities other than routine maintenance were required in the Waste Shaft during this reporting period.

### **3.2.2 Instrumentation**

Radial convergence points, extensometers, piezometers, and earth pressure cells were installed in the Waste Shaft between August 27 and September 10, 1984. Figures 3-5 and 3-6 illustrate the instrumentation configurations in the shaft and shaft key. The radial convergence points were installed prior to the outfitting of the Waste Shaft. Upon completion of the outfitting, no more radial convergence readings were taken.

Nine multiposition borehole extensometers were installed in arrays at 1,071 ft (326 m), 1,566 ft (477 m), and 2,059 ft (628 m) below the surface as shown in Figure 3-5. Each array consists of three extensometers. Currently, six out of nine extensometers remain functional; however, no data has been collected during this reporting period due to the malfunction of the data-logger.


Twelve piezometers were installed in the lined section of the Waste Shaft on September 7 and 8, 1984, to monitor fluid pressure behind the shaft liner and key section in the shaft. Data continue to be received from all 12 piezometers.

Four earth pressure cells were installed in the key section of the Waste Shaft during concrete emplacement between March 23 and April 3, 1984. These instruments measure the normal stress between the concrete key and the Salado Formation as the salt creep loads the key structure.

During this reporting period the Waste Shaft instrumentation data-logger, which records all the data for the borehole extensometers, the piezometers and the earth pressure cells, was nonfunctional. Therefore, comparisons to previous reporting period data is not available.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

## WASTE SHAFT



### LEGEND

- (PE) Piezometer
- (RC) Radial Convergence Points (RC's)
- (GE) Extensometer


### NOTES

1. RC's at each level consist of four points.
2. The term "level" is an approximate depth from the shaft collar at elevation of 3409 feet (1039 meters) above mean sea level.
3. Levels are shown in units of feet (ft) and meters (m).
4. Piezometers are oriented at N30°W and S30°E.

NOT TO SCALE

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**Figure 3-5 Waste Shaft Instrumentation (Without Shaft Key)**



**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**Figure 3-6 Waste Shaft Key Instrumentation**

### **3.3      Exhaust Shaft**

The Exhaust Shaft was drilled from September 22, 1983, to November 29, 1984, to establish a route from the underground facility to the surface for exhaust air (see Figure 1-2). Stratigraphic mapping was conducted from July 16, 1984, to January 18, 1985 (DOE, 1986c). Figure 3-7 illustrates the Exhaust Shaft Stratigraphy.

The Exhaust Shaft is lined with nonreinforced concrete from the surface to the top of the shaft key at a depth of 844 ft (257 m). The liner thickness increases from 10 to 16 in. (25 to 41 cm) over that interval. The Exhaust Shaft key is 63 ft (19 m) long and 3.5 ft (1 m) thick. The shaft diameter below the key is 15 ft (5 m) and the interval below the key is lined with wire mesh anchored by rock bolts. The shaft terminates at the facility horizon, at a depth of approximately 2,150 ft (655 m). There is no excavated shaft sump.

#### **3.3.1    Exhaust Shaft Observations**

Quarterly Exhaust Shaft video inspections are conducted following approved WIPP procedures. Inspections are performed to evaluate the condition and to verify the integrity of the shaft. The shaft is examined for cracks, corrosion, salt buildup, leaks, and debris. In addition, inspections examine the condition of anchors, brackets, and down-hole equipment. Between July 2003 and June 2004, four shaft inspections were conducted. Inspections were conducted on August 13, 2003; October 29, 2003; February 20, 2004; and May 5, 2004.

##### **3.3.1.1   Video Camera**

Video inspections of the Exhaust Shaft were conducted by the Washington TRU Solutions LLC (WTS) Geotechnical Engineering Section using a custom-designed vertical-drop camera. The system consists of a color camera with pan, tilt, and zoom capability. The camera is housed in an aerodynamic housing and suspended by a dual-armored cable. The cable consists of five copper conductors and two multimode optical fibers. The cable is reeled out by a winch mounted in a control van. The video inspections are recorded on VHS tape.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

### **3.3.1.2 Shaft Inspection Observations**

Quarterly video inspection observations concentrate on four major areas: air monitoring systems, shaft liner, shaft walls, and equipment support and cabling. The air monitoring components consist of one air-velocity and three air-monitoring devices in the Exhaust Shaft, as shown in Figure 3-8. The video inspection includes examination of each device, including the transport assembly, guide tubes, the sample intake, and the support brackets that extend from Station A located above the shaft to the Exhaust Shaft collar. From the Exhaust Shaft collar, the air monitoring components extend down 21 ft and into the shaft. Video inspections indicate that the air-sampling components may typically accumulate salt buildup of up to several inches.

The Exhaust Shaft liner is examined for cracks, seepage, and general shaft stability. Currently, there are three principal zones of seepage in the shaft. The first is at a depth of about 50 to 55 ft below the shaft collar (bsc). The second is at a depth of about 60 to 65 ft bsc. The third is at a depth of about 75 to 80 ft bsc, as shown in Figure 3-9.

Monitoring of seepage horizons dates back prior to 1995. Water entering the shaft through these cracks is believed to originate from a perched anthropogenic water-bearing horizon at the base of the Santa Rosa Formation. The fluid level in the Santa Rosa near the shaft is at about 42 ft below ground surface. Based on examination of the inspection videos the flow rate into the shaft is estimated at about 1 to 3 gallons per minute.


Conditions in the shaft change as a function of several variables, including airflow, humidity, temperature, and underground mining activities (dust). The seepage cracks noted above are confined primarily to the eastern side of the shaft wall. During this reporting period, there did not appear to be any significant change in the quantity of fluid entering the shaft. This is confirmed by comparing annual records of the volume of fluid accumulating in the Exhaust Shaft catch basin at the bottom of the Exhaust Shaft.

When fluid was detected seeping into the Exhaust Shaft in 1995, a catch basin was designed and installed at the base of the Exhaust Shaft to intercept and prevent water from draining into the Waste Shaft Sump. Fluid has been removed on an as-needed basis from the catch basin since March 1996. Table 3-1 presents the volume of fluid removal from the catch basin from July 1997 through June 2004. Between July 2003 and June 2004, the volumes of fluid removed from the catch basin ranged from 55 gallons to 660 gallons (Table 3-1). The largest reported volumes are typically associated with periods of reduced

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**


ventilation and increased humidity. For a discussion of the factors affecting the quantity of fluid entering the Exhaust Shaft catch basin, refer to DOE/WIPP 00-2000, "*Brine Generation Study*."

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**




**Figure 3-7 Exhaust Shaft Stratigraphy**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 3-8 Sample Exhaust Shaft Intake Air Monitoring System**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 3-9 Diagram of Exhaust Shaft Fixtures (200 ft Upper Portion)**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

The shaft walls were examined for cracks, moisture, and encrustation, with particular attention paid to three water rings located at the base of the Magenta and Culebra members of the Rustler Formation and the bottom of the shaft key. As noted earlier, the condition of the shaft wall varies depending on the airflow, humidity, temperature, and underground mining activities. During this reporting period, there was significant mining activity in the Panel 3 and in the Northern Access Drifts. The principle areas in the shaft with significant salt buildup were the three water rings located at the Magenta, the Culebra, and the key and along upper portions of the east wall of the shaft generally associated with the support brackets, instrument cables and the air and waterlines.

Though the Magenta and Culebra water rings are encrusted with salt buildup, there does not appear to be any water emanating from the liner or water rings. Most of the seepage was observed along the east face of the shaft wall near the instrumentation cables and the air and waterlines in the upper section of the shaft. Though the presence of water is an inconvenience requiring periodic disposal, at this time it does not appear to have created any hazard or compromised the structural integrity of the shaft. However, the presence of brine increases the probability of corrosion and deterioration of utility hangers and brackets. There are no visible signs of dissolution of the salt below the key.

The video inspection also concentrated on the installed utilities and support brackets. This included the 13.8 kilovolt amp (kVA) power cable and the grounding cable located on the west wall of the shaft, the instrumentation cables located on the northeast wall of the shaft, and the 4-in. airline and the 2-in. water line located on the east wall of the shaft. Video inspection of the 13.8 kVA cable and the grounding cable show no visible signs of damage. There is sporadic salt buildup on the cables. Currently, long-term implications of salt buildup on the cables are unknown. The 4-in. compressed air line and the 2-in. water line extend from the ground surface to the bottom of the shaft. At present, neither line is being used. Inspection of the integrity of the brackets holding the air line and water line is difficult to assess because of salt buildup. However, there does not appear to be any indication that the brackets, which hold the air line and water line in place, are broken. Currently seventeen instrumentation cable breaks were observed in the shaft. However, the majority of these cable breaks are associated with abandoned cables, and therefore should have minimal impact on shaft monitoring or shaft operations.


**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**Table 3-1 Water Removed from the Exhaust Shaft Catch Basin**

<b>July 1997 – June 1998</b>		<b>July 1998 – June 1999</b>		<b>July 1999 – June 2000</b>		<b>July 2000 – June 2001</b>		<b>July 2001 – June 2002</b>		<b>July 2002 – June 2003</b>	
<b>Date</b>	<b>Gallons</b>										
7/18/97	275	7/1/98	770	7/19/99	110	7/3/00	220	7/31/01	165	07/02/2002	165
7/28/97	660	7/7/98	330	12/13/99	165	7/15/00	110	8/21/01	1595	07/08/2002	440
8/1/97	550	7/14/98	220	2/21/00	110	9/18/00	330	9/13/01	330	07/09/2002	495
8/4/97	715	7/16/98	275	5/16/00	715	10/24/00	110	10/15/01	770	07/10/2002	660
8/8/97	770	7/23/98	165	6/7/00	165	3/7/01	110	10/30/01	220	07/30/2002	220
8/11/97	660	7/24/98	220	6/12/00	275	3/21/01	165	4/29/02	275	09/17/2002	165
8/15/97	475	7/27/98	825	6/19/00	440	4/10/01	220	6/11/02	550	09/24/2003	Sludge 330
8/18/97	330	7/28/98	330	6/22/00	330	4/17/01	220	6/22/02	330	03/25/2003	Sludge 220
8/22/97	330	8/3/98	495	6/30/00	165	4/24/01	110	<b>Total</b>	<b>4235</b>	05/27/2003	55
8/25/97	1045	8/10/98	1265	<b>Total</b>	<b>2475</b>	5/22/01	110			06/03/2003	220
8/25/97	Sludge 110	8/21/98	330			5/22/01	Sludge 440			06/25/2003	330
9/2/97	220	8/24/98	990			6/12/01	1100			<b>Total</b>	<b>3300</b>
9/15/97	605	8/27/98	1155			6/13/01	110				
9/22/97	550	9/1/98	330			Sludge	110				
10/13/97	825	10/5/98	385			<b>Total</b>	<b>3465</b>				
10/20/97	220	10/26/98	660								
11/3/97	275	11/23/98	110								
11/10/97	385	2/1/99	385								
11/17/97	385	2/10/99	110								
11/24/97	330	5/4/99	330								
12/10/97	440	5/11/99	110								
12/12/97	550	5/24/99	605								
1/2/98	220	5/26/99	165								
1/12/98	605	6/1/99	165								
2/2/98	660	6/4/99	165								
2/16/98	605	6/10/99	165								
3/16/98	605	6/10/99	Sludge 165								
5/4/98	660	6/16/99	165								
5/11/98	550	6/21/99	1705								
5/18/98	495	6/23/99	275								
5/20/98	110	6/30/99	605								
6/1/98	330	<b>Total</b>	<b>14135</b>								
6/10/98	90										
6/15/98	385										
6/22/98	165										
<b>Total</b>	<b>16185</b>										



**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

### 3.3.2 Instrumentation

The Exhaust Shaft was equipped with geomechanical instrumentation in two stages. Earth pressure cells were installed behind the liner key in November 1984. Piezometers and nine multiposition borehole extensometers were installed during November and December 1985. Figures 3-10 and 3-11 illustrate the instrumentation configuration.

The extensometers at the 1,573-ft (480-m) level indicate annual collar displacement rates ranging from 0.01 to 0.02 in/yr. (0.03 to 0.04 cm/yr.) These rates indicate that the rates are decreasing from the previous reporting period. At the 2,066-ft (630-m) level, the annualized collar displacement rate was 0.07 in/yr (0.19 cm/yr) from the one functioning extensometer. These displacements indicate continued deformation into the shaft; however, there is no indication of accelerated movement. Table 3-2 summarizes information regarding collar displacement measurements from these extensometers.

**Table 3-2 Collar Displacement at the Exhaust Shaft Extensometers**

Field Tag	Location Shaft Level	Date Last Reading	Collar Displacement Relative to Deepest Anchor in. (cm)	Displacement Rate 2003 to 2004 in/yr (cm/yr)	Displacement Rate 2002 to 2003 in/yr (cm/yr)	Rate Change Percent <sup>a</sup>	Comments
35X-GE-00204	1573	06/01/04	0.378 (0.960)	0.01 (0.03)	0.02 (0.04)	-19%	
35X-GE-00205	1573	06/01/04	0.396 (1.006)	0.02 (0.04)	0.02 (0.04)	-12%	
35X-GE-00206	1573	06/01/04	0.409 (1.039)	0.02 (0.04)	0.02 (0.04)	-21%	
35X-GE-00207	2066	06/01/04	1.831 (4.651)	0.07 (0.19)	0.07 (0.18)	1%	

in./yr = inch(es) per year.


cm/yr = centimeter(s) per year.

<sup>a</sup> Rate change is calculated from the difference between the 2003–2004 rate and the 2002–2003 rate.

Eleven of the 21 piezometers remain in working condition. The fluid pressure readings from the working piezometers at the end of the reporting period range from -2.2 psi (-15.2 kPa) at the 544-ft (166-m) level to 141 psi (972 kPa) at the 721-ft (220-m) level. Maximum pressure readings from the working piezometers during this reporting period were consistent with maximum readings from the previous reporting period with some of the recorded pressures having decreased slightly.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

## EXHAUST SHAFT



### LEGEND

- (PE) Piezometer
- (GE) Extensometer


### NOTES

1. The term "level" is an approximate depth from the shaft collar at elevation of 3409 feet (1039 meters) above mean sea level.
2. Levels are shown in units of feet (ft) and meters (m).
3. Piezometers and extensometers are oriented at N75°E, N45°W, and S15°W.

NOT TO SCALE

**Figure 3-10 Exhaust Shaft Instrumentation (Without Shaft Key)**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 3-11 Exhaust Shaft Key Instrumentation**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

Four earth pressure cells were installed in the key section of the Exhaust Shaft during concrete emplacement. Currently, only two of these earth pressure cells are functional. During this reporting period, the pressure cell readings indicated changes of 0.7 and 1.9 psi. The peak recorded pressures during this period are 55.1 and 44.3 psi (380 and 305 kPa).

### **3.4 Air Intake Shaft**

The Air Intake Shaft was drilled from December 4, 1987, to August 31, 1988, to establish a primary route for surface air to enter the repository (see Figure 1-2). Stratigraphic mapping was conducted from September 14, 1988, to November 14, 1989 (Holt and Powers, 1990). Figure 3-12 illustrates the Air Intake Shaft stratigraphy.

The Air Intake Shaft is lined with nonreinforced concrete from the surface to the bottom of the shaft key at a depth of 903 ft (275 m). The Air Intake Shaft key is 81 ft (25 m) long with an inside diameter of 16 ft (5 m). The diameter below the shaft key is 20 ft (6 m), and the shaft is unlined below the key to the facility horizon at a depth of 2,150 ft (655 m). The shaft walls are bolted and meshed from just below the key all the way down to the shaft station. The Air Intake Shaft has no sump.


#### **3.4.1 Shaft Performance**

Weekly visual inspections were performed on the Air Intake Shaft during this reporting period and the shaft was found to be in satisfactory condition. No ground control activities other than routine maintenance were required during this reporting period.

#### **3.4.2 Instrumentation**

Sandia National Laboratories/New Mexico (SNL/NM) installed geomechanical instruments in the Air Intake Shaft in 1988. WTS maintains responsibility for the operation of all of the instruments located in the Air Intake Shaft as well as for data acquisition and instrument maintenance. WTS provides the data to SNL/NM for analysis. Data from these instruments are available from SNL/NM by request.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Geotechnical Analysis Report for July 2003 – June 2004  
DOE/WIPP 05-3177, Vol. 1**

**Figure 3-12 Air Intake Shaft Stratigraphy**

**Geotechnical Analysis Report for July 2003 – June 2004  
DOE/WIPP 05-3177, Vol. 1**

This Page Intentionally  
Left Blank

## **4.0 Performance of Shaft Stations**

---

This chapter describes the instrumentation and geomechanical performance of the shaft stations at the base of the Salt Handling Shaft, the Waste Shaft, and the Air Intake Shaft. The Exhaust Shaft does not have an enlarged shaft station and, therefore, is not included in this chapter.

### **4.1 Salt Handling Shaft Station**

The Salt Handling Shaft Station was excavated between May 2 and June 3, 1982, by drilling and blasting. In 1987 the station was enlarged, removing the roof beam up to Anhydrite "b" between South 90 and North 20 using a mechanical scaler. In 1995 the remaining roof beam at the north end of the station was also removed up to Anhydrite "b." The station area south of the shaft is 90 ft (27.5 m) long and 32 to 38 ft (10 to 12 m) wide. The height of the station south of the shaft is 18 ft (5.5 m). The station dimensions north of the shaft are approximately 30 ft (9 m) long, 32 to 35 ft (10 to 11 m) wide, and 18 ft (5.5 m) high. The shaft extends approximately 140 ft (43 m) below the facility horizon to accommodate the skip loading equipment and to act as a sump. Figure 4-1 shows a generalized cross section of the station.

#### **4.1.1 Modifications to Excavation and Ground Control Activities**


No major modifications were performed in the Salt Handling Station during this reporting period. Ground control was performed as routine maintenance.

#### **4.1.2 Instrumentation**

Geomechanical instrumentation was installed in the Salt Handling Shaft Station between June 1982 and February 1983, with subsequent reinstallation of extensometers and convergence points as necessary. Figure 4-2 shows the instrument locations after the roof beam was taken down.


There were three extensometers located in the Salt Handling Shaft Station. Due to instrument malfunctions and the removal of one extensometer during roof removal, there are no extensometer data for the Salt Handling Shaft Station for this reporting period; however, historical data are maintained for comparative purposes. Four vertical convergence point arrays are currently monitored. Table 4-1 summarizes the vertical closure rates in the Salt Handling Shaft Station from July 2003 through June 2004. Salt

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 4-1 Salt Handling Shaft Station Stratigraphy**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 4-2 Salt Handling Shaft Station Instrumentation After Roof Beam Excavation**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

Handling Shaft Station vertical closure rates indicate that the rates are decreasing compared to previous reporting periods.

**Table 4-1 Vertical Closure Rates in the Salt Handling Shaft Station**

Location	Chord*	Last Reading	Total Cumulative Displacement Inches/(cm.)	Closure Rate 2003 to 2004 in./yr (cm/yr)	Closure Rate 2002 to 2003 in./yr (cm/yr)	Rate Change Percent <sup>a</sup>	Comments
E0, W12	A-C	06/03/04	17.815 (45.250)	0.73 (1.85)	0.83 (2.11)	-12%	
E0, S18	A-E	06/03/04	26.235 (66.637)	1.39 (3.53)	1.57 (4.00)	-12%	
E0, S18	B-D	06/03/04	26.425 (67.120)	1.50 (3.80)	1.83 (4.65)	-18%	
E0, S18	F-H	06/03/04	16.789 (42.644)	0.96 (2.44)	1.10 (2.80)	-13%	
E0, S30	A-C	06/03/04	40.703 (103.386)	1.47 (3.74)	1.65 (4.20)	-11%	
E0, S65	A-C	06/03/04	37.114 (94.270)	1.08 (2.73)	1.24 (3.14)	-13%	

in./yr = inch(es) per year.

cm/yr = centimeter(s) per year.

\*Chord is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data."

<sup>a</sup> Increase in convergence rate is calculated from the difference between the 2003–2004 rate and the 2002–2003 rate.


## 4.2 Waste Shaft Station

The Waste Shaft Station was initially excavated with a continuous miner as a ventilation connection to a 6-ft (2-m) diameter exhaust shaft in November 1982. In 1984, the station was enlarged to a height of 15 to 20 ft (4.5 to 6 m) and a width of 20 to 30 ft (6 to 9 m). The station is approximately 150 ft (46 m) long. In 1988, the station walls were trimmed and concrete was placed on the floor. Since 1988, the Waste Shaft Station has undergone three major floor renovations. A 53-ft (16-m)-long section of the reinforced concrete was removed in February 1991, in 1995 an additional 30-ft (9-m) section was removed, and in 2000 the most recent floor maintenance included trimming of the floor and reinstallation of the rails supported by segmented concrete panels on a crushed rock backfill. Figure 4-3 shows a cross section of the Waste Shaft Station.

### 4.2.1 Modifications to Excavation and Ground Control Activities

During this reporting period, the Waste Shaft Station was pattern bolted using threaded bar bolts and mats. Other ground control activities performed at the Waste Shaft Station during this reporting period consisted of routine rib maintenance and the routine replacement of failed rock bolts.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 4-3 Waste Shaft Station Stratigraphy**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

#### **4.2.2 Instrumentation**

Instruments were initially installed in the Waste Shaft Station between November 12 and December 2, 1982. Figure 4-4 illustrates the locations after enlargement. There are five extensometers in the roof of the Waste Shaft Station (located at West 30 and East 140) that are currently being monitored. In addition, horizontal convergence is being monitored at East 30 and East 90.

Table 4-2 summarizes the recent history of the roof extensometers in the Waste Shaft Station. The extensometers, 51X-GE-00268 (West 30) and 51X-GE-00279 (East 140), remain in working condition. However, due to transducer malfunctions, there are no reliable readings for 51X-GE-00279. There were three new extensometers installed during this reporting period. Extensometers 51X-GE-00356 and 51X-GE-00357 were installed in the shaft brow and 51X-GE-01025 was installed at East 87.

**Table 4-2 Summary of Roof Extensometers in Waste Shaft Station**

Instrument	Location	Last Reading	Collar Displacement Relative to Deepest Anchor in. (cm)	Displacement Rate 2003 to 2004 in./yr (cm/yr)	Displacement Rate 2002 to 2003 in./yr (cm/yr)	Rate Change Percent <sup>a</sup>	Comments
51X-GE-00268	S400, W30	6/30/2004	8.517 (21.633)	0.65 (1.65)	N/A	N/A	Insufficient data
51X-GE-00356	Waste Shaft Brow	6/28/2004	0.029 (0.074)	0.05 (0.12)	N/A	N/A	New Installation
51X-GE-00357	Waste Shaft Brow	6/28/2004	0.080 (0.203)	0.13 (0.33)	N/A	N/A	New Installation
51X-GE-01025	S400, E87	6/29/2004	0.237 (0.602)	0.53 (1.34)	N/A	N/A	New Installation
51X-GE-00279	S400, E140	5/17/2004	11.702 (29.723)	N/A	0.66 (1.68)	N/A	Transducer Malfunction


in./yr = inch(es) per year.

cm/yr = centimeter(s) per year.

<sup>a</sup> Rate change is calculated from the difference between the 2003–2004 rate and the 2002–2003 rate.

Table 4-3 summarizes the annual horizontal closure rates calculated from convergence point data for this reporting period. The data indicate a slight decrease in the horizontal closure rate at East 30 of -2.0 percent and a slight increase at East 90 of 1.0 percent, respectively, relative to the previous annual closure rates.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**Figure 4-4 Waste Shaft Station Instrumentation After Wall Trimming**



**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

Eighteen rock bolt load cells are installed in the roof and brow of the Waste Shaft Station. The loads on 12 of these rock bolt load cells are monitored regularly. During this reporting period, threaded bar bolts and mats were installed in the Waste Shaft Station. Load cells were installed at E40 and E80 to monitor loading of this support system.

**Table 4-3 Horizontal Closure Rates in the Waste Shaft Station**

Location	Chord*	Last Reading	Total Cumulative Displacement Inches/(cm.)	Closure Rate 2003 to 2004 in./yr (cm/yr)	Closure Rate 2002 to 2003 in./yr (cm/yr)	Rate Change Percent <sup>a</sup>	Comments
S400, E30	C-H	6/16/2004	16.727 (42.487)	0.84 (2.13)	0.86 (2.17)	-2%	
S400, E90	C-G	6/16/2004	19.126 (48.580)	0.97 (2.46)	0.96 (2.43)	1%	

in./yr = inch(es) per year.

cm/yr = centimeter(s) per year.

\*Chord is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data."

<sup>a</sup> Increase in convergence rate is calculated from the difference between the 2003–2004 rate and the 2002–2003 rate.

## **4.3 Air Intake Shaft Station**

The Air Intake Shaft Station was excavated in late 1987 and early 1988 using a continuous miner. The Air Intake Shaft typically is not used to transport personnel or materials between the surface and the underground, but does have a work platform that can be raised and lowered in the shaft to perform routine ground maintenance. There is minimal operational activity at the Air Intake Shaft Station.

### **4.3.1 Modifications to Excavation and Ground Control Activities**

During this reporting period, the Air Intake Shaft Station brows were pattern bolted using threaded bar bolts and mats. Routine maintenance and inspections were also performed at the Air Intake Shaft Station during this reporting period.

### **4.3.2 Instrumentation**

Convergence point and extensometer instrumentation located near the Air Intake Shaft Station are presented in Chapter 5.0 as part of the discussion on the performance of the access drifts. Twenty rock bolt load cells installed in the Air Intake Shaft Station area are monitored regularly.

## **5.0 Performance of Access Drifts**

---

This chapter describes the geomechanical performance of the central underground access drifts. The Waste Disposal Area is discussed in Chapter 6.0. There are four major north-south drifts in the WIPP underground, intersected by shorter east-west cross-drifts. These drift dimensions range from 8 ft (2.4 m) to 21 ft (6.4 m) in height and from 14 ft (4.3 m) to 33 ft (9.2 m) in width.

### **5.1 Modifications to Excavation and Ground Control Activities**

Three of the four major north-south access drifts were extended towards the south during this reporting period. E-140 was mined to S3650 in 1983. Trimming, scaling, and floor milling activities were performed as necessary in many areas throughout the WIPP underground. Table 5-1 summarizes these activities. Table 5-1 also summarizes ground control activities (e.g., rock bolting and installing wire mesh) performed in various locations in the access drifts.

### **5.2 Instrumentation**

This section discusses instrumentation details and locations for each instrumentation type.

#### **5.2.1 Borehole Extensometers**

Three new extensometers were installed during this reporting period. These borehole extensometers were installed in E0 and E140. All operating underground extensometers continue to be monitored. Five borehole extensometers were damaged or mined out during this reporting period. Fifty-one borehole extensometers continue to be monitored.

#### **5.2.2 Convergence Points**

Figure 5-1 shows typical convergence point array configurations. Instrumentation installed during this reporting period was limited to the installation and replacement of convergence point arrays and the installation of new monitoring arrays in the newly mined areas. There were twenty new and replaced convergence points at various locations throughout the WIPP underground access drifts where rib, roof, or floor trimming activities had been performed during this and the previous reporting periods. Horizontal and vertical convergence point arrays were installed at various locations. The majority of these installations were located in the East 0, East 140, and the southern cross-drifts.

Convergence points within the access drifts are read manually at least every two months,

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

with more frequent monitoring in some areas. Table 5-2 lists the new and replacement convergence points that were installed during this reporting period.

**Table 5-1 Summary of Modifications and Ground Control Activities in the Access Drifts July 1, 2003, through June 30, 2004**

Location	Work Performed
N215 and N300	pattern bolted/ threaded bar bolts and mesh
N300, E0 to the W620	trimmed floor
N460, E0 to E140	pattern bolted/ mechanical bolts and mesh
N1100 and N1400, E0 to E140	pattern bolted/ mechanical bolts and mesh
N1100 and N1400, E0 to E140	trimmed ribs
S90 from W170 to Room Q	trimmed floor
S700, E140 and E300	trimmed ribs and floor
S1000, W170 to W30	trimmed roof, ribs and floor. pattern bolted/ mechanical bolts and mesh
S1300 Oil Bay	pattern bolted/ mechanical bolts and mesh
S2520, W170 to W30	pattern bolted/ mechanical bolts and mesh
S2750, E300 to W170	pattern bolted/ mechanical bolts and mesh
S3080, E300 to W170	cut to final dimension, pattern bolted/ mechanical bolts and mesh
S3310, E300 to W170	cut to final dimension, pattern bolted/ mechanical bolts and mesh
E300, W30, and W170, S3310 to S3650	Initial mining
E300, S3080 to S3310	pattern bolted/ mechanical bolts and mesh
E140, S1000 to S1300	pattern bolted/ mechanical bolts and mesh
E140 and E0, N460 to N1400	trimmed rib and floor
E140, N460 to N1100	pattern bolted/ mechanical bolts and mesh
E140, S1920 to S3080	pattern bolted/mechanical and threaded bar bolts, mats and mesh
E140, S1550 and S1775	supplemental bolting threaded bar bolts and mats
E140, S1920 to S3080	pattern bolted/mechanical and threaded bar bolts, mats and mesh
E140, S2750 to S3080	trimmed floor
E140, S3080 to S3310	pattern bolted/ mechanical bolts and mesh
E140, S3310 to S3650	re-entry and salt removal
E0, N460 to N1400	pattern bolted/ mechanical bolts and mesh
W30, S3080 to S3310	cut to final dimension
W30, S90 to S700	pattern bolted/ mechanical bolts and mesh
W30, S2520 to S3080	pattern bolted/ mechanical bolts and mesh
W170, S2520 to S3310	pattern bolted/ mechanical bolts and mesh

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**Table 5-2 New and Replaced Convergence Points Installed in the Access Drifts  
 July 1, 2003, through June 30, 2004**

Location	N/R	Field Tag <sup>#</sup>	Chord*	Date Installed
E0, N300	R	E0-N300-5	A-C (Vertical)	5/6/2004
E0, N780	R	E0-N780-2	A-C (Vertical)	10/2/2003
E0, N940	R	E0-N940-4	A-C (Vertical)	10/2/2003
E0, N1100	R	E0-N1100-4	A-C (Vertical)	10/2/2003
E0, N1266	R	E0-N1266-4	A-C (Vertical)	10/2/2003
E140, N150	R	E140-N150-2	A-C (Vertical)	10/15/2003
E140, N150	R	E140-N150-3	A-C (Vertical)	4/21/2004
E140, N220	R	E140-N220-2	A-C (Vertical)	10/15/2003
E140, S1534	R	E140-S1534-3	B-D (Horizontal)	12/3/2003
E140, S1775	R	E140-S1775-3	B-F (Vertical)	3/19/2004
E140, S2007	R	E140-S2007-4	A-C (Vertical)	3/19/2004
E300, N170	R	E300-N170-2	C-G (Horizontal)	4/21/2004
N215, W500	R	N215-W500-2	A-C (Vertical)	3/18/2004
N300, W170	R	N300-W170-2	A-C (Vertical)	3/18/2004
S90, W905	N	S90-W905	A-C (Vertical)	5/6/2004
S700, E55	N	S700-E55	A-C (Vertical)	5/6/2004
S700, E55	N	S700-E55	B-D (Horizontal)	5/6/2004
S1000, W98	R	S1000-W98-2	A-C (Vertical)	3/18/2004
S1000, W98	R	S1000-W98-2	B-D (Horizontal)	3/18/2004
S3080, E55	R	S3080-E55-2	B-D (Horizontal)	1/15/2004

N = New installation.

R = Replacement installation (i.e., instrument replaces older instrument that has failed or has been mined out).

<sup>#</sup>Field tag chords are defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data"

\*Chord configuration is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data."

### 5.3 Analysis of Convergence Point and Extensometer Data

Convergence point data are obtained by measuring the change in distance between fixed points anchored into the rock across an opening, either from rib-to-rib or from roof-to-floor. Extensometer data are obtained by measuring the displacement from the reference head anchor (collar) to each fixed anchor of the extensometer. These measurements are made, at a minimum, every two months throughout the WIPP underground, with the exception of when convergence points are not accessible. Convergence rates and extensometer displacement rates indicate how an excavation is performing; rates that







**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

decrease or are relatively constant typify stable excavations, whereas increasing rates may indicate some type of developing instability or may be the response to nearby mining.

Where possible, annual closure rates were calculated from convergence point array data from the access drifts. A complete tabulation of these convergence point data and

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

Anchor Designator (typical)



**Geotechnical Analysis Report for July 2003 – June 2004  
DOE/WIPP 05-3177, Vol. 1**

**Figure 5-1 Typical Convergence Point Array Configurations Showing Anchor Designations**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

calculated closure rates are presented in the supporting data document for this report<sup>5</sup>.

Locations with increases in annual vertical (Table 5-3) closure rates of greater than 10 percent are shown below.

Routinely, extensometer displacement rates and convergence rates are plotted against time, and comparisons are made through time to identify any acceleration. Annual convergence rates are calculated by determining the difference between the first and last readings of the reporting period and dividing that difference by the time between the two readings (in years). Instruments that indicate acceleration are analyzed to determine the significance of the acceleration. Factors that are considered during the analysis include the magnitude of the respective rates, percentage increase, convergence history, and any recent excavation in the vicinity.

There are 51 active borehole extensometers being monitored at various locations in the access drifts. Of the 51 extensometers, 24 are in the southern East 140 drift to monitor the waste transport route. Where data are available, annual displacement rates were calculated for each of the active extensometers and compared to the annual displacement rates from the previous reporting period. Nine of the extensometers in this area show increased rates; in some cases, this is attributed to lateral displacement. Thirteen of the extensometers in this area show a decreased convergence rate and data was not available on the two other extensometers. The increased movement in the East 140 roof rates may also be attributed to localized fracturing and the effects of anhydrite stringer separations occurring in the roof.

Further analysis of the convergence rate accelerations has shown many of them to be relatively insignificant. Others, such as the southern areas of the access drifts, had closure rate increases that can be directly attributed to continued effects of mining Panel 3 and the associated access drifts.

The rates in East 140, from South 1882 to South 2998, where the roof has been mined to Clay "G," show an increase in the closure rates. These rates are expected to decrease over time as the roof beam removal effect subsides. The rates in West 170, from South 90 to South 1445, show an increase in the closure rates. These rate increases may be attributed

---

<sup>5</sup> Instrumentation data and data plots are presented in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data." The document is available upon request from the National Technical Information Service. See the back side of this documents cover sheet for details and addresses.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

to trimming the cross drifts. An example of this trimming is South 1000, West 98 which had an increase of 68 percent, where the roof, ribs and floor were trimmed. These rates are expected to decrease over time as the effect of cross drift trimming subsides. Convergence measurements in East 140 between South 1534 and South 1862 show an increasing trend over the long-term median convergence rate. This is due to separations along anhydrite stringers in the roof and localized fracturing. An additional supplemental ground control system was installed in this area to address the separation during this reporting period.

**Table 5-3 Increases in Annual Vertical Convergence Rates Greater than 10 Percent in the Access Drifts**

Location	Chord*	Last Reading	Total Cumulative Displacement Inches/(cm.)	Closure Rate 2003 to 2004 in./yr (cm/yr)	Closure Rate 2002 to 2003 in./yr (cm/yr)	Rate Change Percent <sup>a</sup>	Comments
E140, S1862	A-E	06/24/04	18.202 (46.233)	3.86 (9.80)	2.94 (7.47)	31%	Anhydrite Stringer
E140, S1862	H-F	06/24/04	10.614 (26.960)	1.75 (4.45)	1.52 (3.86)	15%	Anhydrite Stringer
E140, S2350	A-C	06/23/04	34.064 (86.523)	6.34 (16.10)	4.49 (11.40)	41%	Roof Beam removal
E140, S2425	A-C	06/23/04	15.303 (38.870)	5.21 (13.23)	4.45 (11.30)	17%	Roof Beam removal
E140, S2833	A-C	06/23/04	6.336 (16.093)	4.54 (11.53)	3.41 (8.66)	33%	
E140, S2915	A-C	06/23/04	8.867 (22.522)	6.08 (15.44)	5.53 (14.05)	10%	
E140, S2998	A-C	06/23/04	9.145 (23.228)	6.25 (15.88)	5.68 (14.43)	10%	
N215, W500	A-C	06/24/04	18.891 (47.983)	2.23 (5.66)	1.34 (3.40)	66%	Reinstalled 3/04 Floor Trimming
N300, W170	A-C	06/24/04	22.953 (58.301)	2.75 (6.99)	1.56 (3.96)	76%	Reinstalled 3/04 Floor Trimming
S1000, W98	A-C	06/16/04	19.326 (49.088)	2.46 (6.25)	1.47 (3.73)	68%	Trimming
S1950, E281	A-C	05/12/04	12.783 (32.469)	1.01 (2.57)	0.90 (2.29)	11%	
S1950, E284	A-C	05/12/04	12.875 (32.703)	1.05 (2.67)	0.93 (2.36)	13%	
W170, S90	A-C	06/16/04	9.154 (23.251)	0.96 (2.44)	0.77 (1.96)	24%	Cross drift trimming
W170, S1000	A-C	06/07/04	19.392 (49.256)	1.05 (2.67)	0.70 (1.78)	50%	Cross drift trimming
W170, S1300	A-C	06/07/04	15.711 (39.906)	1.33 (3.38)	1.10 (2.79)	21%	Cross drift trimming
W170, S1445	A-C	06/07/04	8.677 (22.040)	0.76 (1.93)	0.67 (1.70)	13%	Cross drift trimming

in./yr = inch(es) per year.

cm/yr = centimeter(s) per year.

\*Chord is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data."

<sup>a</sup> Increase in convergence rate is calculated from the difference between the 2003–2004 rate and the 2002–2003 rate.

## 5.4 Excavation Performance

Over 490 readings are collected and assessed on a regular basis from convergence point pairs located throughout the WIPP underground. Convergence rates continue to seasonally vary, typically increasing during the warmer summer months and decreasing during the cooler winter months.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

The performance of the access drift excavations during this reporting period was within acceptable criteria. "Acceptable criteria" is when the drift remains accessible and the ground can be controlled by routine maintenance. Standard remedial ground control maintenance in some areas was required to maintain the performance of the excavations. The drifts remain stable and controlled. The majority of the annualized rates remain steady indicating stability. In some locations where the rates are high, nearby mining activities are most likely the cause. In other locations where necessary, additional ground control measures have been or will be installed.

**Geotechnical Analysis Report for July 2003 – June 2004  
DOE/WIPP 05-3177, Vol. 1**

This Page Intentionally  
Left Blank

## **6.0 Performance of Waste Disposal Area**

---

The Waste Disposal Area as of June 30, 2004, consists of Panels 1, 2 and 3. Panel 1 is closed. Panel 2 is currently being used for waste disposal, with Rooms 5, 6 and 7 filled. Panel 3 mining is complete as shown in Figure 1-2.

Excavation of the Panel 1 waste disposal area began in May 1986 with the mining of access entries to Panel 1. Initially, the disposal rooms and drifts were developed as pilot drifts that were later excavated to nominal operational dimensions of 13 ft (4 m) high, 33 ft (10 m) wide, and 300 ft (91 m) long. Room 1 was completed to these dimensions in August 1986, and pilot drifts for Rooms 2 and 3 were excavated in January and February 1987. Rooms 2 and 3 were completed in February and March 1988 and Rooms 4 through 7 were completed in May 1988. Short access drifts designed to lead to smaller test alcoves were excavated north off of the S1600 drift in June 1989. Only the access drifts to the alcoves were completed; the alcoves were not excavated. Panel 1 waste emplacement is complete and the panel is closed to all access. The Panel 1 access entries, S1600 and S1950 which extend from the E300 drift to the isolation walls, remain open and the instrumentation in this area will continue to be replaced and monitored.

Excavation of the Panel 2 waste disposal area began in September 1999 with the mining of access entries to Panel 2. Initially, the disposal rooms and drifts were developed as pilot drifts that were trimmed to finished dimensions. Room 1 was completed in January 2000, and pilot drifts for Rooms 2 and 3 were excavated in February 2000. Pilot drifts were completed for Rooms 4 through 6 in April 2000. The pilot drift for Room 7 was excavated in May 2000. All the rooms were excavated to final dimensions by August 2000.

Excavation of Panel 3 waste disposal rooms began in May 2002 with the mining of access entries to Panel 3. As with Panel 2, initially, the disposal rooms and drifts were developed as pilot drifts that were trimmed to finished dimensions. All the rooms were excavated to final dimensions by the end of March 2004.

### **6.1 Modifications to Excavations and Ground Control Activities**

There were no new excavations mined in Panel 2 during the reporting period. In Panel 3, initial mining was completed in Rooms 2, 3, 4, 5, 6 and 7, and in the access drifts, S2750 and S3080, from Room 5 to Room 7. Final mining of the entire panel was complete by the end of March 2004. Routine maintenance and ground control activities in the form of

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

trimming, scaling, rock bolt replacement, and installing wire mesh were performed on ribs, floor, and roof throughout accessible areas in Panels 2 and 3. During this reporting period, Panel 2, Rooms 6, 7, parts of South 2520 and South 3080 were wire meshed and bolted. Also during this reporting period, roof bolting was performed in all of the Panel 3 rooms and entries. Table 6-1 summarizes the ground control activities performed in Panels 1, 2 and 3 during this reporting period.


## **6.2      Instrumentation**

Because of Panel 2 floor trimming, there were three convergence points replaced in Room 2 and one convergence point replaced in South 2520 at the intersection of Room 2, Panel 2 during this reporting period. Tables 6-2, 6-3, and 6-4 list the convergence points replaced in Panel 1 entries and Panels 2 and 3. Figures 6-1, 6-2 and 6-3 show the location of the various types of geotechnical instruments in the Panel 1 entries and Panels 2 and 3 of the Waste Disposal Area during this reporting period.

**Table 6-1 Summary of Modifications and Ground Control Activities in the Waste Disposal Area from July 1, 2003, to June 30, 2004**


Location	Work Performed
Panel 1 entries, S1600 and S1950	installed isolation walls
Panel 2, Rooms 1 through 6, S2180 and S2520	trimmed floor
Panel 3, Rooms 2, 3, 4, 5, 6, and 7	initial mining complete
Panel 3, S2750 and S3080 from Rooms 5 to 7	initial mining complete
Panel 3, All Areas	final mining complete bolting complete

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**




**Figure 6-1 Location of Panel 1 Entry Geotechnical Instruments**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 6-2 Location of Panel 2 Geotechnical Instruments**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 6-3 Location of Panel 3 Geotechnical Instruments**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**Table 6-2 New and Replaced Convergence Points in the Panel 1 Entries from July 1, 2003, to June 30, 2004**

Location	N/R	Field Tag <sup>#</sup>	Chord <sup>*</sup>	Date Installed
S1600, E453	N	S1600-E453	A-C (Vertical)	7/23/2003
S1600, E453	N	S1600-E453	B-D (Horizontal)	7/23/2003
S1950, E311	R	S1950-E311-6	A-C (Vertical)	10/16/2003
S1950, E457	R	S1950-E457-5	A-C (Vertical)	7/23/2003

N = New installation.

R = Replacement installation (i.e., instrument replaces older instrument that has failed or has been mined out).

<sup>#</sup>Field tag chords are defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data."

<sup>\*</sup>Chord configuration is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data" and Figure 5-1.

**Table 6-3 New and Replaced Convergence Points in Panel 2 from July 1, 2003, to June 30, 2004**

Location	N/R	Field Tag <sup>#</sup>	Chord <sup>*</sup>	Date Installed
E520, S2275	R	E520-S2275-2	A-C (Vertical)	12/17/2003
E520, S2350	R	E520-S2350-3	A-C (Vertical)	12/17/2003
E520, S2425	R	E520-S2425-2	A-C (Vertical)	12/17/2003
E790, S2275	R	E790-S2275-2	A-C (Vertical)	12/17/2003
E790, S2350	R	E790-S2350-3	A-C (Vertical)	12/17/2003
E790, S2425	R	E790-S2425-2	A-C (Vertical)	12/17/2003
E920, S2275	R	E920-S2275-2	A-C (Vertical)	1/7/2004
E920, S2350	R	E920-S2350-3	A-C (Vertical)	1/7/2004
E920, S2425	R	E920-S2425-2	A-C (Vertical)	1/7/2004
E1050, S2350	R	E1050-S2350-3	A-C (Vertical)	10/22/2003
E1050, S2425	R	E1050-S2425-2	A-C (Vertical)	10/22/2003
S2180, E410	R	S2180-E410-2	A-C (Vertical)	3/18/2004
S2180, E520	R	S2180-E520-2	A-C (Vertical)	3/18/2004
S2180, E586	R	S2180-E586-2	A-C (Vertical)	3/18/2004
S2180, E660	R	S2180-E660-2	A-C (Vertical)	3/18/2004
S2520, E410	R	S2520-E410-3	A-C (Vertical)	1/7/2004
S2520, E520	R	S2520-E520-3	A-C (Vertical)	1/7/2004
S2520, E586	R	S2520-E586-2	A-C (Vertical)	1/7/2004
S2520, E660	R	S2520-E660-3	A-C (Vertical)	12/17/2003
S2520, E790	R	S2520-E790-2	A-C (Vertical)	12/17/2003
S2520, E920	R	S2520-E920-2	A-C (Vertical)	1/7/2004
S2520, E985	R	S2520-E985-2	A-C (Vertical)	1/7/2004
S2520, E1050	R	S2520-E1050-2	A-C (Vertical)	10/22/2003

N = New installation.

R = Replacement installation (i.e., instrument replaces older instrument that has failed or has been mined out).

<sup>#</sup>Field tag chords are defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data."

<sup>\*</sup>Chord configuration is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data" and Figure 5-1.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**Table 6-4 New and Replaced Convergence Points in Panel 3 from July 1, 2003,  
to June 30, 2004**

Location	N/R	Field Tag <sup>#</sup>	Chord <sup>*</sup>	Date Installed
E520, S2833	N	E520-S2833	A-C (Vertical)	7/15/2003
E520, S2833	N	E520-S2833	B-D	7/15/2003
E520, S2833	R	E520-S2833-2	A-C (Vertical)	6/21/2004
E520, S2916	N	E520-S2916	A-C (Vertical)	7/11/2003
E520, S2916	N	E520-S2916	B-D	7/15/2003
E520, S2916	R	E520-S2916-2	A-C (Vertical)	6/21/2004
E520, S2998	N	E520-S2998	A-C (Vertical)	7/15/2003
E520, S2998	N	E520-S2998	B-D	4/16/2004
E520, S2998	R	E520-S2998-2	A-C (Vertical)	6/21/2004
E660, S2833	N	E660-S2833	A-C (Vertical)	8/8/2003
E660, S2833	R	E660-S2833-2	A-C (Vertical)	4/16/2004
E660, S2916	N	E660-S2916	A-C (Vertical)	8/8/2003
E660, S2916	N	E660-S2916	B-D	4/16/2004
E660, S2916	R	E660-S2916-2	A-C (Vertical)	4/16/2004
E660, S2998	N	E660-S2998	A-C (Vertical)	8/8/2003
E660, S2998	N	E660-S2998	B-D	4/16/2004
E660, S2998	R	E660-S2998-2	A-C (Vertical)	4/16/2004
E790, S2833	N	E790-S2833	A-C (Vertical)	8/21/2003
E790, S2833	N	E790-S2833	B-D	4/16/2004
E790, S2833	R	E790-S2833-2	A-C (Vertical)	4/16/2004
E790, S2916	N	E790-S2916	A-E (Vertical)	8/8/2003
E790, S2916	N	E790-S2916	B-D	8/21/2003
E790, S2916	N	E790-S2916	C-G	3/5/2004
E790, S2916	N	E790-S2916	F-H (Vertical)	8/21/2003
E790, S2916	R	E790-S2916-2	A-E (Vertical)	4/16/2004
E790, S2998	N	E790-S2998	A-C (Vertical)	9/4/2003
E790, S2998	N	E790-S2998	B-D	3/5/2004
E790, S2998	R	E790-S2998-2	A-C (Vertical)	4/16/2004
E920, S2833	N	E920-S2833	A-C (Vertical)	9/4/2003
E920, S2833	N	E920-S2833	B-D	4/22/2004
E920, S2833	R	E920-S2833-2	A-C (Vertical)	4/22/2004
E920, S2916	N	E920-S2916	A-C (Vertical)	9/4/2003
E920, S2916	N	E920-S2916	B-D	4/22/2004
E920, S2916	R	E920-S2916-2	A-C (Vertical)	4/22/2004
E920, S2998	N	E920-S2998	A-C (Vertical)	9/4/2003
E920, S2998	N	E920-S2998	B-D	4/22/2004
E920, S2998	R	E920-S2998-2	A-C (Vertical)	4/22/2004
E1050, S2833	N	E1050-S2833	A-C (Vertical)	6/17/2004
E1050, S2833	N	E1050-S2833	B-D	3/5/2004
E1050, S2916	N	E1050-S2916	A-C (Vertical)	1/6/2004
E1050, S2916	N	E1050-S2916	B-D	3/5/2004

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

E1050, S2916	R	E1050-S2916-2	A-C (Vertical)	6/17/2004
--------------	---	---------------	----------------	-----------

**Table 6-4 Continued**

Location	N/R	Field Tag <sup>#</sup>	Chord*	Date Installed
E1050, S2998	N	E1050-S2998	A-C (Vertical)	6/17/2004
E1050, S2998	N	E1050-S2998	B-D (Horizontal)	3/5/2004
E1190, S2833	N	E1190-S2833	A-C (Vertical)	6/10/2004
E1190, S2833	N	E1190-S2833	B-D (Horizontal)	2/6/2004
E1190, S2916	N	E1190-S2916	A-C (Vertical)	1/6/2004
E1190, S2916	N	E1190-S2916	B-D	2/6/2004
E1190, S2916	R	E1190-S2916-2	A-C (Vertical)	6/11/2004
E1190, S2998	N	E1190-S2998	A-C (Vertical)	6/11/2004
E1190, S2998	N	E1190-S2998	B-D	2/6/2004
E1320, E2916	N	E1320-S2916	B-D	2/6/2004
E1320, S2833	N	E1320-S2833	A-C (Vertical)	6/11/2004
E1320, S2833	N	E1320-S2833	B-D	2/6/2004
E1320, S2916	N	E1320-S2916	A-C (Vertical)	1/6/2004
E1320, S2916	R	E1320-S2916-2	A-C (Vertical)	6/11/2004
E1320, S2998	N	E1320-S2998	A-C (Vertical)	6/11/2004
E1320, S2998	N	E1320-S2998	B-D	2/6/2004
S2750, E410	N	S2750-E410	A-C (Vertical)	7/14/2003
S2750, E410	N	S2750-E410	B-D	7/14/2003
S2750, E520	N	S2750-E520	A-C (Vertical)	11/5/2003
S2750, E520	R	S2750-E520-2	A-C (Vertical)	6/25/2004
S2750, E586	N	S2750-E586	A-C (Vertical)	11/5/2003
S2750, E586	R	S2750-E586-2	A-C (Vertical)	6/25/2004
S2750, E660	N	S2750-E660	A-C (Vertical)	11/5/2003
S2750, E660	R	S2750-E660-2	A-C (Vertical)	6/25/2004
S2750, E790	N	S2750-E790	A-C (Vertical)	11/5/2003
S2750, E790	R	S2750-E790-2	A-C (Vertical)	6/25/2004
S2750, E920	N	S2750-E920	A-C (Vertical)	11/5/2003
S2750, E920	R	S2750-E920-2	A-C (Vertical)	6/25/2004
S2750, E986	N	S2750-E986	A-C (Vertical)	11/5/2003
S2750, E986	R	S2750-E986-2	A-C (Vertical)	6/25/2004
S2750, E1050	N	S2750-E1050	A-C (Vertical)	11/5/2003
S2750, E1050	R	S2750-E1050-2	A-C (Vertical)	6/25/2004
S2750, E1190	N	S2750-E1190	A-C (Vertical)	1/6/2004
S2750, E1190	R	S2750-E1190-2	A-C (Vertical)	1/28/2004
S2750, E1190	R	S2750-E1190-3	A-C (Vertical)	6/25/2004
S2750, E1255	N	S2750-E1255	A-C (Vertical)	1/6/2004
S2750, E1255	R	S2750-E1255-2	A-C (Vertical)	6/25/2004
S2750, E1320	N	S2750-E1320	A-C (Vertical)	1/6/2004

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

S2750, E1320	R	S2750-E1320-2	A-C (Vertical)	6/25/2004
S3080, E410	N	S3080-E410	A-C (Vertical)	7/11/2003
S3080, E410	N	S3080-E410	B-D	7/11/2003
S3080, E520	N	S3080-E520	A-C (Vertical)	9/8/2003

**Table 6-4 Continued**

Location	N/R	Field Tag <sup>#</sup>	Chord <sup>*</sup>	Date Installed
S3080, E520	R	S3080-E520-2	A-C (Vertical)	6/25/2004
S3080, E586	N	S3080-E586	A-C (Vertical)	9/8/2003
S3080, E586	N	S3080-E586	B-D	6/17/2004
S3080, E586	R	S3080-E586-2	A-C (Vertical)	6/17/2004
S3080, E660	N	S3080-E660	A-C (Vertical)	9/8/2003
S3080, 660	R	S3080-E660-2	A-C (Vertical)	6/17/2004
S3080, E725	N	S3080-E725	A-C (Vertical)	6/30/2004
S3080, E725	N	S3080-E725	B-D	6/30/2004
S3080, E790	N	S3080-E790	A-C (Vertical)	9/4/2003
S3080, E790	R	S3080-E790-2	A-C (Vertical)	6/17/2004
S3080, E857	N	S3080-E857	A-C (Vertical)	9/4/2003
S3080, E857	N	S3080-E857	B-D	6/30/2004
S3080, E857	R	S3080-E857-2	A-C (Vertical)	6/30/2004
S3080, E920	N	S3080-E920	A-C (Vertical)	9/4/2003
S3080, E920	R	S3080-E920-2	A-C (Vertical)	6/25/2004
S3080, E986	N	S3080-E986	A-C (Vertical)	1/15/2004
S3080, E986	N	S3080-E986	B-D	6/30/2004
S3080, E986	R	S3080-E986-2	A-C (Vertical)	6/30/2004
S3080, E1050	N	S3080-E1050	A-C (Vertical)	1/6/2004
S3080, E1050	R	S3080-E1050-2	A-C (Vertical)	6/17/2004
S3080, E1190	N	S3080-E1190	A-C (Vertical)	1/6/2004
S3080, E1255	N	S3080-E1255	A-C (Vertical)	1/6/2004
S3080, E1255	N	S3080-E1255	B-D	2/6/2004
S3080, E1255	R	S3080-E1255-2	A-C (Vertical)	6/17/2004
S3080, E1320	N	S3080-E1320	A-C (Vertical)	1/6/2004
S3080, E1320	R	S3080-E1320-2	A-C (Vertical)	6/11/2004

N = New installation.

R = Replacement installation (i.e., instrument replaces older instrument that has failed or has been mined out).

<sup>#</sup>Field tag chords are defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data."

<sup>\*</sup>Chord configuration is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data." and Figure 5-1.

### 6.3 Excavation Performance

Horizontal and vertical convergence rates have been calculated for the S1600 and S1950 entries of Panel 1 for this and the previous reporting period. Tables 6-5 and 6-6 present these convergence rates. The vertical and horizontal convergence rates in the Panel entries

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

have all increased with the exception of the South 1950, East 457 horizontal convergence point.

**Table 6-5 Annual Convergence Rates in the S1600 Panel 1 Entry**

Location	Chord <sup>*</sup>	Last Reading	Total Cumulative Displacement Inches/(cm.)	Closure Rate 2003 to 2004 in./yr (cm/yr)	Closure Rate 2002 to 2003 in./yr (cm/yr)	Rate Change Percent <sup>a</sup>	Comments
S1600, E311	A-C (Vertical)	06/25/04	16.011 (40.668)	0.79 (2.00)	0.77 (1.94)	3%	
S1600, E311	B-D (Horizontal)	06/25/04	14.387 (36.543)	0.72 (1.82)	0.60 (1.51)	21%	
S1600, E332	A-C (Vertical)	06/25/04	13.908 (35.326)	0.84 (2.12)	0.68 (1.72)	24%	
S1600, E357	A-C (Vertical)	06/25/04	16.260 (41.300)	0.96 (2.44)	0.75 (1.89)	29%	
S1600, E382	A-C (Vertical)	06/25/04	16.365 (41.567)	0.94 (2.39)	0.72 (1.83)	30%	
S1600, E407	A-G (Vertical)	06/25/04	17.215 (43.726)	1.02 (2.58)	0.74 (1.88)	38%	
S1600, E407	B-F (Vertical)	06/25/04	15.815 (40.170)	0.95 (2.42)	0.68 (1.74)	39%	
S1600, E407	H-L (Vertical)	06/25/04	16.515 (41.948)	1.00 (2.55)	0.76 (1.92)	33%	
S1600, E432	A-C (Vertical)	06/25/04	20.302 (51.567)	1.11 (2.81)	0.93 (2.36)	19%	

in./yr = inch(es) per year.

cm/yr = centimeter(s) per year.

<sup>\*</sup>Chord is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data" and Figure 5-1

<sup>a</sup> Increase in convergence rate is calculated from the difference between the 2003–2004 rate and the 2002–2003 rate.

**Table 6-6 Annual Convergence Rates in the S1950 Panel 1 Entry**

Location	Chord <sup>*</sup>	Last Reading	Total Cumulative Displacement Inches/(cm.)	Closure Rate 2003 to 2004 in./yr (cm/yr)	Closure Rate 2002 to 2003 in./yr (cm/yr)	Rate Change Percent <sup>a</sup>	Comments
S1950, E311	B-D (Horizontal)	06/29/04	20.205 (51.321)	1.12 (2.85)	0.87 (2.20)	30%	
S1950, E332	A-C (Vertical)	06/29/04	27.099 (68.831)	1.41 (3.58)	1.28 (3.25)	10%	
S1950, E332	B-D (Horizontal)	06/29/04	22.395 (56.883)	1.23 (3.12)	0.98 (2.50)	25%	
S1950, E357	B-D (Horizontal)	06/29/04	23.243 (59.037)	1.31 (3.34)	1.14 (2.90)	15%	
S1950, E357	A-C (Vertical)	06/29/04	30.832 (78.313)	1.74 (4.42)	1.60 (4.06)	9%	
S1950, E382	B-D (Horizontal)	06/29/04	25.197 (64.000)	1.40 (3.55)	1.21 (3.07)	16%	
S1950, E382	A-C (Vertical)	06/29/04	31.439 (79.855)	1.98 (5.02)	1.74 (4.42)	14%	
S1950, E407	C-K (Horizontal)	04/27/04	23.157 (58.819)	1.30 (3.29)	1.21 (3.07)	7%	
S1950, E407	D-J (Horizontal)	06/29/04	25.654 (65.161)	1.48 (3.77)	1.34 (3.39)	11%	
S1950, E407	H-L (Vertical)	06/29/04	34.399 (87.373)	2.15 (5.47)	1.80 (4.56)	20%	
S1950, E407	A-G (Vertical)	06/29/04	34.057 (86.505)	2.12 (5.39)	1.95 (4.96)	9%	
S1950, E432	A-C (Vertical)	06/29/04	34.410 (87.401)	2.04 (5.18)	2.00 (5.09)	2%	
S1950, E432	B-D (Horizontal)	06/29/04	25.317 (64.305)	1.41 (3.58)	1.26 (3.19)	12%	
S1950, E457	B-D (Horizontal)	06/29/04	24.876 (63.185)	0.63 (1.61)	1.18 (2.99)	-46%	

in./yr = inch(es) per year.

cm/yr = centimeter(s) per year.

<sup>\*</sup>Chord is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data." & Figure 5-1

<sup>a</sup> Increase in convergence rate is calculated from the difference between the 2003–2004 rate and the 2002–2003 rate.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

Horizontal and vertical convergence rates have been calculated at the center of each of the rooms in Panel 2 for this and the previous reporting period. Tables 6-7 and 6-8 present these convergence rates. The vertical and horizontal convergence rates at the center of each room in Panel 2 have all increased with the exception of the Room 6 horizontal center point.

**Table 6-7 Annual Vertical Convergence Rates at the Center of Panel 2 Rooms**

Location	Chord*	Last Reading	Total Cumulative Displacement Inches/(cm.)	Closure Rate 2003 to 2004 in./yr (cm/yr)	Closure Rate 2002 to 2003 in./yr (cm/yr)	Rate Change Percent	Comments
Room 1, E520, S2350	A-C	06/29/04	17.567 (44.620)	4.74 (12.04)	3.38 (8.60)	40%	Floor Trimming
Room 2, E660, S2350	A-C	06/29/04	17.512 (44.480)	3.96 (10.07)	3.31 (8.40)	20%	Floor Trimming
Room 3, E790, S2350	A-C	06/07/04	15.691 (39.855)	3.72 (9.44)	2.92 (7.42)	27%	Floor Trimming
Room 4, E920, S2350	A-C	04/20/04	17.811 (45.240)	3.64 (9.26)	3.20 (8.12)	14%	Floor Trimming
Room 5, E1050, S2350	A-C	09/23/03	15.825 (40.196)	3.22 (8.18)	2.92 (7.42)	10%	Floor Trimming
Room 6, E1190, S2350	A-C	08/26/03	14.041 (35.664)	2.99 (7.59)	2.87 (7.29)	4%	
Room 7 <sup>b</sup> , E1320, S2350	A-C	N/A	N/A	N/A	N/A	N/A	

in./yr = inch(es) per year

cm/yr = centimeter(s) per year

\*Chord is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data," and Figure 5-1

<sup>a</sup>Increase in convergence rate is calculated from the difference between the 2003–2004 rate and the 2002–2003 rate.

<sup>b</sup>Panel 2, Room 7 closed during this reporting period.

**Table 6-8 Annual Horizontal Convergence Rates at the Center of Panel 2 Rooms (Mid-Rib)**

Location	Chord*	Last Reading	Total Cumulative Displacement Inches/(cm.)	Closure Rate 2003 to 2004 in./yr (cm/yr)	Closure Rate 2002 to 2003 in./yr (cm/yr)	Rate Change Percent	Comments
Room 1, E520, S2350	B-D	06/29/04	11.422 (29.012)	2.69 (6.82)	2.29 (5.81)	17%	Floor Trimming
Room 2, E660, S2350	B-D	12/02/03	9.780 (24.841)	2.15 (5.46)	2.10 (5.33)	2%	Floor Trimming
Room 3, E790, S2350	B-D	06/07/04	10.059 (25.550)	2.27 (5.77)	1.99 (5.04)	14%	Floor Trimming
Room 4, E920, S2350	B-D	04/20/04	10.588 (26.894)	2.38 (6.04)	2.08 (5.29)	14%	Floor Trimming
Room 5, E1050, S2350	B-D	10/22/03	8.092 (20.554)	2.26 (5.73)	1.79 (4.53)	26%	Floor Trimming
Room 6, E1190, S2350	B-D	08/26/03	7.511 (19.078)	1.30 (3.31)	1.65 (4.20)	-21%	
Room 7 <sup>b</sup> , E1320, S2350	B-D	N/A	N/A	N/A	N/A	N/A	

in./yr = inch(es) per year

cm/yr = centimeter(s) per year

\*Chord is defined in "Geotechnical Analysis Report for July 2003–June 2004 Supporting Data." & Figure 5-1

<sup>a</sup>Increase in convergence rate is calculated from the difference between the 2003–2004 rate and the 2002–2003 rate.

<sup>b</sup>Panel 2, Room 7 closed during this reporting period.

All of Panel 3 was mined as of June 30, 2004. Monitoring data indicates a reduction in the extensometer and convergence rates as a result of initial mining. There is insufficient data for comparison to the previous reporting period.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

#### **6.4 Analysis of Extensometer and Convergence Point Data**

There were 19 monitored extensometers installed in the roofs of Panels 2 and 3. Eleven of the extensometers are located in Panel 2 and eight are in Panel 3. Most of the extensometers are located in the center of the disposal rooms with the exception of four extensometers located in the Panel 2 ventilation drifts. All of the extensometers in Panel 2 showed a displacement rate increase with the exception of the extensometer located in Panel 2, Room 6, which had an erroneous reading due to the loss of the deepest anchor. The convergence and roof beam expansion rate increases in Panel 2 are probably in response to floor trimming in Rooms 1 through 6 and the effect of mining of Panel 3.

During this reporting period, vertical convergence rates were read in the Panel 1 entries, Panel 2 and Panel 3. Convergence rates from the Panel 1 entries increased, with the exception of one point located at South 1950, East 457 which showed a 46 percent rate decrease. The rate increases in the Panel 1 entries can be attributed to rib and floor trimming conducted in preparation of the panel closure construction. Convergence monitoring nearest the panel closure wall indicate a significant reduction in closure rate since the closure wall was constructed.

The closure rates in Panel 2 increased with exception of one location in Panel 2, Room 5 and two in Panel 2, Rooms 6. At the center convergence point in Room 1, the closure rate increase was the highest at 40 percent. Convergence in South 2520 and the southernmost points in the rooms of Panel 2 were the most affected by the mining of Panel 3. Closure rates in Panel 2 show an indication of decreasing due to redistribution of Panel 3 mining stress.

Convergence data from Panel 3 indicate annualized closure rates varying from 11.41 in/year (28.98 cm/yr) at the center vertical point of Room 6 to 4.63 in/year (11.75 cm/yr) at the north quarter convergence vertical point of Room 5. The initial effects due to mining significantly decreased similar to that experienced in the previous panels. However, subsequent monitoring indicated some areas with increased convergence and roof beam deformation. These areas were associated with the development of separations along thin anhydrite stringers observed in the lower roof beam. The number and continuity of these stringers vary, however, these stringers are commonly observed throughout the panel. Deformation rates, in these areas, have stabilized or decreased in response to installation of ground control.

## **7.0 Geoscience Program**

---

The Geoscience Program confirms the suitability of the site through the collection of various geologic data and excavation characteristics from the underground facility. These include the inspection of open boreholes for fractures (separations) and offsets (lateral displacements) in roof beams and the mapping of fracture development on roof (back) surfaces.

Data collected through these activities support the design and evaluation of ground support systems (Westinghouse Waste Isolation Division, 1999).

During this reporting period, the following activities were performed:

- Borehole Inspections
- Fracture Mapping


### **7.1 Borehole Inspections**

Geotechnical observation boreholes are drilled at various locations throughout the underground facility. A location may contain one or more boreholes arranged in an array. These holes are drilled to depths that allow the monitoring of fracture development and offsetting and are inspected for the development of those features. Depending on location roof observation holes usually intersect clays "G" and "H" (Figure 7-1) or "H" and "I."


The clay seams nearest the excavation surfaces define the immediate roof beam. The roof beam is bounded by clay "G" in most of the access drifts and Panels 1 and 2. Some areas, such as the Salt Handling Shaft Station, portions of the East 0 and East 140 drifts, the south mains south of South 2620 and Panel 3 are excavated to clay "G" and so have roof beams bounded by clay "H."

The offset in a borehole is determined by visually estimating the degree of borehole occlusion. The direction of offset along clay seams is observed as the movement of the strata nearer to the observer relative to the strata farther away. Typically, the nearer strata move toward the center of the excavation (Figure 7-2). Based on previous observations in the underground, the magnitude of offset is usually greater in boreholes located near ribs than in those located along excavation centerlines. Offsetting along the clay layers is

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**



**Figure 7-1 Examples of Observation Borehole Layouts**



**Figure 7-2 Generalized Fracture Pattern at Lower Horizon**

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

observable until the total borehole offset is reached or visibility is obstructed by intervening offsets at other clay seams or fractures. Boreholes are inspected for fractures using an aluminum rod with a flattened steel wire probe attached to one end perpendicular to the rod (referred to as a "scratcher rod"). Fractures and clay seams are located by moving the probe along the inside of the borehole until it is snagged in one of these features. Depth to each feature is recorded, as is the magnitude of separations encountered. In addition, during this reporting period, a use of the borehole camera has been introduced in conjunction with the scratch rod.

The separation and offset data observed in accessible boreholes during this reporting period are presented in the supporting data document for this report.<sup>6</sup> Twenty-eight of the 45 observation holes in Panel 3 show some offset. Most offsets are minor, with the exception of six of the 11 holes in South 2750 which range from 33 to 42 percent closure. Only one hole in South 3080 exhibits closure of greater than 33 percent.

## **7.2      Fracture Mapping**

Routine mapping documents the progression of fractures in the roof exposed on the excavation surfaces of the drifts and rooms in the underground repository. The fracture surveys are generally performed on an annual basis, and the fracture maps are updated. The fracture maps facilitate the analysis of strain in the immediate roof-beam as they document the development and propagation of fractures through time. The supporting data document contains fracture maps for Panels 2 and 3. For this reporting period, Rooms 1 through 4 and a limited portion of South 2180 and South 2750 were accessible in Panel 2.

---

<sup>6</sup> Instrumentation data and data plots are available in "Geotechnical Analysis Report for July 2002-June 2003 Supporting Data." This document is available upon request from Washington TRU Solutions. Refer to Foreword and Acknowledgments for details and address.

**Geotechnical Analysis Report for July 2003 – June 2004  
DOE/WIPP 05-3177, Vol. 1**

This Page Intentionally  
Left Blank

## **8.0 Summary**

---

At the inception of the WIPP Project, criteria were developed that address the requirements for the design of WIPP (DOE, 1984). These criteria, in the form of design requirements, pertain to all aspects of the mined facility and its operation as a pilot plant for the demonstration of technical and operational methods for permanent disposal of contact-handled (CH) and remote-handled (RH) TRU waste. In 1994, as WIPP developed and the focus moved toward the permanent disposal of TRU waste, these design requirements were reassessed and replaced by a new set of requirements called system design descriptions (SDDs). Table 8-1 shows the comparison of these design requirements with conditions actually observed in the underground from July 2003 through June 2004.

Fracture development in the roof is primarily caused by the concentration of compressive stresses in the roof beam and is influenced by the size and shape of the excavation and the stratigraphy in the immediate vicinity of the opening. In a thick roof beam, pillar deformations induce lateral compressive stresses into the immediate roof and floor. With time, the buildup of stress causes differential movement along stratigraphic boundaries. This differential movement is identified as offsets in observation boreholes and is indicated by the bends in failed rock bolts. Large strains associated with lateral movements can induce fracturing in the roof, which is frequently seen near the ribs, however, this process may take a long time (years) to develop.

At some locations, such as Panel 3 where anhydrite stringers occur in the roof, clay or anhydrite stringers can dominate the effective thickness of the roof beam. The presence of these stringers causes the roof beam to behave as a series of thin independent beams. There is little or no tensile support provided across the stringer interface. As horizontal end loading continues, each beam can deflect downward causing a tensile fracture to develop along the bottom of the beam. These tensile fractures can develop in relatively new excavations soon after separation occurs along the stringer interface.

The location and initiation of interface separation is also influenced by slope of the stratigraphic beds. Currently the roofs and floors of the excavation are mined level through the sloping beds. At some locations, this may be the result the result of a significant differential roof beam thickness from one side of the excavation to the other. Areas with the thinnest beam are the most likely to separate and subsequently develop fracturing.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

Normal drift and room maintenance continued during this reporting period with rib, roof, and floor scaling and trimming in various locations, and rock bolts and wire mesh installed as needed. Supplemental ground control systems consisting of resin anchored bolts and roof mats were installed in sections of the E140 drift, Panel 3 and the Waste Shaft Station.

New geomechanical instrumentation was installed in Panel 3 and the Panel 3 access drifts and in various locations throughout the repository to replace mined-out instruments. Remote convergence monitoring no longer continues in non-accessible areas in the north. All accessible areas of the underground are connected to data loggers or are monitored manually.

The *in situ* performance of the excavations generally continues to satisfy the appropriate design criteria, although specific areas are being identified where deterioration resulting from aging must be addressed through routine maintenance and implementation of engineered systems. This deterioration has been identified through the analysis of data acquired from geomechanical instrumentation and the Geoscience Program. If the planned life of some of the openings needs to be extended, redesigning the geometry of the access drifts (e.g., changing the horizontal and vertical dimensions) or additional ground control (e.g., roof removal, installing bolts, mesh, or straps) may be necessary. The ground conditions in the Waste Disposal Area and associated waste transport routes continue to slowly deteriorate; however, routine ground control installations and maintenance continue to allow safe access in the underground facility.

In addition to underground instrumentation, qualitative assessments of fracture development are documented through mapping the underground repository and inspecting the observation boreholes. The information acquired from these programs provides early detection of ground deterioration, contributes to the understanding of the dynamic geomechanical processes in the WIPP underground, and aids in the design of effective ground control and support systems.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

**Table 8-1 Comparison of Excavation Performance to System Design Requirements**

<b>Requirement</b>	<b>Comments</b>
"The lining shall be designed for a hydrostatic pressure. . . ."	Water pressure observed on piezometers located behind the shaft liners remains below design levels.
"The key shall be designed to resist the lateral pressure generated by salt creep."	Geomechanical data from the Waste Shaft indicate that the shaft key is minimally loaded and is structurally stable. Visual inspections of all shaft keys do not indicate any deterioration due to creep loading.
"The key shall be designed to retain the rock formation and will be provided with chemical seal rings and a water collection ring with drains to prevent water from flowing down the unlined shaft from the lining above."	Shaft inspection observations and instrumentation show no indication of instability due to salt dissolution.
"The underground waste disposal facilities shall be designed to provide space and adequate access for the underground equipment and temporary storage space to support underground operations."	Geomechanical instrument data and visual observations indicate that the current design provides adequate access and storage space. Ground control maintenance is performed as necessary to maintain access.
"Entries and sub-entries to the underground disposal area and the experimental areas shall be provided and sized for personnel safety, adequate air flow, and space for equipment."	Deformation of excavation remains within the required limits. Normal periodic maintenance consisting of rock bolting, wire meshing, trimming, and scaling continue throughout the repository. All of the Northeast and Northwest Areas, a former experimental area, is now deactivated and closed to access.
"Geomechanical instrumentation shall be provided to measure the cumulative deformation of the rock mass surrounding mined drifts. . . ."	Geotechnical instrumentation is operated and maintained to meet this requirement. This annual report acts to provide a summary and analysis of the geomechanical data.

**Geotechnical Analysis Report for July 2003 – June 2004  
DOE/WIPP 05-3177, Vol. 1**

This Page Intentionally  
Left Blank

## **9.0 References and Bibliography**

---

DOE, see U.S. Department of Energy

Public Law 96-164, Department of Energy National Security and Military Applications of Nuclear Energy Authorization Act of 1980.

Title 40 CFR Part 191, "Environmental Radiation Protection Standards for Management and Disposal of Spent Nuclear Fuel, High-Level and Transuranic Radioactive Wastes."

Title 40 CFR Part 194, "Criteria for the Certification and Re-certification of the Waste Isolation Pilot Plant's Compliance with the 40 CFR Part 191 Disposal Regulations."

Holt, R.M., and D.W. Powers, 1990, *Geologic Mapping of the Air Intake Shaft at the Waste Isolation Pilot Plant*, DOE/WIPP 90-051, Waste Isolation Pilot Plant, Carlsbad, New Mexico.

Holt, R.M., and D.W. Powers, 1984, "Geotechnical Activities in the Waste Handling Shaft, Waste Isolation Pilot Plant (WIPP) Project, Southeastern New Mexico," WTSD-TME 038, Waste Isolation Pilot Plant, Carlsbad, New Mexico.

New Mexico Environment Department (NMED), 1999, "Waste Isolation Pilot Plant Hazardous Waste Facility Permit," NM4890139088-TSDF, Santa Fe, New Mexico.

Powers, D.W., and R.M. Holt, 1993, "The Upper Cenozoic Gatuña Formation of Southeastern New Mexico," New Mexico Geological Society Guidebook, 44th Field Conference, Carlsbad Region, New Mexico and West Texas, D.W. Love et al., Eds., pp 271–282.

Powers, D.W., and R.M. Holt, 1995, "Gatuña Formation (Miocene to Pleistocene) Geology and Paleohydrology," prepared for Westinghouse Waste Isolation Division by International Technology Corporation, Albuquerque, New Mexico.

Powers, D.W., S.J. Lambert, S.E. Shaffer, L.R. Hill, and W.D. Weart, Eds., 1978, "Geological Characterization Report, Waste Isolation Pilot Plant (WIPP) Site, Southeastern New Mexico," Vols. I and II, SAND 78-1596; Sandia National Laboratories, Albuquerque, New Mexico.

U.S. Department of Energy (DOE), 2000, *Brine Generation Study*, DOE/WIPP 00-2000, Waste Isolation Pilot Plant, Carlsbad, New Mexico.

U.S. Department of Energy (DOE), 1986a, *Interim Geotechnical Field Data Report*, DOE/WIPP 86-012, Waste Isolation Pilot Plant, Carlsbad, New Mexico.

U.S. Department of Energy (DOE), 1986b, *Waste Isolation Pilot Plant Design Validation Final Report*, DOE/WIPP 86-010; Prepared by Bechtel National, Inc., for the U.S. Department of Energy, San Francisco, California.

**Geotechnical Analysis Report for July 2003 – June 2004**  
**DOE/WIPP 05-3177, Vol. 1**

U.S. Department of Energy (DOE), 1986c, *Geotechnical Activities in the Exhaust Shaft*, DOE/WIPP 86-008, Waste Isolation Pilot Plant, Carlsbad, New Mexico.

U.S. Department of Energy (DOE), 1985, *Quarterly Geotechnical Field Data Report*, DOE/WIPP-221, Waste Isolation Pilot Plant, Carlsbad, New Mexico.

U.S. Department of Energy (DOE), 1984, *Design Criteria, Waste Isolation Pilot Plant (WIPP) Revised Mission Concept-IIA*, DOE/WIPP-071; Waste Isolation Pilot Plant, Carlsbad, New Mexico.

U.S. Department of Energy (DOE), 1983, *Summary of the Results of the Evaluation of the WIPP Site and Preliminary Design Validation Program*, DOE/WIPP-161; Waste Isolation Pilot Plant, Carlsbad, New Mexico.

**Geotechnical Analysis  
Report  
for  
July 2003 - June 2004**

**Supporting Data**

March 2005



Waste Isolation Pilot Plant

## **FOREWORD AND ACKNOWLEDGMENTS**

This Supporting Data Document to the Geotechnical Analysis Report (GAR) presents the data that were used to assess the geotechnical status of the Waste Isolation Pilot Plant (WIPP). This report presents data for the underground facility including the shafts, shaft stations, access drifts, Northern Experimental Area, and the Waste Disposal Area. The data are presented as both tables and plots in order to meet the needs of several audiences. This report presents the data collected through June 30, 2004. This data can be provided in its original format upon written request to the U.S. Department of Energy (DOE) at the following address:

U.S. Department of Energy  
Carlsbad Field Office  
P.O. Box 3090  
Carlsbad, NM 88221-3090

The Geotechnical Analysis Report is a multi-author report that was prepared by Washington TRU Solutions for the DOE, Carlsbad Field Office, Carlsbad, New Mexico. Work was supported by the DOE under Contract No. DE-AC29-01AL66444.

## **Table of Contents**

---

List of Tables.....	iii
List of Figures .....	v
1.0      Introduction.....	1-1
1.1      Instrumentation.....	1-1
1.2      Data Plot Explanation.....	1-2
1.3      Report Organization.....	1-2
2.0      Instrumentation Summary for Shafts .....	2-1
3.0      Instrumentation Summary for Shaft Stations.....	3-1
4.0      Instrumentation Summary for the Access Drifts.....	4-1
5.0      Instrumentation Summary for the Northern Experimental Area.....	5-1
6.0      Instrumentation Summary for the Waste Disposal Area.....	6-1
7.0      Geoscience Program Supporting Data .....	7-1
7.1      Borehole Inspections.....	7-1
7.2      Fracture Mapping.....	7-1

This Page Intentionally  
Left Blank

## **List of Tables**

---

<b>Table</b>	<b>Title</b>	<b>Page No.</b>
2-1	Salt Handling Shaft Data Analysis .....	2-3
2-2	Waste Shaft Data Analysis .....	2-13
2-3	Exhaust Shaft Data Analysis .....	2-23
3-1	Salt Handling Shaft Station Data Analysis.....	3-3
3-2	Waste Shaft Station Data Analysis .....	3-7
3-3	Air Intake Shaft Station Data Analysis.....	3-15
4-1	Access Drifts Data Analysis .....	4-3
6-1	Panel 1 Access Drifts Data Analysis .....	6-3
6-2	Panel 2 Data Analysis.....	6-12
6-3	Panel 3 Data Analysis.....	6-38
7-1	Observation Borehole Fractures and Offset Data Summary .....	7-2
7-2	Summary of New Boreholes.....	7-16

This Page Intentionally  
Left Blank

## ***List of Figures***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
Shafts and Keys		
Salt Handling Shaft		
2-1	Piezometers 37X-PE-00201 and 37X-PE-00202 Salt Handling Shaft – Level 580 at the Forty-niner Member .....	2-5
2-2	Piezometers 37X-PE-00203 and 37X-PE-00204 Salt Handling Shaft – Level 620 at the Magenta Dolomite Member .....	2-5
2-3	Piezometers 37X-PE-00205 and 37X-PE-00206 Salt Handling Shaft – Level 691 at the Tamarisk Member .....	2-6
2-4	Piezometers 37X-PE-00207 Salt Handling Shaft – Level 726 at the Culebra Dolomite Member .....	2-6
2-5	Piezometers 37X-PE-00209 and 37X-PE-00210 Salt Handling Shaft – Level 802 at the Los Medaños Member.....	2-7
2-6	Piezometers 37X-PE-00211 and 37X-PE-00212 Salt Handling Shaft – Level 850 at the Rustler-Salado Contact.....	2-7
2-7	Earth Pressure Cells Behind Shaft Key Salt Handling Shaft Key – Level 860 .....	2-8
2-8	Spot Welded Strain Gages Salt Handling Shaft Key – Level 856.3 .....	2-8
2-9	Spot Welded Strain Gages Salt Handling Shaft Key – Level 862.4 .....	2-9
2-10	Embedment Strain Gages Salt Handling Shaft Key – Level 856.3.....	2-9
2-11	Embedment Strain Gages Salt Handling Shaft Key – Level 862.4.....	2-10
2-12	Embedment Strain Gages Salt Handling Shaft Key – Level 856.3.....	2-10
2-13	Embedment Strain Gages Salt Handling Shaft Key – Level 862.4.....	2-11
Waste Shaft		
2-14	Extensometer 31X-GE-00203 Waste Shaft – Level 1071 / S 15W .....	2-15
2-15	Extensometer 31X-GE-00204 Waste Shaft – Level 1566 / N 45W.....	2-15
2-16	Extensometer 31X-GE-00205 Waste Shaft – Level 1566 / N 75E.....	2-16
2-17	Extensometer 31X-GE-00206 Waste Shaft – Level 1566 / S 15W .....	2-16
2-18	Extensometer 31X-GE-00207 Waste Shaft – Level 2059 / N 45W.....	2-17
2-19	Extensometer 31X-GE-00208 Waste Shaft – Level 2059 / N 75E.....	2-17
2-20	Extensometer 31X-GE-00209 Waste Shaft – Level 2059 / S 15W .....	2-18
2-21	Piezometers 31X-PE-00201 and 31X-PE-00202 Waste Shaft – Level 532 at the Base of Dewey Lake Redbeds.....	2-18
2-22	Piezometers 31X-PE-00203 and 31X-PE-00204 Waste Shaft – Level 611 at the Magenta Dolomite Member.....	2-19
2-23	Piezometers 31X-PE-00205 and 31X-PE-00206 Waste Shaft – Level 669 at the Tamarisk Member.....	2-19
2-24	Piezometer 31X-PE-00208 Waste Shaft – Level 717 at the Culebra Dolomite Member.....	2-20
2-25	Piezometers 31X-PE-00209 and 31X-PE-00210 Waste Shaft – Level 758 at the Los Medaños Member.....	2-20

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
2-26	Piezometers 31X-PE-00211 and 31X-PE-00212 Waste Shaft – Level 845 at the Rustler-Salado Contact.....	2-21
2-27	Earth Pressure Cells Waste Shaft Key – Level 866 .....	2-21
Exhaust Shaft		
2-28	Extensometer 35X-GE-00204 Exhaust Shaft – Level 1573 / N 75E.....	2-25
2-29	Extensometer 35X-GE-00205 Exhaust Shaft – Level 1573 / N 45W.....	2-25
2-30	Extensometer 35X-GE-00206 Exhaust Shaft – Level 1573 / S 15W .....	2-26
2-31	Extensometer 35X-GE-00207 Exhaust Shaft – Level 2066 / N 75E .....	2-26
2-32	Piezometer 35X-PE-00202 Exhaust Shaft – Level 544 at the Base of Dewey Lake Redbeds.....	2-27
2-33	Piezometers 35X-PE-00204 and 35X-PE-00205 Exhaust Shaft – Level 615 at the Magenta Dolomite Member.....	2-27
2-34	Piezometer 35X-PE-00208 Exhaust Shaft – Level 673 at the Tamarisk Member.....	2-28
2-35	Piezometer 35X-PE-00210 Exhaust Shaft – Level 721 at the Culebra Dolomite Member .....	2-28
2-36	Piezometers 35X-PE-00213 and 35X-PE-00214 Exhaust Shaft – Level 768 at the Los Medaños Member.....	2-29
2-37	Piezometers 35X-PE-00216 and 35X-PE-00218 Exhaust Shaft – Level 850 at the Rustler-Salado Contact.....	2-29
2-38	Piezometers 35X-PE-00219 and 35X-PE-00220 Exhaust Shaft – Level 887 below the Lower Chemical Seal.....	2-30
2-39	Earth Pressure Cells 35X-WE-00201 and 35X-WE-00202 Exhaust Shaft Key – Level 874.....	2-30
Shaft Stations		
Salt Handling Shaft Station		
3-1	Convergence Point Array Salt Handling Shaft Station 12 Feet West of Shaft – Roof to Floor .....	3-4
3-2	Convergence Point Array Salt Handling Shaft Station at South 18 – All Chords .....	3-4
3-3	Convergence Point Array Salt Handling Shaft Station at South 30 – All Chords .....	3-5
3-4	Convergence Point Array Salt Handling Shaft Station at South 65 – Roof to Floor .....	3-5
Waste Shaft Station		
3-5	Extensometer 51X-GE-00268 Waste Shaft Station at West 30 – Roof.....	3-9
3-6	Extensometer 51X-GE-00356 Waste Shaft Station Brow – North.....	3-9
3-7	Extensometer 51X-GE-00357 Waste Shaft Station Brow – South.....	3-10
3-8	Extensometer 51X-GE-01025 Waste Shaft Station at East 87 – Roof .....	3-10
3-9	Extensometer 51X-GE-00279 Waste Shaft Station at East 140 – Roof .....	3-11
3-10	Convergence Point Array Waste Shaft Station at East 30 – All Chords.....	3-11
3-11	Convergence Point Array Waste Shaft Station at East 90 – All Chords.....	3-12
3-12	Rock Bolt Load Cells Waste Shaft Station Brow – Roof Bolts Set 1 .....	3-12

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
3-13	Rock Bolt Load Cells Waste Shaft Station Brow – Roof Bolts Set 2.....	3-13
Air Intake Shaft Station		
3-14	Rock Bolt Load Cells Air Intake Shaft Station Brow – South Side Roof Bolts Set 1.....	3-16
3-15	Rock Bolt Load Cells Air Intake Shaft Station Brow – South Side Roof Bolts Set 2.....	3-16
3-16	Rock Bolt Load Cells Air Intake Shaft Station Brow – North Side Roof Bolts Set 1.....	3-17
3-17	Rock Bolt Load Cells Air Intake Shaft Station Brow – North Side Roof Bolts Set 2.....	3-17
Access Drifts		
4-1	Extensometer 51X-GE-00265 S700 Drift at E220 – Roof.....	4-19
4-2	Extensometer 51X-GE-00364 E140 Drift at N1266 – Roof.....	4-19
4-3	Extensometer 51X-GE-00365 E140 Drift at N940 – Roof.....	4-20
4-4	Extensometer 41X-GE-00106 E140 Drift at N250 – Roof.....	4-20
4-5	Extensometer 51X-GE-00105-3 E140 Drift at N150 – Roof.....	4-21
4-6	Extensometer 51X-GE-00276 E140 Drift at S700 Drift Intersection – Roof.....	4-21
4-7	Extensometer 51X-GE-00474 E120 at S1000 – Roof.....	4-22
4-8	Extensometer 51X-GE-00472 E140 Drift at S1000 – Roof.....	4-22
4-9	Extensometer 51X-GE-00473 E160 at S1000 – Roof.....	4-23
4-10	Extensometer 51X-GE-00464 E140 Drift at S1025 – Roof.....	4-23
4-11	Extensometer 51X-GE-00333 E140 Drift at S1075 – Roof.....	4-24
4-12	Extensometer 51X-GE-00460-2 E140 Drift at S1150 – Roof.....	4-24
4-13	Extensometer 41X-GE-00103 E140 Drift at S1150 – Roof.....	4-25
4-14	Extensometer 51X-GE-00461 E140 Drift at S1225 – Roof.....	4-25
4-15	Extensometer 51X-GE-00334 E140 Drift at S1225 – Roof.....	4-26
4-16	Extensometer 51X-GE-00462 E120 at S1300 – Roof.....	4-26
4-17	Extensometer 51X-GE-00465 E140 Drift at S1300 – Roof.....	4-27
4-18	Extensometer 51X-GE-00335 E140 Drift at S1300 Drift Intersection – Roof.....	4-27
4-19	Extensometer 51X-GE-00463 E160 at S1300 – Roof.....	4-28
4-20	Extensometer 51X-GE-00336 E140 Drift at S1375 – Roof.....	4-28
4-21	Extensometer 41X-GE-00102-2 E140 Drift at S1450 – Roof.....	4-29
4-22	Extensometer 51X-GE-00411 E140 Drift at S1525 – Roof.....	4-29
4-23	Extensometer 51X-GE-00442 E120 at S1600 – Roof.....	4-30
4-24	Extensometer 51X-GE-00446 E140 Drift at S1600 – Roof.....	4-30
4-25	Extensometer 51X-GE-00338-2 E140 Drift at S1600 Drift Intersection – Roof.....	4-31
4-26	Extensometer 51X-GE-00441 E160 at S1600 – Roof.....	4-31
4-27	Extensometer 51X-GE-00443 E140 Drift at S1685 – Roof.....	4-32
4-28	Extensometer 51X-GE-00339-2 E140 Drift at S1685 – Roof.....	4-32
4-29	Extensometer 51X-GE-00492 E140 Drift at S2750 Drift Intersection – Roof.....	4-33
4-30	Extensometer 51X-GE-00367 E140 Drift at S2916 – Roof.....	4-33

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
4-31	Extensometer 51X-GE-00493 E140 Drift at S2916 – Roof.....	4-34
4-32	Extensometer 51X-GE-00361 E0 Drift at N1266 – Roof.....	4-34
4-33	Extensometer 51X-GE-00352 E0 Drift at N940 – Roof.....	4-35
4-34	Extensometer 51X-GE-00353 E0 Drift at N626 – Roof.....	4-35
4-35	Extensometer 51X-GE-00355 E0 Drift at N300 – Roof.....	4-36
4-36	Extensometer 51X-GE-00481 N300 Drift at W10 – Roof.....	4-36
4-37	Extensometer 41X-GE-00127 N300 Drift at W110 – Roof.....	4-37
4-38	Extensometer 41X-GE-00126 N300 Drift at W212 – Roof.....	4-37
4-39	Extensometer 41X-GE-00125 N215 Drift at W417 – Roof.....	4-38
4-40	Extensometer 41X-GE-00124 N215 Drift at W519 – Roof.....	4-38
4-41	Extensometer 41X-GE-00123 W620 Drift at N93 – Roof.....	4-39
4-42	Extensometer 41X-GE-00122 W620 Drift at S65 – Roof.....	4-39
4-43	Extensometer 51X-GE-00494 E300 Drift at S2892 – Roof.....	4-40
4-44	Extensometer 51X-GE-00490 W30 Drift at S2750 Drift Intersection – Roof.....	4-40
4-45	Extensometer 51X-GE-00491 W30 Drift at S2916 – Roof.....	4-41
4-46	Extensometer 51X-GE-00489 W30 Drift at S3080 Drift Intersection – Roof.....	4-41
4-47	Extensometer 51X-GE-00495 W170 Drift at S2634 – Roof.....	4-42
4-48	Convergence Point Array E300 Shop – E300 Drift at N250 – Roof to Floor .....	4-42
4-49	Convergence Point Array E300 Shop – E300 Drift at N170 – All Chords.....	4-43
4-50	Convergence Point Array E300 Shop – E300 Drift at N45 – All Chords.....	4-43
4-51	Convergence Point Array E300 Shop – E300 Drift at S45 – All Chords .....	4-44
4-52	Convergence Point Array E300 Drift at S90 Drift Intersection – Roof to Floor.....	4-44
4-53	Convergence Point Array E300 Drift at S250 – All Chords.....	4-45
4-54	Convergence Point Array E300 Drift at S700 Drift Intersection – Roof to Floor.....	4-45
4-55	Convergence Point Array E300 Drift at S850 – All Chords.....	4-46
4-56	Convergence Point Array E300 Drift at S1000 Drift Intersection – Roof to Floor.....	4-46
4-57	Convergence Point Array E300 Drift at S1150 – Roof to Floor.....	4-47
4-58	Convergence Point Array E300 Drift at S1150 – Rib to Rib.....	4-47
4-59	Convergence Point Array E300 Drift at S1300 Drift Intersection – Roof to Floor.....	4-48
4-60	Convergence Point Array E300 Drift at S1450 – All Chords.....	4-48
4-61	Convergence Point Array E300 Drift at S1687 – All Chords.....	4-49
4-62	Convergence Point Array E300 Drift at S1775 – All Chords.....	4-49
4-63	Convergence Point Array E300 Drift at S1862 – All Chords.....	4-50
4-64	Convergence Point Array E300 Drift at S2065 – All Chords.....	4-50
4-65	Convergence Point Array E300 Drift at S2275 – All Chords.....	4-51
4-66	Convergence Point Array E300 Drift at S2350 – All Chords.....	4-51
4-67	Convergence Point Array E300 Drift at S2425 – All Chords.....	4-52
4-68	Convergence Point Array E300 Drift at S2634 – All Chords.....	4-52
4-69	Convergence Point Array E300 Drift at S2833 – All Chords.....	4-53
4-70	Convergence Point Array E300 Drift at S2916 – All Chords.....	4-53
4-71	Convergence Point Array E300 Drift at S2998 – All Chords.....	4-54
4-72	Convergence Point Array E300 Drift at S3195 – All Chords.....	4-54
4-73	Convergence Point Array E140 Drift at N780 Drift Intersection – Roof to Floor.....	4-55
4-74	Convergence Point Array E140 Drift at N686 – All Chords .....	4-55

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
4-75	Convergence Point Array E140 Drift at N626 – All Chords .....	4-56
4-76	Convergence Point Array E140 Drift at N562 – All Chords .....	4-56
4-77	Convergence Point Array E140 Drift at N460 Drift Intersection – Roof to Floor.....	4-57
4-78	Convergence Point Array E140 Drift at N355 – All Chords .....	4-57
4-79	Convergence Point Array E140 Drift at N220 – Roof to Floor.....	4-58
4-80	Convergence Point Array E140 Drift at N150 Drift Intersection – Roof to Floor.....	4-58
4-81	Convergence Point Array E140 Drift at N5 – All Chords .....	4-59
4-82	Convergence Point Array E140 Drift at S90 Drift Intersection – Roof to Floor.....	4-59
4-83	Convergence Point Array E140 Drift at S262 – All Chords.....	4-60
4-84	Convergence Point Array E140 Drift at S460 – All Chords.....	4-60
4-85	Convergence Point Array E140 Drift at S550 – All Chords.....	4-61
4-86	Convergence Point Array E140 Drift at S700 Drift Intersection – Roof to Floor Centerline .....	4-61
4-87	Convergence Point Array E140 Drift at S700 Drift Intersection – Roof to Floor Quarter Points.....	4-62
4-88	Convergence Point Array E140 Drift at S850 – Roof to Floor.....	4-62
4-89	Convergence Point Array E140 Drift at S850 – Rib to Rib.....	4-63
4-90	Convergence Point Array E140 Drift at S1000 Drift Intersection – Roof to Floor.....	4-63
4-91	Convergence Point Array E140 Drift at S1025 – Roof to Floor.....	4-64
4-92	Convergence Point Array E140 Drift at S1075 – All Chords.....	4-64
4-93	Convergence Point Array E140 Drift at S1150 – Roof to Floor.....	4-65
4-94	Convergence Point Array E140 Drift at S1150 – Rib to Rib.....	4-65
4-95	Convergence Point Array E140 Drift at S1225 – All Chords.....	4-66
4-96	Convergence Point Array E140 Drift at S1300 Drift Intersection – Roof to Floor.....	4-66
4-97	Convergence Point Array E140 Drift at S1378 – Roof to Floor.....	4-67
4-98	Convergence Point Array E140 Drift at S1378 – Rib to Rib.....	4-67
4-99	Convergence Point Array E140 Drift at S1450/S1456 – Roof to Floor – Centerline .....	4-68
4-100	Convergence Point Array E140 Drift at S1450/S1456 – Roof to Floor – Quarter Points.....	4-68
4-101	Convergence Point Array E140 Drift at S1450/S1456 – Rib to Rib – Midheight.....	4-69
4-102	Convergence Point Array E140 Drift at S1450/S1456 – Rib to Rib – Quarter Points.....	4-69
4-103	Convergence Point Array E140 Drift at S1534 – All Chords.....	4-70
4-104	Convergence Point Array E140 Drift at S1600 Drift Intersection – Roof to Floor.....	4-70
4-105	Convergence Point Array E140 Drift at S1687 – All Chords.....	4-71
4-106	Convergence Point Array E140 Drift at S1775 – Roof to Floor.....	4-71
4-107	Convergence Point Array E140 Drift at S1775 – Rib to Rib.....	4-72
4-108	Convergence Point Array E140 Drift at S1862 – All Chords.....	4-72
4-109	Convergence Point Array E140 Drift at S1950 Drift Intersection – Roof to Floor.....	4-73
4-110	Convergence Point Array E140 Drift at S2007 – Roof to Floor.....	4-73
4-111	Convergence Point Array E140 Drift at S2065 – All Chords.....	4-74
4-112	Convergence Point Array E140 Drift at S2122 – Roof to Floor.....	4-74
4-113	Convergence Point Array E140 Drift at S2180 Drift Intersection – Roof to Floor.....	4-75

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
4-114	Convergence Point Array E140 Drift at S2275 – All Chords.....	4-75
4-115	Convergence Point Array E140 Drift at S2350 – All Chords.....	4-76
4-116	Convergence Point Array E140 Drift at S2425 – All Chords.....	4-76
4-117	Convergence Point Array E140 Drift at S2520 Drift Intersection – Roof to Floor.....	4-77
4-118	Convergence Point Array E140 Drift at S2634 – All Chords.....	4-77
4-119	Convergence Point Array E140 Drift at S2750 Drift Intersection – Roof to Floor.....	4-78
4-120	Convergence Point Array E140 Drift at S2833 – All Chords.....	4-78
4-121	Convergence Point Array E140 Drift at S2915 – All Chords.....	4-79
4-122	Convergence Point Array E140 Drift at S2998 – All Chords.....	4-79
4-123	Convergence Point Array E140 Drift at S3080 Drift Intersection – Roof to Floor.....	4-80
4-124	Convergence Point Array E140 Drift at S3195 – All Chords.....	4-80
4-125	Convergence Point Array E140 Drift at S3310 Drift Intersection – Roof to Floor.....	4-81
4-126	Convergence Point Array E0 Drift at N1266 – All Chords .....	4-81
4-127	Convergence Point Array E0 Drift at N940 – All Chords .....	4-82
4-128	Convergence Point Array E0 Drift at N780 – Roof to Floor.....	4-82
4-129	Convergence Point Array E0 Drift at N686 – All Chords .....	4-83
4-130	Convergence Point Array E0 Drift at N626 – All Chords .....	4-83
4-131	Convergence Point Array E0 Drift at N562 – All Chords .....	4-84
4-132	Convergence Point Array E0 Drift at N460 Drift Intersection – Roof to Floor.....	4-84
4-133	Convergence Point Array E0 Drift at N300 – All Chords .....	4-85
4-134	Convergence Point Array E0 Drift at N225 – All Chords .....	4-85
4-135	Convergence Point Array E0 Drift at N75 – All Chords .....	4-86
4-136	Convergence Point Array W30 Drift at S120 – Roof to Floor.....	4-86
4-137	Convergence Point Array W30 Drift at S250 – All Chords.....	4-87
4-138	Convergence Point Array W30 Drift at S400 Drift Intersection – Roof to Floor.....	4-87
4-139	Convergence Point Array W30 Drift at S500 – All Chords.....	4-88
4-140	Convergence Point Array W30 Drift at S700 Drift Intersection – Roof to Floor.....	4-88
4-141	Convergence Point Array W30 Drift at S850 – All Chords.....	4-89
4-142	Convergence Point Array W30 Drift at S1000 Drift Intersection – Roof to Floor.....	4-89
4-143	Convergence Point Array W30 Drift at S1100 – Roof to Floor.....	4-90
4-144	Convergence Point Array W30 Drift at S1200 – Roof to Floor.....	4-90
4-145	Convergence Point Array W30 Drift at S1300 Drift Intersection – Roof to Floor.....	4-91
4-146	Convergence Point Array W30 Drift at S1453 – All Chords.....	4-91
4-147	Convergence Point Array W30 Drift at S1600 Drift Intersection – Roof to Floor.....	4-92
4-148	Convergence Point Array W30 Drift at S1775 – All Chords.....	4-92
4-149	Convergence Point Array W30 Drift at S1950 Drift Intersection – Roof to Floor.....	4-93
4-150	Convergence Point Array W30 Drift at S2067 – All Chords.....	4-93
4-151	Convergence Point Array W30 Drift at S2180 Drift Intersection – Roof to Floor.....	4-94
4-152	Convergence Point Array W30 Drift at S2275 – All Chords.....	4-94
4-153	Convergence Point Array W30 Drift at S2350 – All Chords.....	4-95
4-154	Convergence Point Array W30 Drift at S2425 – All Chords.....	4-95
4-155	Convergence Point Array W30 Drift at S2520 Drift Intersection – Roof to Floor.....	4-96
4-156	Convergence Point Array W30 Drift at S2685 – All Chords.....	4-96
4-157	Convergence Point Array W30 Drift at S2750 Drift Intersection – Roof to Floor.....	4-97

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
4-158	Convergence Point Array W30 Drift at S2833 – All Chords.....	4-97
4-159	Convergence Point Array W30 Drift at S2916 – All Chords.....	4-98
4-160	Convergence Point Array W30 Drift at S2998 – All Chords.....	4-98
4-161	Convergence Point Array W30 Drift at S3080 Drift Intersection – Roof to Floor .....	4-99
4-162	Convergence Point Array W30 Drift at S3195 – All Chords.....	4-99
4-163	Convergence Point Array W30 Drift at S3310 Drift Intersection – Roof to Floor.....	4-100
4-164	Convergence Point Array W170 Drift at N150 Drift Intersection – Roof to Floor....	4-100
4-165	Convergence Point Array W170 Drift at S5 – All Chords.....	4-101
4-166	Convergence Point Array W170 Drift at S90 – Roof to Floor.....	4-101
4-167	Convergence Point Array W170 Drift at S232 – All Chords.....	4-102
4-168	Convergence Point Array W170 Drift at S400 Drift Intersection – Roof to Floor.....	4-102
4-169	Convergence Point Array W170 Drift at S560 – All Chords.....	4-103
4-170	Convergence Point Array W170 Drift at S700 Drift Intersection – Roof to Floor.....	4-103
4-171	Convergence Point Array W170 Drift at S850 – Roof to Floor – Centerline.....	4-104
4-172	Convergence Point Array W170 Drift at S850 – Roof to Floor – Quarter Points .....	4-104
4-173	Convergence Point Array W170 Drift at S850 – Rib to Rib.....	4-105
4-174	Convergence Point Array W170 Drift at S1000 – Roof to Floor.....	4-105
4-175	Convergence Point Array W170 Drift at S1150 – All Chords.....	4-106
4-176	Convergence Point Array W170 Drift at S1300 Drift Intersection – Roof to Floor...	4-106
4-177	Convergence Point Array W170 Drift at S1445 – All Chords.....	4-107
4-178	Convergence Point Array W170 Drift at S1600 Drift Intersection – Roof to Floor...	4-107
4-179	Convergence Point Array W170 Drift at S1779 – All Chords.....	4-108
4-180	Convergence Point Array W170 Drift at S1950 Drift Intersection – Roof to Floor...	4-108
4-181	Convergence Point Array W170 Drift at S2060 – All Chords.....	4-109
4-182	Convergence Point Array W170 Drift at S2180 Drift Intersection – Roof to Floor...	4-109
4-183	Convergence Point Array W170 Drift at S2275 – All Chords.....	4-110
4-184	Convergence Point Array W170 Drift at S2350 – All Chords.....	4-110
4-185	Convergence Point Array W170 Drift at S2425 – All Chords.....	4-111
4-186	Convergence Point Array W170 Drift at S2520 Drift Intersection – Roof to Floor...	4-111
4-187	Convergence Point Array W170 Drift at S2685 – All Chords.....	4-112
4-188	Convergence Point Array W170 Drift at S2750 Drift Intersection – Roof to Floor...	4-112
4-189	Convergence Point Array W170 Drift at S2833 – All Chords.....	4-113
4-190	Convergence Point Array W170 Drift at S2916 – All Chords.....	4-113
4-191	Convergence Point Array W170 Drift at S2998 – All Chords.....	4-114
4-192	Convergence Point Array W170 Drift at S3080 Drift Intersection – Roof to Floor...	4-114
4-193	Convergence Point Array W170 Drift at S3195 – All Chords.....	4-115
4-194	Convergence Point Array W170 Drift at S3310 Drift Intersection – Roof to Floor...	4-115
4-195	Convergence Point Array N780 Drift at E70 – All Chords .....	4-116
4-196	Convergence Point Array N460 Drift at E70 – All Chords .....	4-116
4-197	Convergence Point Array N250 Drift at E220 – All Chords .....	4-117
4-198	Convergence Point Array N300 Drift at W170 – All Chords.....	4-117
4-199	Convergence Point Array N215 Drift at W500 – All Chords.....	4-118
4-200	Convergence Point Array N215 Drift at W620 at Air Intake Shaft – Roof to Floor..	4-118
4-201	Convergence Point Array N140 Drift at E90 – All Chords .....	4-119

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
4-202	Convergence Point Array N140 Drift at W50 – Rib to Rib.....	4-119
4-203	Convergence Point Array S90 Drift at W120 – All Chords.....	4-120
4-204	Convergence Point Array S90 Drift at W400 – All Chords.....	4-120
4-205	Convergence Point Array S90 Drift at W590 – All Chords.....	4-121
4-206	Convergence Point Array S90 Drift at W620 – Roof to Floor.....	4-121
4-207	Convergence Point Array S90 Drift at W770 – All Chords.....	4-122
4-208	Convergence Point Array S400 Core Storage Library – All Chords .....	4-122
4-209	Convergence Point Array S700 Drift at E205 – All Chords.....	4-123
4-210	Convergence Point Array S700 Drift at W98 – Roof to Floor.....	4-123
4-211	Convergence Point Array S1000 Drift at E160 – Roof to Floor.....	4-124
4-212	Convergence Point Array S1000 Drift at E120 – Roof to Floor.....	4-124
4-213	Convergence Point Array S1000 Drift at E58 – All Chords.....	4-125
4-214	Convergence Point Array S1000 Drift at W98 – All Chords.....	4-125
4-215	Convergence Point Array S1300 Drift at E160 – Roof to Floor.....	4-126
4-216	Convergence Point Array S1300 Drift at E120 – Roof to Floor.....	4-126
4-217	Convergence Point Array S1300 Drift at E24 – Roof to Floor.....	4-127
4-218	Convergence Point Array S1300 Drift at W55 – Roof to Floor.....	4-127
4-219	Convergence Point Array S1300 Drift at W100 – Roof to Floor.....	4-128
4-220	Convergence Point Array S1600 Drift at E170 – Roof to Floor.....	4-128
4-221	Convergence Point Array S1600 Drift at E110 – Roof to Floor.....	4-129
4-222	Convergence Point Array S1950 Drift at E113 – Roof to Floor.....	4-129
4-223	Convergence Point Array S1950 Drift at E281 – Roof to Floor.....	4-130
4-224	Convergence Point Array S1950 Drift at E284 – Roof to Floor.....	4-130
4-225	Convergence Point Array S2180 Drift at E55 – All Chords.....	4-131
4-226	Convergence Point Array S2180 Drift at E220 – All Chords.....	4-131
4-227	Convergence Point Array S2180 Drift at W100 – All Chords.....	4-132
4-228	Convergence Point Array S2520 Drift at E55 – All Chords.....	4-132
4-229	Convergence Point Array S2520 Drift at E220 – All Chords.....	4-133
4-230	Convergence Point Array S2520 Drift at W100 – All Chords.....	4-133
4-231	Convergence Point Array S2750 Drift at E55 – All Chords.....	4-134
4-232	Convergence Point Array S2750 Drift at E220 – All Chords.....	4-134
4-233	Convergence Point Array S2750 Drift at W93 – All Chords.....	4-135
4-234	Convergence Point Array S3080 Drift at E55 – All Chords.....	4-135
4-235	Convergence Point Array S3080 Drift at E220 – All Chords.....	4-136
4-236	Convergence Point Array S3080 Drift at W100 – All Chords.....	4-136
4-237	Convergence Point Array S3310 Drift at E55 – All Chords.....	4-137
4-238	Convergence Point Array S3310 Drift at E220 – All Chords.....	4-137
4-239	Convergence Point Array S3310 Drift at W100 – All Chords.....	4-138
4-240	Joint Meters S1950 Drift at E300 Drift Overcast.....	4-138
4-241	Rock Bolt Load Cells E140 Drift at S1550.....	4-139
4-242	Rock Bolt Load Cells E140 Drift at S1775.....	4-139
4-243	Rock Bolt Load Cells E140 Drift at S2900.....	4-140

Waste Disposal Area Panel 1 Access Drifts

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
6-1	Convergence Point Array S1600 Drift at E311 – All Chords.....	6-4
6-2	Convergence Point Array S1600 Drift at E332 – All Chords.....	6-4
6-3	Convergence Point Array S1600 Drift at E357 – All Chords.....	6-5
6-4	Convergence Point Array S1600 Drift at E382 – All Chords.....	6-5
6-5	Convergence Point Array S1600 Drift at E407 – Roof to Floor.....	6-6
6-6	Convergence Point Array S1600 Drift at E432 – All Chords.....	6-6
6-7	Convergence Point Array S1600 Drift at E453 – All Chords.....	6-7
6-8	Convergence Point Array S1950 Drift at E311 – All Chords.....	6-7
6-9	Convergence Point Array S1950 Drift at E332 – All Chords.....	6-8
6-10	Convergence Point Array S1950 Drift at E357 – All Chords.....	6-8
6-11	Convergence Point Array S1950 Drift at E382 – All Chords.....	6-9
6-12	Convergence Point Array S1950 Drift at E407 – Roof to Floor.....	6-9
6-13	Convergence Point Array S1950 Drift at E407 – Rib to Rib.....	6-10
6-14	Convergence Point Array S1950 Drift at E432 – All Chords.....	6-10
6-15	Convergence Point Array S1950 Drift at E457 – All Chords.....	6-11
Waste Disposal Area Panel 2		
6-16	Extensometer 51X-GE-00341 Room 1, Panel 2 – Room Center – Roof.....	6-15
6-17	Extensometer 51X-GE-00342 Room 2, Panel 2 – Room Center – Roof.....	6-15
6-18	Extensometer 51X-GE-00343 Room 3, Panel 2 – Room Center – Roof.....	6-16
6-19	Extensometer 51X-GE-00344 Room 4, Panel 2 – Room Center – Roof.....	6-16
6-20	Extensometer 51X-GE-00345 Room 5, Panel 2 – Room Center – Roof .....	6-17
6-21	Extensometer 51X-GE-00346 Room 6, Panel 2 – Room Center – Roof.....	6-17
6-22	Extensometer 51X-GE-00347 Room 7, Panel 2 – Room Center – Roof.....	6-18
6-23	Extensometer 51X-GE-00348 S2180 Drift at E725 – Roof.....	6-18
6-24	Extensometer 51X-GE-00351 S2180 Drift at E1120 – Roof.....	6-19
6-25	Extensometer 51X-GE-00350 S2520 Drift at E735 – Roof.....	6-19
6-26	Extensometer 51X-GE-00349 S2520 Drift at E 1120– Roof.....	6-20
6-27	Convergence Point Array S2180 Drift at E410 – All Chords.....	6-20
6-28	Convergence Point Array S2180 Drift at E520 Drift Intersection (Room 1, Panel 2) – Roof to Floor.....	6-21
6-29	Convergence Point Array S2180 Drift at E586 – All Chords.....	6-21
6-30	Convergence Point Array S2180 Drift at E660 Drift Intersection (Room 2, Panel 2) – Roof to Floor.....	6-22
6-31	Convergence Point Array S2180 Drift at E790 Drift Intersection (Room 3, Panel 2) – Roof to Floor.....	6-22
6-32	Convergence Point Array S2180 Drift at E920 Drift Intersection (Room 4, Panel 2) – Roof to Floor.....	6-23
6-33	Convergence Point Array S2180 Drift at E986 – All Chords.....	6-23
6-34	Convergence Point Array S2180 Drift at E1050 Drift Intersection (Room 5, Panel 2) – Roof to Floor.....	6-24
6-35	Convergence Point Array S2520 Drift at E410 – All Chords.....	6-24

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
6-36	Convergence Point Array S2520 Drift at E520 Drift Intersection (Room 1, Panel 2) – Roof to Floor.....	6-25
6-37	Convergence Point Array S2520 Drift at E586 – All Chords.....	6-25
6-38	Convergence Point Array S2520 Drift at E660 Drift Intersection (Room 2, Panel 2) – Roof to Floor.....	6-26
6-39	Convergence Point Array S2520 Drift at E790 Drift Intersection (Room 3, Panel 2) – Roof to Floor.....	6-26
6-40	Convergence Point Array S2520 Drift at E920 Drift Intersection (Room 4, Panel 2) – Roof to Floor.....	6-27
6-41	Convergence Point Array S2520 Drift at E985 – All Chords.....	6-27
6-42	Convergence Point Array S2520 Drift at E1050 Drift Intersection (Room 5, Panel 2) – Roof to Floor.....	6-28
6-43	Convergence Point Array S2520 Drift at E1190 Drift Intersection (Room 6, Panel 2) – Roof to Floor.....	6-28
6-44	Convergence Point Array Room 1, Panel 2 at S2275 – All Chords.....	6-29
6-45	Convergence Point Array Room 1, Panel 2 at S2350 – Room Center – All Chords .....	6-29
6-46	Convergence Point Array Room 1, Panel 2 at S2425 – All Chords.....	6-30
6-47	Convergence Point Array Room 2, Panel 2 at S2275 – All Chords.....	6-30
6-48	Convergence Point Array Room 2, Panel 2 at S2350 – Room Center – All Chords .....	6-31
6-49	Convergence Point Array Room 2, Panel 2 at S2425 – All Chords.....	6-31
6-50	Convergence Point Array Room 3, Panel 2 at S2275 – All Chords.....	6-32
6-51	Convergence Point Array Room 3, Panel 2 at S2350 – Room Center – All Chords .....	6-32
6-52	Convergence Point Array Room 3, Panel 2 at S2425 – All Chords.....	6-33
6-53	Convergence Point Array Room 4, Panel 2 at S2275 – All Chords.....	6-33
6-54	Convergence Point Array Room 4, Panel 2 at S2350 – Room Center – All Chords .....	6-34
6-55	Convergence Point Array Room 4, Panel 2 at S2425 – All Chords.....	6-34
6-56	Convergence Point Array Room 5, Panel 2 at S2275 – All Chords.....	6-35
6-57	Convergence Point Array Room 5, Panel 2 at S2350 – Room Center – All Chords .....	6-35
6-58	Convergence Point Array Room 5, Panel 2 at S2425 – All Chords.....	6-36
6-59	Convergence Point Array Room 6, Panel 2 at S2350 – Room Center – All Chords .....	6-36
6-60	Convergence Point Array Room 6, Panel 2 at S2425 – All Chords.....	6-37

### Waste Disposal Area Panel 3

6-61	Extensometer 51X-GE-00354 Room 1, Panel 3 – Room Center – Roof.....	6-42
6-62	Extensometer 51X-GE-00354-2 Room 1, Panel 3 – Room Center – Roof.....	6-42
6-63	Extensometer 51X-GE-00358 Room 2, Panel 3 – Room Center – Roof.....	6-43
6-64	Extensometer 51X-GE-00359 Room 3, Panel 3 – Room Center – Roof.....	6-43
6-65	Extensometer 51X-GE-00360 Room 4, Panel 3 – Room Center – Roof.....	6-44
6-66	Extensometer 51X-GE-00362 Room 5, Panel 3 – Room Center – Roof .....	6-44
6-67	Extensometer 51X-GE-00363 Room 6, Panel 3 – Room Center – Roof.....	6-45
6-68	Extensometer 51X-GE-00366 Room 7, Panel 3 – Room Center – Roof.....	6-45
6-69	Rock Bolt Load Cells S2750 Drift at E950-E1050 – Roof.....	6-46
6-70	Convergence Point Array S2750 Drift at E410 – All Chords.....	6-46

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
6-71	Convergence Point Array S2750 Drift at E520 Drift Intersection (Room 1, Panel 3) – Roof to Floor.....	6-47
6-72	Convergence Point Array S2750 Drift at E586 – Roof to Floor.....	6-47
6-73	Convergence Point Array S2750 Drift at E660 Drift Intersection (Room 2, Panel 3) – Roof to Floor.....	6-48
6-74	Convergence Point Array S2750 Drift at E790 Drift Intersection (Room 3, Panel 3) – Roof to Floor.....	6-48
6-75	Convergence Point Array S2750 Drift at E920 Drift Intersection (Room 4, Panel 3) – Roof to Floor.....	6-49
6-76	Convergence Point Array S2750 Drift at E986 – Roof to Floor.....	6-49
6-77	Convergence Point Array S2750 Drift at E1050 Drift Intersection (Room 5, Panel 3) – Roof to Floor.....	6-50
6-78	Convergence Point Array S2750 Drift at E1190 Drift Intersection (Room 6, Panel 3) – Roof to Floor.....	6-50
6-79	Convergence Point Array S2750 Drift at E1255 – Roof to Floor.....	6-51
6-80	Convergence Point Array S2750 Drift at E1320 Drift Intersection (Room 7, Panel 3) – Roof to Floor.....	6-51
6-81	Convergence Point Array S3080 Drift at E410 – All Chords.....	6-52
6-82	Convergence Point Array S3080 Drift at E520 Drift Intersection (Room 1, Panel 3) – Roof to Floor.....	6-52
6-83	Convergence Point Array S3080 Drift at E586 – All Chords.....	6-53
6-84	Convergence Point Array S3080 Drift at E660 Drift Intersection (Room 2, Panel 3) – Roof to Floor.....	6-53
6-85	Convergence Point Array S3080 Drift at E790 Drift Intersection (Room 3, Panel 3) – Roof to Floor.....	6-54
6-86	Convergence Point Array S3080 Drift at E920 Drift Intersection (Room 4, Panel 3) – Roof to Fbor.....	6-54
6-87	Convergence Point Array S3080 Drift at E1050 Drift Intersection (Room 5, Panel 3) – Roof to Floor.....	6-55
6-88	Convergence Point Array S3080 Drift at E1190 Drift Intersection (Room 6, Panel 3) – Roof to Floor.....	6-55
6-89	Convergence Point Array S3080 Drift at E1255 – All Chords.....	6-56
6-90	Convergence Point Array S3080 Drift at E1320 Drift Intersection (Room 7, Panel 3) – Roof to Floor.....	6-56
6-91	Convergence Point Array Room 1, Panel 3 at S2833 – All Chords.....	6-57
6-92	Convergence Point Array Room 1, Panel 3 at S2916 – Room Center – All Chords .....	6-57
6-93	Convergence Point Array Room 1, Panel 3 at S2998 – All Chords.....	6-58
6-94	Convergence Point Array Room 2, Panel 3 at S2833 – Roof to Floor .....	6-58
6-95	Convergence Point Array Room 2, Panel 3 at S2916 – Room Center – All Chords .....	6-59
6-96	Convergence Point Array Room 2, Panel 3 at S2998 – All Chords.....	6-59
6-97	Convergence Point Array Room 3, Panel 3 at S2833 – All Chords.....	6-60
6-98	Convergence Point Array Room 3, Panel 3 at S2916 – Room Center – All Chords ....	6-60
6-99	Convergence Point Array Room 3, Panel 3 at S2998 – All Chords.....	6-61
6-100	Convergence Point Array Room 4, Panel 3 at S2833 – All Chords.....	6-61

## ***List of Figures (Continued)***

---

<b>Figure</b>	<b>Title</b>	<b>Page No.</b>
6-101	Convergence Point Array Room 4, Panel 3 at S2916 – Room Center – All Chords .....	6-62
6-102	Convergence Point Array Room 4, Panel 3 at S2998 – All Chords.....	6-62
6-103	Convergence Point Array Room 5, Panel 3 at S2833 – All Chords.....	6-63
6-104	Convergence Point Array Room 5, Panel 3 at S2916 – Room Center – All Chords .....	6-63
6-105	Convergence Point Array Room 5, Panel 3 at S2998 – All Chords.....	6-64
6-106	Convergence Point Array Room 6, Panel 3 at S2833 – All Chords.....	6-64
6-107	Convergence Point Array Room 6, Panel 3 at S2916 – Room Center – All Chords .....	6-65
6-108	Convergence Point Array Room 6, Panel 3 at S2998 – All Chords.....	6-65
6-109	Convergence Point Array Room 7, Panel 3 at S2833 – All Chords.....	6-66
6-110	Convergence Point Array Room 7, Panel 3 at S2916 – Room Center – All Chords .....	6-66
6-111	Convergence Point Array Room 7, Panel 3 at S2998 – All Chords.....	6-67

### Geosciences Program

7-1	Panel 2, Room 1, Roof Fractures .....	7-18
7-2	Panel 2, Room 2, Roof Fractures .....	7-19
7-3	Panel 2, Room 3, Roof Fractures .....	7-20
7-4	Panel 2, Room 4, Roof Fractures .....	7-21
7-5	Panel 2, South 2180, E500-E790, Roof Fractures.....	7-22
7-6	Panel 2, South 2180, E790-E1075, Roof Fractures.....	7-23
7-7	Panel 2, South 2520, E505-795, Roof Fractures.....	7-24
7-8	Panel 2, South 2520, E795-E1080, Roof Fractures.....	7-25
7-9	Panel 3, Room 1, Roof Fractures .....	7-26
7-10	Panel 3, Room 2, Roof Fractures .....	7-27
7-11	Panel 3, Room 3, Roof Fractures .....	7-28
7-12	Panel 3, Room 4, Roof Fractures .....	7-29
7-13	Panel 3, Room 5, Roof Fractures .....	7-30
7-14	Panel 3, Room 6, Roof Fractures .....	7-31
7-15	Panel 3, Room 7, Roof Fractures .....	7-32
7-16	Panel 3, South 2750, E500-E772, Roof Fractures.....	7-33
7-17	Panel 3, South 2750, E772-E1062, Roof Fractures.....	7-34
7-18	Panel 3, South 2750, E1062-E1335, Roof Fractures.....	7-35
7-19	Panel 3, South 3080, E500-E770, Roof Fractures.....	7-36
7-20	Panel 3, South 3080, E770-E1060, Roof Fractures.....	7-37
7-21	Panel 3, South 3080, E1060-E1335, Roof Fractures.....	7-38

## **1.0 Introduction**

---

This report is a compilation of geotechnical data presented as plots for each active instrument installed in the underground at the Waste Isolation Pilot Plant (WIPP) through June 30, 2004. A summary of the geotechnical analyses that were performed using the enclosed data is provided in Volume 1 of the Geotechnical Analysis Report (GAR).

### **1.1 Instrumentation**

Geomechanical data included in this report reflect the measurements of the geomechanical response from instruments installed in the underground and shafts. These instruments consist of convergence points, borehole extensometers, rockbolt load cells, pressure cells, strain gages, piezometers, and joint meters.

Closure measurements are taken at convergence points. Rock displacement is calculated by measuring the distance between two opposing points. Displacement is monitored over time and is plotted as closure versus time. Annual rates of closure are calculated for the convergence data and are compared with annual closure rates from previous reporting periods.

Borehole extensometers are used to determine the absolute movements of the ground around the openings. With these instruments, rods or wires are placed into a hole and anchored at various depths. The displacement at the extensometer head (located near the excavation face) is measured relative to each of the fixed anchors. These data are used in the extensometer *displacement* plots presented here. As part of the post-processing of acquired extensometer data a *relative displacement* value is calculated. The deepest anchor is assumed to be fixed in undisturbed ground and a displacement for the remaining anchors relative to the deepest anchor is calculated. Annual rates of collar displacement are calculated for each extensometer and are compared with the annual displacement rate reported during the previous reporting period.

Rockbolt load cells are used to determine the ground loading and the effectiveness of rockbolts. Plots consist of load versus time for each instrumented bolt.

Earth pressure cells and strain gages are used in and around the shaft liners to determine their loads. These are also depicted in time-based plots. Monitoring of these instruments indicates whether there is any stress buildup in the shaft lining systems.

Piezometers are used to measure the gage pressure of groundwater. They have been installed in the shafts at varying elevations to monitor the hydraulic head acting on the shaft liners. Plots from piezometers are presented as pressure versus time.

Joint meters are installed perpendicular to a crack and monitor any changes in separation of the crack which may occur over time.

## **1.2 Data Plot Explanation**

Data are presented in graphical form for ease in interpretation. Time-based plots are used in this report. Each plot generally consists of a legend in the upper right-hand corner that gives the array name and specific location of the instrument or point evaluated. The legend ties the graphical cross-sectional representation of the drift or shaft typically presented in the lower right-hand corner to the symbols on the curve in the graph. For extensometers, each anchor is designated with an alpha character “A” closest to the collar and “C,” “D,” or “E” for the furthest point from the collar (the deepest anchor). For convergence points, the horizontal and vertical sections of the drift are referred to as chords. Breaks in the graph for convergence data and a numeric designator added to the legend indicate that the convergence point was lost due to normal mine maintenance activities and later reinstalled.

## **1.3 Report Organization**

Chapter 1.0 provides an introduction to this Supporting Data volume of the GAR. Chapter 2.0 provides instrument data analysis for the Salt Handling Shaft, Waste Shaft, and Exhaust Shaft followed by data plots for the extensometers, piezometers, earth pressure cells, spot welded strain gages, and embedment strain gages installed in the shafts. Chapter 3.0 provides instrument data analysis for the Salt Handling Shaft Station and Waste Shaft Station, an instrument data summary only for the area immediately surrounding the Air Intake Shaft, and data plots for extensometers, convergence points, and rockbolt load cells for all three locations. Chapter 4.0 provides instrument data analysis for the access drifts followed by data plots for the extensometers, convergence points and joint meters. Chapter 5.0: the northeast and northwest sections of the former WIPP Experimental Areas are no longer accessible and readings have been discontinued. Instrumentation data for this area has been presented in previous Geotechnical Annual Reports. However, East 0, East 140, and East 300 from North 1100 to North 1400 drifts have been renovated and the area reopened. Accordingly instrumentation was reinstalled and the data are now presented in Chapter 4.0 (access drifts). Chapter 6.0 provides instrument data analysis for the Waste Disposal Area followed by data plots for the

extensometers, rock bolt load cells and convergence points.

Chapter 7.0 provides geologic data collected through the mapping of fractures and the observation displacements in vertical boreholes.

This Page Intentionally  
Left Blank

## ***2.0 Instrumentation Summary for Shafts***

---

Instrumentation data analysis for three of the four shafts at the WIPP follows. Table 2-1 presents data and analysis of the Salt Shaft. Plots of the instrument data are presented as Figures 2-1 through 2-13. Table 2-2 presents data and analysis of the Waste Shaft. Plots of the instrument data are presented as Figures 2-14 through 2-27. Table 2-3 presents data and analysis of the Exhaust Shaft. Plots of the instrument data are presented as Figures 2-28 through 2-39.

This Page Intentionally  
Left Blank

**Table 2-1**  
**Salt Handling Shaft Data Analysis**

**PIEZOMETERS**

Field Tag	Level feet	Figure Number	Date of 2003-2004 Max. Reading	2003-2004 Maximum Pressure Readings (psi)	Date of 2002-2003 Max. Reading	2002-2003 Maximum Pressure Readings (psi)	Change in Maximum Pressure From Previous Year (psi)	Comments
37X-PE-00201	580	2-1	06/14/04	86	06/10/03	74	12	
37X-PE-00202	580	2-1	06/14/04	91	06/10/03	79	12	
37X-PE-00203	620	2-2	06/14/04	163	06/10/03	90	73	
37X-PE-00204	620	2-2	06/14/04	152	06/10/03	121	32	
37X-PE-00205	691	2-3	06/14/04	171	06/10/03	149	22	
37X-PE-00206	691	2-3	06/14/04	164	05/21/03	145	20	
37X-PE-00207	726	2-4	12/01/03	143	05/21/03	142	1	
37X-PE-00209	802	2-5	07/01/03	106	06/10/03	105	1	
37X-PE-00210	802	2-5	07/01/03	106	06/10/03	105	1	
37X-PE-00211	850	2-6	06/14/04	124	05/21/03	114	11	
37X-PE-00212	850	2-6	06/14/04	132	05/21/03	112	20	

**EARTH PRESSURE CELLS**

Field Tag	Level feet	Figure Number	Date of 2003-2004 Max. Reading	2003-2004 Maximum Pressure Readings (psi)	Date of 2002-2003 Max. Reading	2002-2003 Maximum Pressure Readings (psi)	Change in Maximum Pressure From Previous Year (psi)	Comments
37X- WE-00201	860	2-7	08/26/03	-2.8	06/10/03	-7	4.2	
37X- WE-00202	860	2-7	07/01/03	-21.2	06/10/03	-21.1	-0.1	
37X- WE-00203	860	2-7	07/01/03	2	06/10/03	0.6	1.4	


**Table 2-1 (Continued)**  
**Salt Handling Shaft Data Analysis**

**SPOT WELDED STRAIN GAGES**


Field Tag	Level feet	Figure Number	Date of 2003-2004 Max. Reading	2003-2004 Maximum Total microstrain	Date of 2002-2003 Max. Reading	2002-2003 Maximum Total microstrain	Change in Maximum Strain From Previous Year	Comments
37X-ZE-00201	856.3	2-8	09/02/03	759	05/21/03	748	11	
37X-ZE-00206	856.3	2-8	06/14/04	670	06/11/03	652	18	
37X-ZE-00220	862.4	2-9	09/02/03	837	06/11/03	784	53	
37X-ZE-00223	862.4	2-9	06/14/04	565	05/22/03	507	58	

**EMBEDMENT STRAIN GAGES**


Field Tag	Level feet	Figure Number	Date of 2003-2004 Max. Reading	2003-2004 Maximum Total microstrain	Date of 2002-2003 Max. Reading	2002-2003 Maximum Total microstrain	Change in Maximum Strain From Previous Year	Comments
37X-ZE-00209	856.3	2-10	02/04/04	-544	06/10/03	-513	-31	
37X-ZE-00210	856.3	2-10	08/26/03	991	06/10/03	977	14	
37X-ZE-00211	856.3	2-10	08/26/03	332	06/10/03	318	14	
37X-ZE-00212	856.3	2-10	03/02/04	-802	06/10/03	-676	-126	
37X-ZE-00213	856.3	2-10	06/14/04	321	06/10/03	304	17	
37X-ZE-00214	856.3	2-10	03/02/04	-127	06/10/03	-40	-87	
37X-ZE-00215	856.3	2-10	08/26/03	82	06/10/03	70	12	
37X-ZE-00216	856.3	2-10	06/14/04	583	06/10/03	555	28	
37X-ZE-00225	862.4	2-11	08/26/03	183	06/10/03	161	22	
37X-ZE-00235	856.3	2-12	03/02/04	-418	06/10/03	-378	-40	
37X-ZE-00236	856.3	2-12	06/14/04	90	06/10/03	58	32	
37X-ZE-00237	856.3	2-12	06/14/04	78	06/10/03	52	26	
37X-ZE-00238	856.3	2-12	06/14/04	482	06/10/03	463	19	
37X-ZE-00239	862.4	2-13	08/26/03	320	06/10/03	297	23	




**Figure 2-1 Piezometers 37X-PE- 00201 and 37X-PE-00202  
Salt Handling Shaft – Level 580 at the Forty-niner Member**




**Figure 2-2 Piezometers 37X-PE-00203 and 37X-PE-00204  
Salt Handling Shaft – Level 620 at the Magenta Dolomite Member**




**Figure 2-3 Piezometers 37X-PE-00205 and 37X-PE-00206  
Salt Handling Shaft – Level 691 at the Tamarisk Member**




**Figure 2-4 Piezometer 37X-PE-00207  
Salt Handling Shaft – Level 726 at the Culebra Dolomite Member**




**Figure 2-5 Piezometers 37X-PE-00209 and 37X-PE-00210  
Salt Handling Shaft – Level 802 at the Unnamed Lower Member**




**Figure 2-6 Piezometers 37X-PE-00211 and 37X-PE-00212  
Salt Handling Shaft – Level 850 at the Rustler-Salado Contact**




**Figure 2-7 Earth Pressure Cells Behind Shaft Key  
Salt Handling Shaft Key – Level 860**



**Figure 2-8 Spot Welded Strain Gages  
Salt Handling Shaft Key – Level 856.3**



**Figure 2-9 Spot Welded Strain Gages  
Salt Handling Shaft Key – Level 862.4**



**Figure 2-10 Embedment Strain Gages  
Salt Handling Shaft Key – Level 856.3**




Figure 2-11 Embedment Strain Gages  
Salt Handling Shaft Key Level 862.4





Figure 2-12 Embedment Strain Gages  
Salt Handling Shaft Key Level 856.3



**Figure 2-13 Embedment Strain Gages  
Salt Handling Shaft Key – Level 862.4**

This Page Intentionally  
Left Blank

**Table 2-2**  
**Waste Shaft Data Analysis**

**EXTENSOMETERS**

Field Tag	Location	Level feet	Figure Number	Date of Last Reading	Collar Displacement Relative to Deepest Anchor ( inches)	Displacement Rate 2002 to 2003 in/year	Displacement Rate 2001 to 2002 in/year	Rate Change Percent <sup>A</sup>	Comments
31X-GE-00203	WASTE SHAFT	1071	2-14	04/28/03	0.207	0.003	0.002	50%	Not read this reporting period.
31X-GE-00204	WASTE SHAFT	1566	2-15	04/28/03	0.781	0.019	0.018	6%	Not read this reporting period.
31X-GE-00205	WASTE SHAFT	1566	2-16	04/28/03	0.661	0.016	0.016	0%	Not read this reporting period.
31X-GE-00206	WASTE SHAFT	1566	2-17	04/28/03	0.791	0.021	0.021	0%	Not read this reporting period.
31X-GE-00207	WASTE SHAFT	2059	2-18	07/10/02	1.945	N/A	0.060	N/A	Not read this reporting period.
31X-GE-00208	WASTE SHAFT	2059	2-19	04/28/03	1.860	0.055	0.047	17%	Not read this reporting period.
31X-GE-00209	WASTE SHAFT	2059	2-20	04/28/03	2.115	0.072	0.067	7%	Not read this reporting period.

<sup>A</sup> N/A indicates insufficient data to compare annualized rates.

**PIEZOMETERS**

Field Tag	Level feet	Figure Number	Date of 2002-2003 Max. Reading	2002-2003 Maximum Pressure Readings (psi)	Date of 2001-2002 Max. Reading	2001-2002 Maximum Pressure Readings (psi)	Change in Maximum Pressure From Previous Year (psi)	Comments
31X-PE-00201	532	2-21	04/28/03	0	03/04/02	-3	3	Not read this reporting period.
31X-PE-00202	532	2-21	07/10/02	-4	10/01/01	-4	-1	Not read this reporting period.
31X-PE-00203	611	2-22	07/03/02	39	09/04/01	42	-3	Not read this reporting period.
31X-PE-00204	611	2-22	07/03/02	34	08/09/01	33	1	Not read this reporting period.
31X-PE-00205	669	2-23	07/10/02	-1	03/04/02	0	-1	Not read this reporting period.
31X-PE-00206	669	2-23	07/10/02	-1	06/05/02	-1	0	Not read this reporting period.
31X-PE-00208	717	2-24	07/03/02	144	08/09/01	146	-2	Not read this reporting period.
31X-PE-00209	758	2-25	07/10/02	43	06/05/02	43	1	Not read this reporting period.
31X-PE-00210 <sup>B</sup>	758	2-25	04/28/03	-1	05/03/02	0	-1	Not read this reporting period.
31X-PE-00211	845	2-26	07/10/02	75	10/01/01	79	-4	Not read this reporting period.
31X-PE-00212	845	2-26	07/10/02	80	06/05/02	76	5	Not read this reporting period.

<sup>B</sup> Probable Instrument Failure.

**Table 2-2 (Continued)**  
**Waste Shaft Data Analysis**

**EARTH PRESSURE CELLS**

Field Tag	Level feet	Figure Number	Date of 2002-2003 Max. Reading	2002-2003 Maximum Pressure Readings (psi)	Date of 2001-2002 Max. Reading	2001-2002 Maximum Pressure Readings (psi)	Change in Maximum Pressure From Previous Year (psi)	Comments
31X- WE-00201	866	2-27	07/10/02	74.0	11/06/01	77.5	-3.5	Not read this reporting period.
31X- WE-00202	866	2-27	07/10/02	80.9	09/04/01	88.4	-7.5	Not read this reporting period.
31X- WE-00203	866	2-27	07/03/02	100.1	08/09/01	102.9	-2.8	Not read this reporting period.
31X- WE-00204	866	2-27	07/03/02	101.0	08/09/01	104.2	-3.2	Not read this reporting period.




Figure 2-14 Extensometer 31X-GE-00203  
Waste Shaft – Level 1071 / S15W




Figure 2-15 Extensometer 31X-GE-00204  
Waste Shaft – Level 1566 / N45W




Figure 2-16 Extensometer 31X-GE-00205  
Waste Shaft – Level 1566 / N75E




Figure 2-17 Extensometer 31X-GE-00206  
Waste Shaft – Level 1566 / S15W




Figure 2-18 Extensometer 31X-GE-00207  
Waste Shaft – Level 2059 / N45W




Figure 2-19 Extensometer 31X-GE-00208  
Waste Shaft – Level 2059 / N75E




Figure 2-20 Extensometer 31X-GE-00209  
Waste Shaft – Level 2059 / S15W




Figure 2-21 Piezometers 31X-PE-00201 and 31X-PE-00202  
Waste Shaft – Level 532 at the Base of Dewey Lake Redbeds




Figure 2-22 Piezometers 31X-PE-00203 and 31X-PE-00204  
Waste Shaft – Level 611 at the Magenta Dolomite Member






Figure 2-23 Piezometers 31X-PE-00205 and 31X-PE-00206  
Waste Shaft – Level 669 at the Tamarisk Member



**Figure 2-24 Piezometers 31X-PE-00208  
Waste Shaft – Level 717 at the Culebra Dolomite Member**



**Figure 2-25 Piezometers 31X-PE-00209 and 31X-PE-00210  
Waste Shaft – Level 758 at the Los Medaños Member**




Figure 2-26 Piezometers 31X-PE-00211 and 31X-PE-00212  
Waste Shaft – Level 845 at the Rustler-Salado Contact




Figure 2-27 Earth Pressure Cells  
Waste Shaft Key – Level 866

This Page Intentionally  
Left Blank

**Table 2-3**  
**Exhaust Shaft Data Analysis**

**EXTENSOMETERS**

Field Tag	Location	Level feet	Figure Number	Date of Last Reading	Collar Displacement Relative to Deepest Anchor ( inches)	Displacement Rate 2003 to 2004 in/year	Displacement Rate 2002 to 2003 in/year	Rate Change Percent	Comments
35X-GE-00204	EXHAUST SHAFT	1573	2-28	06/01/04	0.378	0.013	0.016	-19%	
35X-GE-00205	EXHAUST SHAFT	1573	2-29	06/01/04	0.396	0.015	0.017	-12%	
35X-GE-00206	EXHAUST SHAFT	1573	2-30	06/01/04	0.409	0.015	0.019	-21%	
35X-GE-00207	EXHAUST SHAFT	2066	2-31	06/01/04	1.831	0.073	0.072	1%	


**PIEZOMETERS**

Field Tag	Level feet	Figure Number	Date of 2003-2004 Max. Reading	2003-2004 Maximum Pressure Readings (psi)	Date of 2002-2003 Max. Reading	2002-2003 Maximum Pressure Readings (psi)	Change in Maximum Pressure From Previous Year (psi)	Comments
35X-PE-00202	544	2-32	09/02/03	-2	09/04/02	-2	0	
35X-PE-00204	615	2-33	09/02/03	125	09/04/02	126	-1	
35X-PE-00205	615	2-33	09/02/03	136	09/04/02	137	-1	
35X-PE-00208	673	2-34	10/01/03	6	09/04/02	6	0	
35X-PE-00210	721	2-35	08/04/03	141	09/04/02	141	0	
35X-PE-00213	768	2-36	10/01/03	10	09/04/02	11	-1	
35X-PE-00214	768	2-36	09/02/03	7	09/04/02	9	-2	
35X-PE-00216	850	2-37	10/01/03	89	10/02/02	91	-2	
35X-PE-00218	850	2-37	10/01/03	16	08/05/02	15	1	
35X-PE-00219	887	2-38	10/01/03	28	10/02/02	27	2	
35X-PE-00220	887	2-38	10/01/03	27	10/02/02	27	0	


**Table 2-3 (Continued)**  
**Exhaust Shaft Data Analysis**

**EARTH PRESSURE CELLS**


Field Tag	Level feet	Figure Number	Date of 2003-2004 Max. Reading	2003-2004 Maximum Pressure Readings (psi)	Date of 2002-2003 Max. Reading	2002-2003 Maximum Pressure Readings (psi)	Change in Maximum Pressure From Previous Year (psi)	Comments
35X-WE-00201	874	2-39	11/03/03	44.3	12/02/02	43.6	0.7	
35X-WE-00202	874	2-39	08/04/03	55.1	06/02/03	53.2	1.9	




**Figure 2-28 Extensometer 35X-GE-00204  
 Exhaust Shaft – Level 1573 / N75E**




**Figure 2-29 Extensometer 35X-GE-00205  
 Exhaust Shaft – Level 1573 / N45W**




**Figure 2-30 Extensometer 35X-GE-00206**  
**Exhaust Shaft – Level 1573 / S15W**



**Figure 2-31 Extensometer 35X-GE-00207**  
**Exhaust Shaft – Level 2066 / N75E**



**Figure 2-32 Piezometer 35X-PE-00202  
Exhaust Shaft – Level 544 at the Base of Dewey Lake Redbeds**



**Figure 2-33 Piezometers 35X-PE-00204 and 35X-PE-00205  
Exhaust Shaft – Level 615 at the Magenta Dolomite Member**




Figure 2-34 Piezometers 35X-PE-00208  
Exhaust Shaft – Level 673 at the Tamarisk Member







Figure 2-35 Piezometers 35X-PE-00210  
Exhaust Shaft – Level 721 at the Culebra Dolomite Member




**Figure 2-36 Piezometers 35X-PE-00213 and 35X-PE-00214  
Exhaust Shaft – Level 768 at the Los Medaños Member**



**Figure 2-37 Piezometers 35X-PE-00216 and 35X-PE-00218  
Exhaust Shaft – Level 850 at the Rustler-Salado Contact**



**Figure 2-38 Piezometers 35X-PE-00219 and 35X-PE-00220  
Exhaust Shaft – Level 887 below the Lower Chemical Seal**



**Figure 2-39 Earth Pressure Cells 35X-WE-00201 and 35X-WE-00202  
Exhaust Shaft Key – Level 874**

### ***3.0 Instrumentation Summary for Shaft Stations***

---


Instrumentation data analysis for the Salt Handling Shaft Station, Waste Shaft Station, and the area around the Air Intake Shaft follow. Table 3-1 presents data analyses for each of the Salt Handling Shaft Station instruments. Figures 3-1 through 3-4 present plots of the instrumentation data for the Salt Handling Shaft Station. Tables 3-2 presents data and analysis for the Waste Shaft Station. Plots from the instrumentation in the Waste Shaft Station are presented as Figures 3-5 through 3-13. Table 3-3 and Figures 3-14 through 3-17 present the data from rock bolt load cells located in the immediate area around the Air Intake Shaft.

This Page Intentionally  
Left Blank


**Table 3-1**  
**Salt Handling Shaft Station Data Analysis**

**CONVERGENCE POINTS**


Field Tag	Location	Figure Number	Last Reading		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
			Date	Inches					
E0-W12-5 A-C	Salt Shaft-W12	3-1	06/03/04	4.646	17.815	0.728	0.832	-12%	
E0-S18-6 A-E	E0 Drift-S18	3-2	06/03/04	8.679	26.235	1.391	1.573	-12%	
E0-S18-4 B-D	E0 Drift-S18	3-2	06/03/04	9.367	26.425	1.498	1.831	-18%	
E0-S18-4 F-H	E0 Drift-S18	3-2	06/03/04	5.933	16.789	0.96	1.103	-13%	
E0-S30-5 A-C	E0 Drift-S30	3-3	06/03/04	9.096	40.703	1.472	1.652	-11%	
E0-S65-3 A-C	E0 Drift-S65	3-4	06/03/04	6.763	37.114	1.076	1.235	-13%	




**Figure 3-1 Convergence Point Array  
Salt Handling Shaft Station 12 Feet West of Shaft – Roof to Floor**



**Figure 3-2 Convergence Point Array  
Salt Handling Shaft Station at South 18 – All Chords**



**Figure 3-3 Convergence Point Array  
Salt Handling Shaft Station at South 30 – All Chords**



**Figure 3-4 Convergence Point Array  
Salt Handling Shaft Station at South 65 – Roof to Floor**

This Page Intentionally  
Left Blank

**Table 3-2**  
**Waste Shaft Station Data Analysis**

**EXTENSOMETERS**

Field Tag	Location	Figure Number	Date of Last Reading	Collar Displacement Relative to Deepest Anchor ( inches)	Displacement Rate 2003 to 2004 in/year	Displacement Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
51X-GE-00268	W30 Drift-S400 Roof	3-5	06/30/04	8.517	0.652	0.254	N/A	Insufficient data.
51X-GE-00356	Waste Shaft Brow Brow	3-6	06/28/04	0.029	0.047	N/A	N/A	New installation.
51X-GE-00357	Waste Shaft Brow Brow	3-7	06/28/04	0.080	0.130	N/A	N/A	New installation.
51X-GE-01025	S400 Drift-E87 Roof	3-8	06/29/04	0.237	0.528	N/A	N/A	New installation.
51X-GE-00279	S400 Drift-E140 Roof	3-9	05/17/04	11.702	-0.060	0.662	N/A	Transducer malfunction.

<sup>A</sup> N/A indicates insufficient data to compare annualized rates.


**CONVERGENCE POINTS**

Field Tag	Location	Figure Number	Last Reading		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
			Date	Inches					
S400-E30-2 C-H	S400 Drift-E30	3-10	06/16/04	16.654	16.727	0.838	0.856	-2%	
S400-E90-2 C-G	S400 Drift-E90	3-11	06/16/04	18.935	19.126	0.968	0.958	1%	


**Table 3-2 (Continued)**  
**Waste Shaft Station Data Analysis**

**ROCKBOLT LOAD CELLS**

Field Tag	Location	Figure Number	Date of Initial Reading	Date of Last Reading	Load (kips)	Comments
51X WG-00226	Waste Shaft Station Brow	3-12	07/15/92	06/28/04	15.450	
51X WG-00227	Waste Shaft Station Brow	3-12	07/15/92	06/28/04	38.250	
51X WG-00228	Waste Shaft Station Brow	3-12	03/20/96	06/28/04	44.250	
51X WG-00229	Waste Shaft Station Brow	3-12	03/20/96	06/28/04	40.700	
51X WG-00230	Waste Shaft Station Brow	3-12	03/20/96	06/28/04	53.500	
51X WG-00231	Waste Shaft Station Brow	3-13	03/20/96	06/28/04	1.350	Broken bolt.
51X WG-00232	Waste Shaft Station Brow	3-13	07/15/92	06/28/04	49.450	
51X WG-00233	Waste Shaft Station Brow	3-13	07/15/92	06/28/04	1.750	
51X WG-00234	Waste Shaft Station Brow	3-13	07/15/92	06/28/04	64.200	
51X WG-00235	Waste Shaft Station Brow	3-13	03/20/96	06/28/04	40.350	



**Figure 3-5 Extensometer 51X-GE-00268**  
**Waste Shaft Station at West 30 – Roof**



**Figure 3-6 Extensometer 51X-GE-00356**  
**Waste Shaft Station Brow – North**




Figure 3-7 Extensometer 51X-GE-00357  
Waste Shaft Station Brow – South




Figure 3-8 Extensometer 51X-GE-01025  
Waste Shaft Station at East 87 – Roof




Figure 3-9 Extensometer 51X-GE-00279  
Waste Shaft Station at East 140 – Roof




Figure 3-10 Convergence Point Array  
Waste Shaft Station at East 30 – All Chords




Figure 3-11 Convergence Point Array  
Waste Shaft Station at East 90 – All Chords




Figure 3-12 Rock Bolt Load Cells  
Waste Shaft Station Brow – Roof Bolts Set 1





Figure 3-13 Rock Bolt Load Cells  
Waste Shaft Station Brow – Roof Bolts Set 2

This Page Intentionally  
Left Blank


**Table 3-3**  
**Air Intake Shaft Station Data Analysis**

**ROCKBOLT LOAD CELLS**


Field Tag	Location	Figure Number	Date of Initial Reading	Date of Last Reading	Load (kips)	Comments
51X-WG-00236	AIS Station Brow - South	3-14	01/19/93	06/29/04	47.200	
51X-WG-00237	AIS Station Brow - South	3-14	01/19/93	06/29/04	16.650	
51X-WG-00238	AIS Station Brow - South	3-14	01/19/93	06/29/04	6.100	
51X-WG-00239	AIS Station Brow - South	3-14	01/19/93	06/29/04	0.600	Broken bolt.
51X-WG-00240	AIS Station Brow - South	3-14	01/19/93	06/29/04	13.050	
51X-WG-00241	AIS Station Brow - South	3-15	01/19/93	06/29/04	39.650	
51X-WG-00242	AIS Station Brow - South	3-15	01/19/93	06/29/04	52.500	
51X-WG-00243	AIS Station Brow - South	3-15	01/19/93	06/29/04	48.250	
51X-WG-00244	AIS Station Brow - South	3-15	12/24/94	06/29/04	0.550	Broken bolt.
51X-WG-00245	AIS Station Brow - South	3-15	01/19/93	06/29/04	47.350	
51X-WG-00246	AIS Station Brow - North	3-16	01/19/93	06/29/04	25.950	
51X-WG-00247	AIS Station Brow - North	3-16	01/19/93	06/29/04	46.400	
51X-WG-00248	AIS Station Brow - North	3-16	01/19/93	06/29/04	40.350	
51X-WG-00249	AIS Station Brow - North	3-16	01/19/93	06/29/04	6.600	
51X-WG-00250	AIS Station Brow - North	3-16	12/24/94	06/29/04	18.000	
51X-WG-00251	AIS Station Brow - North	3-17	01/19/93	06/29/04	32.850	
51X-WG-00252	AIS Station Brow - North	3-17	01/19/93	06/29/04	3.050	
51X-WG-00253	AIS Station Brow - North	3-17	01/19/93	06/29/04	52.400	
51X-WG-00254	AIS Station Brow - North	3-17	01/19/93	06/29/04	13.250	
51X-WG-00255	AIS Station Brow - North	3-17	01/19/93	06/29/04	16.450	




**Figure 3-14 Rock Bolt Load Cells  
Air Intake Shaft Station Brow – South Side Roof Bolts Set 1**



**Figure 3-15 Rock Bolt Load Cells  
Air Intake Shaft Station Brow – South Side Roof Bolts Set 2**



**Figure 3-16 Rock Bolt Load Cells  
Air Intake Shaft Station Brow – North Side Roof Bolts Set 1**



**Figure 3-17 Rock Bolt Load Cells  
Air Intake Shaft Station Brow – North Side Roof Bolts Set 2**

This Page Intentionally  
Left Blank

## ***4.0 Instrumentation Summary for the Access Drifts***

---

This chapter presents the instrumentation data and data analyses for the access drifts throughout the WIPP underground. Table 4-1 provides the results of analyses performed on the instrument data including displacement, convergence rates, and rock bolt loading. Figures 4-1 through 4-47 present data from borehole extensometers installed in the access drifts while Figures 4-48 through 4-239 present the convergence point data. Figure 4-240 presents data from joint meters installed in the S1950/E300 overcast. Figures 4-241 through 4-243 presents the data from rock bolt load cells installed at E140/S1550, E140/S1775, and E140/S2900.

This Page Intentionally  
Left Blank

**Table 4-1**  
**Access Drifts Data Analysis**

**EXTENSOMETERS**

Field Tag	Location	Figure Number	Date of Last Reading	Collar Displacement Relative to Deepest Anchor (inches)	Displacement Rate 2003 to 2004 in/year	Displacement Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
51X-GE-00265	S700 DRIFT-E220	Roof	4-1	05/10/04	11.374	0.540	0.532	2%
51X-GE-00364	E140 DRIFT-N1266	Roof	4-2	06/29/04	0.221	0.574	N/A	N/A
51X-GE-00365	E140 DRIFT-N940	Roof	4-3	06/03/04	0.186	0.678	N/A	New installation.
41X-GE-00106	E140 DRIFT-N250	Roof	4-4	12/10/03	3.015	0.137	0.298	-54%
51X-GE-00105-3	E140 DRIFT-N150-3	Roof	4-5	06/03/04	0.897	0.277	0.153	81%
51X-GE-00276	E140 DRIFT-S700	Roof	4-6	06/29/04	8.879	0.547	0.526	4%
51X-GE-00474	S1000 DRIFT-E120	Roof	4-7	06/14/04	0.742	0.064	0.075	-15%
51X-GE-00472	E140 DRIFT-S1000	Roof	4-8	05/18/04	3.191	0.147	0.249	-41%
51X-GE-00473	S1000 DRIFT-E160	Roof	4-9	06/29/04	0.620	0.039	0.035	11%
51X-GE-00464	E140 DRIFT-S1025	Roof	4-10	05/18/04	3.337	0.128	0.235	-46%
51X-GE-00333	E140 DRIFT-S1075	Roof	4-11	06/14/04	2.843	0.445	0.436	2%
51X-GE-00460-2	E140 DRIFT-S1150	Roof	4-12	05/18/04	0.767	0.429	0.503	-15%
41X-GE-00103	E140 DRIFT-S1150	Roof	4-13	06/14/04	3.955	0.769	0.676	14%
51X-GE-00461	E140 DRIFT-S1225	Roof	4-14	05/18/04	2.059	0.245	0.273	-10%
51X-GE-00334	E140 DRIFT-S1225	Roof	4-15	06/14/04	3.044	0.503	0.491	2%
51X-GE-00462	S1300 DRIFT-E120	Roof	4-16	06/14/04	0.398	0.036	0.036	0%
51X-GE-00465	E140DRIFT-S1300	Roof	4-17	05/18/04	1.410	0.099	0.138	-28%
51X-GE-00335	E140 DRIFT-S1300	Roof	4-18	06/07/04	2.175	0.289	0.330	-12%
51X-GE-00463	S1300 DRIFT-E160	Roof	4-19	06/14/04	2.072	0.288	0.231	25%
51X-GE-00336	E140 DRIFT-S1375	Roof	4-20	06/14/04	4.404	0.757	0.439	72%
41X-GE-00102-2	E140 DRIFT-S1450	Roof	4-21	06/14/04	3.869	1.634	1.478	11%
51X-GE-00411	E140 DRIFT-S1525	Roof	4-22	10/14/03	10.476	N/A	N/A	Installation damaged.
51X-GE-00442	S1600 DRIFT-E120	Roof	4-23	06/14/04	0.601	0.054	0.055	-2%
51X-GE-00446	E140 DRIFT-S1600	Roof	4-24	05/18/04	1.880	0.154	0.189	-19%
51X-GE-00338-2	E140 DRIFT-S1600	Roof	4-25	06/14/04	1.980	1.892	-0.009	-21122% Instrument malfunction.

<sup>A</sup> NA indicates insufficient data to compare annualized rates.

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**EXTENSOMETERS (Continued)**

Field Tag	Location	Figure Number	Date of Last Reading	Collar Displacement Relative to Deepest Anchor (inches)	Displacement Rate 2003 to 2004 in/year	Displacement Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
51X-GE-00441	S1600 DRIFT-E160	Roof	4-26	06/14/04	1.590	0.107	0.183	-42%
51X-GE-00443	E140 DRIFT-S1685	Roof	4-27	03/17/04	2.644	0.109	0.274	-60%
51X-GE-00339-2	E140 DRIFT-S1685	Roof	4-28	06/14/04	2.625	1.145	1.009	13%
51X-GE-00492	E140 DRIFT-S2750	Roof	4-29	04/20/04	0.586	0.379	0.817	-54%
51X-GE-00367	E140 DRIFT-S2916	Roof	4-30	06/28/04	0.480	3.824	N/A	N/A
51X-GE-00493	E140 DRIFT-S2916	Roof	4-31	04/20/04	4.296	4.075	3.052	34%
51X-GE-00361	E0 DRIFT-N1266	Roof	4-32	06/29/04	0.424	1.034	N/A	N/A
51X-GE-00352	E0 DRIFT-N940	Roof	4-33	06/16/04	0.558	0.429	0.947	-55%
51X-GE-00353	E0 DRIFT-N626	Roof	4-34	06/16/04	0.586	0.424	1.001	-58%
51X-GE-00355	E0 DRIFT-N300	Roof	4-35	06/16/04	1.395	0.403	0.464	-13%
51X-GE-00481	N300 DRIFT-W10	Roof	4-36	06/24/04	0.887	0.384	0.278	38%
41X-GE-00127	N300 DRIFT-W110	Roof	4-37	06/29/04	4.977	0.580	0.709	-18%
41X-GE-00126	N300 DRIFT-W212	Roof	4-38	06/29/04	5.865	0.695	0.862	-19%
41X-GE-00125	N215 DRIFT-W417	Roof	4-39	06/29/04	3.432	0.392	0.591	-34%
41X-GE-00124	N215 DRIFT-W519	Roof	4-40	06/29/04	3.338	0.386	0.591	-35%
41X-GE-00123	W620 DRIFT-N93	Roof	4-41	06/29/04	2.802	0.365	0.303	20%
41X-GE-00122	W620 DRIFT-S65	Roof	4-42	06/29/04	2.152	0.292	0.211	38%
51X-GE-00494	E300 DRIFT-S2892	Roof	4-43	06/23/04	0.935	0.682	0.848	-20%
51X-GE-00490	W30 DRIFT-S2750	Roof	4-44	06/23/04	0.367	0.317	0.691	-54%
51X-GE-00491	W30 DRIFT-S2916	Roof	4-45	06/23/04	0.967	0.811	0.578	40%
51X-GE-00489	W30 DRIFT-S3080	Roof	4-46	06/23/04	2.137	1.331	2.561	-48%
51X-GE-00495	W170 DRIFT-S2634	Roof	4-47	06/23/04	0.992	0.788	0.722	9%

<sup>A</sup> NA indicates insufficient data to compare annualized rates.

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
E300-N250-2 A-C	E300 DRIFT-N250	4-48	05/17/04	11.616	25.969	1.698	1.880	-10%	
E300-N170 A-E	E300 DRIFT-N170	4-49	05/17/04	19.196	19.196	1.350	1.479	-9%	
E300-N170 H-F	E300 DRIFT-N170	4-49	05/17/04	17.011	17.011	1.210	1.351	-10%	
E300-N170-2 C-G	E300 DRIFT-N170	4-49	05/17/04	0.097	14.990	N/A	1.115	N/A	Reinstalled 4/04.
E300-N45 A-E	E300 DRIFT-N45	4-50	05/17/04	19.829	19.829	1.456	1.551	-6%	
E300-N45 H-F	E300 DRIFT-N45	4-50	05/17/04	16.825	16.825	1.455	1.533	-5%	
E300-N45 C-G	E300 DRIFT-N45	4-50	05/17/04	14.407	14.407	1.019	1.133	-10%	
E300-S45-2 A-E	E300 DRIFT-S45	4-51	05/17/04	16.053	16.053	1.085	1.241	-13%	
E300-S45-2 B-D	E300 DRIFT-S45	4-51	05/17/04	12.865	12.865	0.868	0.976	-11%	
E300-S45-2 H-F	E300 DRIFT-S45	4-51	05/17/04	13.827	13.827	0.974	1.153	-16%	
E300-S45 C-G	E300 DRIFT-S45	4-51	05/17/04	12.624	12.624	0.782	0.930	-16%	
E300-S90 A-C	E300 DRIFT-S90	4-52	06/01/04	12.719	12.719	0.681	0.729	-7%	
E300-S250-2 A-C	E300 DRIFT-S250	4-53	06/01/04	4.117	8.527	0.582	0.643	-9%	
E300-S250-2 B-D	E300 DRIFT-S250	4-53	06/01/04	4.544	8.617	0.596	0.642	-7%	
E300-S700 A-C	E300 DRIFT-S700	4-54	06/01/04	15.701	15.701	0.575	0.626	-8%	
E300-S850 A-E	E300 DRIFT-S850	4-55	06/01/04	12.099	12.099	0.415	0.471	-12%	
E300-S850 B-D	E300 DRIFT-S850	4-55	06/01/04	9.041	9.041	0.314	0.369	-15%	
E300-S850 H-F	E300 DRIFT-S850	4-55	06/01/04	8.288	8.288	0.321	0.346	-7%	
E300-S850-2 C-G	E300 DRIFT-S850	4-55	06/01/04	4.142	13.420	0.491	0.517	-5%	
E300-S1000 A-C	E300 DRIFT-S1000	4-56	06/01/04	15.691	15.691	0.533	0.539	-1%	
E300-S1150-3 A-E	E300 DRIFT-S1150	4-57	06/01/04	7.943	13.433	0.524	0.558	-6%	
E300-S1150-3 B-D	E300 DRIFT-S1150	4-57	06/01/04	5.529	9.588	0.381	0.398	-4%	
E300-S1150-3 H-F	E300 DRIFT-S1150	4-57	06/01/04	5.509	9.129	0.365	0.408	-11%	
E300-S1150-2 C-G	E300 DRIFT-S1150	4-58	06/01/04	4.875	15.331	0.597	0.575	4%	
E300-S1300 A-C	E300 DRIFT-S1300	4-59	06/01/04	8.950	8.950	0.669	0.700	-4%	

<sup>A</sup> NA indicates insufficient data to compare annualized rates.

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
			Date	Inches					
E300-S1450 A-C	E300 DRIFT-S1450	4-60	06/01/04	4.556	4.556	0.664	0.684	-3%	
E300-S1450 B-D	E300 DRIFT-S1450	4-60	06/01/04	5.100	5.100	0.744	0.737	1%	
E300-S1687 A-C	E300 DRIFT-S1687	4-61	06/01/04	4.539	4.539	0.732	0.727	1%	
E300-S1687 B-D	E300 DRIFT-S1687	4-61	06/01/04	5.019	5.019	0.806	0.793	2%	
E300-S1775 A-C	E300 DRIFT-S1775	4-62	06/01/04	4.297	4.297	0.719	0.657	9%	
E300-S1775 B-D	E300 DRIFT-S1775	4-62	06/01/04	5.082	5.082	0.802	0.788	2%	
E300-S1862 A-C	E300 DRIFT-S1862	4-63	06/01/04	4.479	4.479	0.776	0.751	3%	
E300-S1862 B-D	E300 DRIFT-S1862	4-63	06/01/04	5.405	5.405	0.878	0.886	-1%	
E300-S2065 A-C	E300 DRIFT-S2065	4-64	06/01/04	5.233	5.233	0.848	0.839	1%	
E300-S2065 B-D	E300 DRIFT-S2065	4-64	06/01/04	6.751	6.751	1.125	1.097	3%	
E300-S2275 A-C	E300 DRIFT-S2275	4-65	06/01/04	6.095	6.095	1.236	1.200	3%	
E300-S2275 B-D	E300 DRIFT-S2275	4-65	06/01/04	7.411	7.411	1.622	1.503	8%	
E300-S2350 A-C	E300 DRIFT-S2350	4-66	06/01/04	7.120	7.120	1.440	1.404	3%	
E300-S2350 B-D	E300 DRIFT-S2350	4-66	06/01/04	7.811	7.811	1.680	1.570	7%	
E300-S2425 A-C	E300 DRIFT-S2425	4-67	06/01/04	7.172	7.172	1.500	1.403	7%	
E300-S2425 B-D	E300 DRIFT-S2425	4-67	06/01/04	7.952	7.952	1.720	1.589	8%	
E300-S2634 A-C	E300 DRIFT-S2634	4-68	05/17/04	2.672	2.672	1.936	2.229	-13%	
E300-S2634 B-D	E300 DRIFT-S2634	4-68	05/17/04	2.803	2.803	2.008	2.484	-19%	
E300-S2833 A-C	E300 DRIFT-S2833	4-69	05/17/04	3.053	3.053	2.091	2.857	-27%	
E300-S2833 B-D	E300 DRIFT-S2833	4-69	05/17/04	3.140	3.140	2.070	2.844	-27%	
E300-S2916 A-C	E300 DRIFT-S2916	4-70	05/17/04	4.323	4.323	3.085	3.882	-21%	
E300-S2916 B-D	E300 DRIFT-S2916	4-70	05/17/04	3.345	3.345	2.251	3.206	-30%	
E300-S2998 A-C	E300 DRIFT-S2998	4-71	05/17/04	6.257	6.257	4.941	5.575	-11%	
E300-S2998 B-D	E300 DRIFT-S2998	4-71	05/17/04	3.115	3.115	2.142	3.513	-39%	
E300-S3195 A-C	E300 DRIFT-S3195	4-72	05/17/04	2.960	2.960	1.939	3.400	-43%	

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
E300-S3195 B-D	E300 DRIFT-S3195	4-72	05/17/04	3.169	3.169	2.027	3.726	-46%	
E140-N780-2 A-C	E140 DRIFT-N780	4-73	06/03/04	3.660	35.438	2.772	3.613	-23%	
E140-N686-2 A-C	E140 DRIFT-N686	4-74	06/03/04	2.624	15.786	2.082	2.478	-16%	
E140-N686-2 B-D	E140 DRIFT-N686	4-74	06/03/04	1.976	13.019	1.553	2.041	-24%	
E140-N626-3 A-C	E140 DRIFT-N626	4-75	06/03/04	3.163	35.757	2.540	2.844	-11%	
E140-N626-4 B-D	E140 DRIFT-N626	4-75	06/03/04	1.965	23.325	1.522	1.898	-20%	
E140-N562-2 A-C	E140 DRIFT-N562	4-76	06/03/04	2.504	14.345	2.007	2.211	-9%	
E140-N562-2 B-D	E140 DRIFT-N562	4-76	06/03/04	1.990	10.292	1.518	1.794	-15%	
E140-N460-3 A-C	E140 DRIFT-N460	4-77	06/03/04	5.085	25.981	1.918	1.927	0%	
E140-N355 A-C	E140 DRIFT-N355	4-78	06/03/04	5.058	5.058	1.621	1.730	-6%	
E140-N355 B-D	E140 DRIFT-N355	4-78	06/03/04	4.520	4.520	1.459	1.545	-6%	
E140-N220-2 A-C	E140 DRIFT-N220	4-79	06/03/04	0.923	22.412	1.437	1.627	-12%	Reinstalled 10/03.
E140-N150-3 A-C	E140 DRIFT-N150	4-80	06/03/04	0.184	16.627	N/A	1.125	N/A	Reinstalled 4/04.
E140-N5-4 A-C	E140 DRIFT-N5	4-81	06/03/04	7.741	29.447	1.249	1.210	3%	
E140-N5-3 B-D	E140 DRIFT-N5	4-81	06/03/04	8.080	23.321	0.960	0.983	-2%	
E140-S90-3 A-C	E140 DRIFT-S90	4-82	06/03/04	7.579	14.959	1.129	1.177	-4%	
E140-S262-3 A-C	E140 DRIFT-S262	4-83	06/03/04	17.074	20.090	1.548	1.594	-3%	
E140-S262-3 B-D	E140 DRIFT-S262	4-83	06/03/04	11.709	13.062	0.970	1.031	-6%	
E140-S460-4 A-C	E140 DRIFT-S460	4-84	05/17/04	12.913	38.624	1.834	2.050	-11%	
E140-S460-2 B-D	E140 DRIFT-S460	4-84	05/17/04	18.327	24.271	0.927	0.978	-5%	
E140-S550-4 A-C	E140 DRIFT-S550	4-85	05/17/04	8.260	32.377	1.170	1.255	-7%	
E140-S550-4 B-D	E140 DRIFT-S550	4-85	05/17/04	19.076	27.718	0.947	1.009	-6%	
E140-S700-5 A-D	E140 DRIFT-S700	4-86	05/17/04	4.315	20.498	1.088	1.194	-9%	
E140-S700-4 B-C	E140 DRIFT-S700	4-87	05/17/04	8.097	20.058	1.107	1.189	-7%	
E140-S700-4 E-F	E140 DRIFT-S700	4-87	05/17/04	5.852	14.668	0.796	0.854	-7%	
E140-S850-7 A-C	E140 DRIFT-S850	4-88	05/17/04	11.356	37.876	1.747	1.795	-3%	

<sup>A</sup> NA indicates insufficient data to compare annualized rates.

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
			Date	Inches					
E140-S850-4 B-D	E140 DRIFT-S850	4-89	05/17/04	9.882	25.829	0.915	0.999	-8%	
E140-S1000 A-C	E140 DRIFT-S1000	4-90	05/17/04	25.898	25.898	1.064	1.278	-17%	
E140-S1025-2 A-C	E140 DRIFT-S1025	4-91	06/24/04	9.655	12.201	1.304	1.279	2%	
E140-S1075-2 A-E	E140 DRIFT-S1075	4-92	06/24/04	9.970	11.717	1.481	1.501	-1%	
E140-S1075-2 B-D	E140 DRIFT-S1075	4-92	06/24/04	9.771	11.433	1.536	1.479	4%	
E140-S1075-2 F-H	E140 DRIFT-S1075	4-92	06/24/04	8.284	9.864	1.199	1.235	-3%	
E140-S1075-2 C-G	E140 DRIFT-S1075	4-92	06/24/04	7.990	8.864	1.014	1.141	-11%	
E140-S1150-2 A-G	E140 DRIFT-S1150	4-93	06/24/04	11.717	40.864	1.929	1.865	3%	
E140-S1150-2 B-F	E140 DRIFT-S1150	4-93	06/24/04	11.665	13.177	1.876	1.810	4%	
E140-S1150-3 L-H	E140 DRIFT-S1150	4-93	06/24/04	8.568	10.211	1.332	1.420	-6%	
E140-S1150 C-K	E140 DRIFT-S1150	4-94	06/24/04	8.887	8.887	1.005	1.085	-7%	
E140-S1150-2 D-J	E140 DRIFT-S1150	4-94	06/24/04	8.631	28.502	1.135	1.221	-7%	
E140-S1150-2 E-I	E140 DRIFT-S1150	4-94	06/24/04	7.864	8.774	1.039	1.104	-6%	
E140-S1225-2 A-E	E140 DRIFT-S1225	4-95	06/24/04	11.648	13.673	1.871	1.894	-1%	
E140-S1225-2 B-D	E140 DRIFT-S1225	4-95	06/24/04	12.194	14.304	1.918	1.878	2%	
E140-S1225-2 H-F	E140 DRIFT-S1225	4-95	06/24/04	8.718	10.317	1.321	1.432	-8%	
E140-S1225-2 C-G	E140 DRIFT-S1225	4-95	06/24/04	9.613	10.570	1.390	1.408	-1%	
E140-S1300-4 A-C	E140 DRIFT-S1300	4-96	06/24/04	8.480	25.103	1.216	1.218	0%	
E140-S1378-2 A-E	E140 DRIFT-S1378	4-97	06/24/04	11.366	22.204	1.791	1.776	1%	
E140-S1378-2 B-D	E140 DRIFT-S1378	4-97	06/24/04	7.682	17.386	1.179	1.181	0%	
E140-S1378-2 H-F	E140 DRIFT-S1378	4-97	06/24/04	13.233	24.511	2.066	2.070	0%	
E140-S1378 C-G	E140 DRIFT-S1378	4-98	06/24/04	10.395	14.565	1.174	1.250	-6%	
E140-S1456-4 A-G	E140 DRIFT-S1456	4-99	06/24/04	12.998	48.067	2.846	2.698	5%	
E140-S1456-2 B-F	E140 DRIFT-S1456	4-100	06/24/04	14.076	24.244	2.323	2.253	3%	
E140-S1456-2 L-H	E140 DRIFT-S1456	4-100	06/24/04	10.542	19.312	1.844	1.745	6%	
E140-S1456-2 D-J	E140 DRIFT-S1456	4-101	06/24/04	10.015	31.363	1.484	1.483	0%	

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
			Date	Inches					
E140-S1456 K-C	E140 DRIFT-S1456	4-102	06/24/04	10.141	10.141	1.181	1.262	-6%	
E140-S1456-2 I-E	E140 DRIFT-S1456	4-102	06/24/04	8.391	10.001	1.192	1.233	-3%	
E140-S1534-2 A-E	E140 DRIFT-S1534	4-103	06/24/04	25.442	28.603	3.676	5.592	-34%	
E140-S1534-3 B-D	E140 DRIFT-S1534	4-103	06/24/04	1.611	15.055	2.620	3.555	-26%	Reinstalled 12/03.
E140-S1534-2 H-F	E140 DRIFT-S1534	4-103	06/24/04	15.697	18.767	2.366	2.986	-21%	
E140-S1534-2 C-G	E140 DRIFT-S1534	4-103	06/24/04	9.063	10.586	1.302	1.391	-6%	
E140-S1600-5 A-C	E140 DRIFT-S1600	4-104	06/24/04	9.653	26.498	1.484	1.467	1%	
E140-S1687-2 A-E	E140 DRIFT-S1687	4-105	06/24/04	14.747	17.705	2.790	2.575	8%	
E140-S1687-2 B-D	E140 DRIFT-S1687	4-105	06/24/04	12.729	15.613	2.181	2.077	5%	
E140-S1687-2 H-F	E140 DRIFT-S1687	4-105	06/24/04	11.214	13.810	1.962	1.823	8%	
E140-S1687 C-G	E140 DRIFT-S1687	4-105	06/24/04	10.264	10.264	1.300	1.285	1%	
E140-S1775-2 A-G	E140 DRIFT-S1775	4-106	06/21/04	27.353	30.580	5.598	6.695	-16%	
E140-S1775-3 B-F	E140 DRIFT-S1775	4-106	06/21/04	1.280	25.886	4.869	5.145	-5%	Reinstalled 3/04.
E140-S1775-2 L-H	E140 DRIFT-S1775	4-106	06/21/04	11.884	14.070	2.152	2.366	-9%	
E140-S1775 C-K	E140 DRIFT-S1775	4-107	06/21/04	10.342	10.342	1.379	1.243	11%	
E140-S1775-2 D-J	E140 DRIFT-S1775	4-107	06/21/04	9.381	10.691	1.502	1.363	10%	
E140-S1775-2 I-E	E140 DRIFT-S1775	4-107	06/21/04	9.078	10.619	1.467	1.194	23%	
E140-S1862-2 A-E	E140 DRIFT-S1862	4-108	06/24/04	15.596	18.202	3.858	2.944	31%	
E140-S1862-2 B-D	E140 DRIFT-S1862	4-108	06/24/04	14.419	17.335	3.045	2.406	27%	
E140-S1862-2 H-F	E140 DRIFT-S1862	4-108	06/24/04	8.783	10.614	1.748	1.519	15%	
E140-S1862-3 C-G	E140 DRIFT-S1862	4-108	06/24/04	3.700	10.105	1.354	1.309	3%	
E140-S1950-5 A-C	E140 DRIFT-S1950	4-109	06/23/04	3.219	33.329	2.199	3.092	-29%	
E140-S2007-4 A-C	E140 DRIFT-S2007	4-110	06/23/04	0.764	16.877	2.848	3.115	-9%	Reinstalled 3/04.
E140-S2065-3 A-C	E140 DRIFT-S2065	4-111	06/23/04	4.057	16.167	2.874	3.599	-20%	
E140-S2065-2 B-D	E140 DRIFT-S2065	4-111	06/23/04	2.556	9.256	1.730	2.444	-29%	
E140-S2122-3 A-C	E140 DRIFT-S2122	4-112	06/23/04	4.083	17.633	2.860	3.626	-21%	

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
E140-S2180-4 A-C	E140 DRIFT-S2180	4-113	06/23/04	3.889	21.973	2.615	3.739	-30%	
E140-S2275-2 A-C	E140 DRIFT-S2275	4-114	06/23/04	11.711	23.491	8.139	11.037	-26%	
E140-S2275 B-D	E140 DRIFT-S2275	4-114	06/23/04	8.829	8.829	2.162	2.266	-5%	
E140-S2350-3 A-C	E140 DRIFT-S2350	4-115	06/23/04	7.898	34.064	6.338	4.489	41%	
E140-S2350-2 B-D	E140 DRIFT-S2350	4-115	06/23/04	9.308	16.199	2.308	2.540	-9%	
E140-S2425-2 A-C	E140 DRIFT-S2425	4-116	06/23/04	6.453	15.303	5.210	4.449	17%	
E140-S2425 B-D	E140 DRIFT-S2425	4-116	06/23/04	9.292	9.292	2.325	2.507	-7%	
E140-S2520-2 A-C	E140 DRIFT-S2520	4-117	06/23/04	4.388	13.038	3.141	3.805	-17%	
E140-S2634 A-C	E140 DRIFT-S2634	4-118	06/23/04	8.430	8.430	5.997	9.014	-33%	
E140-S2634 B-D	E140 DRIFT-S2634	4-118	06/23/04	3.242	3.242	2.365	2.791	-15%	
E140-S2750 A-C	E140 DRIFT-S2750	4-119	06/23/04	4.029	4.029	2.704	2.705	0%	
E140-S2833 A-C	E140 DRIFT-S2833	4-120	06/23/04	6.336	6.336	4.542	3.414	33%	
E140-S2833 B-D	E140 DRIFT-S2833	4-120	06/23/04	3.367	3.367	2.048	2.418	-15%	
E140-S2915 A-C	E140 DRIFT-S2915	4-121	06/23/04	8.867	8.867	6.076	5.525	10%	
E140-S2915 B-D	E140 DRIFT-S2915	4-121	06/23/04	3.737	3.737	2.275	2.690	-15%	
E140-S2998 A-C	E140 DRIFT-S2998	4-122	06/23/04	9.145	9.145	6.253	5.681	10%	
E140-S2998 B-D	E140 DRIFT-S2998	4-122	06/23/04	3.565	3.565	2.143	2.695	-20%	
E140-S3080 A-C	E140 DRIFT-S3080	4-123	06/23/04	4.376	4.376	3.071	3.646	-16%	
E140-S3195 A-C	E140 DRIFT-S3195	4-124	06/23/04	6.448	6.448	4.961	4.582	8%	
E140-S3195 B-D	E140 DRIFT-S3195	4-124	06/23/04	3.436	3.436	2.033	3.354	-39%	
E140-S3310 A-C	E140 DRIFT-S3310	4-125	06/23/04	4.277	4.277	2.845	3.975	-28%	
E0-N1266-4 A-C	E0 DRIFT-N1266	4-126	06/03/04	1.403	38.329	2.017	N/A	N/A	Reinstalled 10/03.
E0-N940-4 A-C	E0 DRIFT-N940	4-127	06/03/04	1.529	47.039	2.193	N/A	N/A	Reinstalled 10/03.
E0-N780-2 A-C	E0 DRIFT-N780	4-128	06/03/04	1.415	21.855	2.032	N/A	N/A	Reinstalled 10/03.
E0-N686 A-C	E0 DRIFT-N686	4-129	06/03/04	2.809	2.809	2.328	N/A	N/A	Installed 4/03.
E0-N686 B-D	E0 DRIFT-N686	4-129	06/03/04	1.924	1.924	1.534	N/A	N/A	Installed 4/03.
E0-N626-4 A-C	E0 DRIFT-N626	4-130	06/03/04	2.620	43.598	2.039	N/A	N/A	Reinstalled 4/03.
E0-N562 A-C	E0 DRIFT-N562	4-131	06/03/04	1.981	1.981	1.553	N/A	N/A	Installed 4/03.
E0-N562 B-D	E0 DRIFT-N562	4-131	06/03/04	1.880	1.880	1.488	N/A	N/A	Installed 4/03.

<sup>A</sup> NA indicates insufficient data to compare annualized rates.

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
E0-N460-3 A-C	E0 DRIFT-N460	4-132	06/03/04	5.479	25.626	1.813	2.053	-12%	
E0-N300-5 A-C	E0 DRIFT-N300	4-133	06/08/04	0.313	39.988	N/A	1.800	N/A	Reinstalled 5/04.
E0-N225-2 A-C	E0 DRIFT-N225	4-134	06/03/04	4.781	4.872	1.641	1.809	-9%	
E0-N225 B-D	E0 DRIFT-N225	4-134	06/03/04	4.535	4.535	1.317	1.511	-13%	
E0-N75 A-C	E0 DRIFT-N75	4-135	06/03/04	4.562	21.582	1.841	2.200	-16%	
E0-N75 B-D	E0 DRIFT-N75	4-135	06/03/04	3.282	3.282	1.267	1.614	-21%	
W30-S120 A-C	W30 DRIFT-S120	4-136	06/01/04	17.449	17.449	0.850	0.960	-11%	
W30-S250-3 A-C	W30 DRIFT-S250	4-137	01/26/04	14.267	23.779	0.925	1.061	-13%	
W30-S250-5 B-D	W30 DRIFT-S250	4-137	06/01/04	9.503	20.457	0.671	0.773	-13%	
W30-S400 A-C	W30 DRIFT-S400	4-138	12/01/03	15.082	15.082	0.749	0.830	-10%	
W30-S500 A-C	W30 DRIFT-S500	4-139	06/01/04	20.420	20.420	0.727	0.772	-6%	
W30-S500 B-D	W30 DRIFT-S500	4-139	06/01/04	19.322	19.322	0.628	0.743	-15%	
W30-S700-2 A-C	W30 DRIFT-S700	4-140	06/01/04	6.398	26.839	0.860	0.979	-12%	
W30-S850-2 A-E	W30 DRIFT-S850	4-141	06/01/04	9.049	15.802	0.537	0.621	-14%	
W30-S850-2 B-D	W30 DRIFT-S850	4-141	06/01/04	6.212	10.774	0.360	0.450	-20%	
W30-S850 H-F	W30 DRIFT-S850	4-141	06/01/04	11.734	11.734	0.380	0.460	-17%	
W30-S850 C-G	W30 DRIFT-S850	4-141	06/01/04	17.608	17.608	0.577	0.717	-20%	
W30-S1000-3 A-C	W30 DRIFT-S1000	4-142	06/01/04	13.434	30.301	1.092	1.160	-6%	
W30-S1100 A-C	W30 DRIFT-S1100	4-143	06/01/04	8.082	8.082	0.827	0.899	-8%	
W30-S1200 A-C	W30 DRIFT-S1200	4-144	06/01/04	8.150	8.150	0.842	0.817	3%	
W30-S1300 A-C	W30 DRIFT-S1300	4-145	06/01/04	15.010	15.010	0.959	1.011	-5%	
W30-S1453 A-C	W30 DRIFT-S1453	4-146	06/01/04	10.297	10.297	0.757	0.834	-9%	
W30-S1453-2 B-D	W30 DRIFT-S1453	4-146	06/01/04	5.536	10.459	0.721	0.775	-7%	
W30-S1600-1 A-C	W30 DRIFT-S1600	4-147	06/01/04	4.825	13.567	0.932	0.994	-6%	
W30-S1775 A-C	W30 DRIFT-S1775	4-148	06/01/04	7.622	7.622	0.545	0.601	-9%	
W30-S1775-2 B-D	W30 DRIFT-S1775	4-148	06/01/04	4.966	9.006	0.676	0.670	1%	

<sup>A</sup> NA indicates insufficient data to compare annualized rates.

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
			Date	Inches					
W30-S1950 A-C	W30 DRIFT-S1950	4-149	06/01/04	13.041	13.041	0.966	0.974	-1%	
W30-S2067 A-C	W30 DRIFT-S2067	4-150	06/01/04	9.954	9.954	0.815	0.855	-5%	
W30-S2067-2 B-D	W30 DRIFT-S2067	4-150	06/01/04	5.622	10.531	0.844	0.828	2%	
W30-S2180 A-C	W30 DRIFT-S2180	4-151	06/01/04	16.033	16.033	1.208	1.173	3%	
W30-S2275-2 A-C	W30 DRIFT-S2275	4-152	05/28/04	3.735	4.574	0.891	0.987	-10%	
W30-S2275 B-D	W30 DRIFT-S2275	4-152	05/28/04	5.369	5.369	1.027	1.109	-7%	
W30-S2350-2 A-C	W30 DRIFT-S2350	4-153	05/28/04	4.183	5.271	0.979	1.074	-9%	
W30-S2350 B-D	W30 DRIFT-S2350	4-153	05/28/04	6.119	6.119	1.133	1.252	-10%	
W30-S2425-2 A-C	W30 DRIFT-S2425	4-154	05/28/04	4.474	5.463	1.015	1.105	-8%	
W30-S2425 B-D	W30 DRIFT-S2425	4-154	05/28/04	6.358	6.358	1.233	1.303	-5%	
W30-S2520-2 A-C	W30 DRIFT-S2520	4-155	06/01/04	6.772	8.693	1.496	1.575	-5%	
W30-S2685-2 A-C	W30 DRIFT-S2685	4-156	05/20/04	4.744	6.878	1.951	1.929	1%	
W30-S2685-2 B-D	W30 DRIFT-S2685	4-156	05/20/04	4.044	6.224	1.475	1.673	-12%	
W30-S2750 A-C	W30 DRIFT-S2750	4-157	05/20/04	2.493	2.493	1.588	1.897	-16%	
W30-S2833 A-C	W30 DRIFT-S2833	4-158	05/20/04	2.206	2.206	1.547	1.819	-15%	
W30-S2833 B-D	W30 DRIFT-S2833	4-158	05/20/04	2.254	2.254	1.535	1.941	-21%	
W30-S2916 A-C	W30 DRIFT-S2916	4-159	05/20/04	2.782	2.782	2.138	2.457	-13%	
W30-S2916 B-D	W30 DRIFT-S2916	4-159	05/20/04	2.048	2.048	1.477	2.049	-28%	
W30-S2998 A-C	W30 DRIFT-S2998	4-160	05/20/04	2.330	2.330	1.541	2.090	-26%	
W30-S2998 B-D	W30 DRIFT-S2998	4-160	05/20/04	2.320	2.320	1.505	2.093	-28%	
W30-S3080 A-C	W30 DRIFT-S3080	4-161	05/20/04	4.312	4.312	2.636	4.256	-38%	
W30-S3195 A-C	W30 DRIFT-S3195	4-162	05/20/04	2.759	2.759	1.672	2.780	-40%	
W30-S3195 B-D	W30 DRIFT-S3195	4-162	05/20/04	2.613	2.613	1.521	2.691	-43%	
W30-S3310 A-C	W30 DRIFT-S3310	4-163	05/20/04	2.782	2.782	1.862	3.295	-43%	
W170-N150-2 A-C	W170 DRIFT-N150	4-164	06/16/04	5.540	6.986	0.516	0.494	4%	
W170-S5 A-C	W170 DRIFT-S5	4-165	06/16/04	10.702	10.702	0.575	0.529	9%	

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
			Date	Inches					
W170-S5-2 B-D	W170 DRIFT-S5	4-165	06/16/04	4.353	12.145	0.665	0.664	0%	
W170-S90-3 A-C	W170 DRIFT-S90	4-166	06/16/04	1.884	9.154	0.959	0.772	24%	
W170-S232-2 A-C	W170 DRIFT-S232	4-167	06/07/04	2.138	7.750	0.555	0.598	-7%	
W170-S232-2 B-D	W170 DRIFT-S232	4-167	06/07/04	5.216	7.858	0.547	0.641	-15%	
W170-S400 A-C	W170 DRIFT-S400	4-168	06/07/04	9.519	9.519	0.652	0.674	-3%	
W170-S560-3 A-C	W170 DRIFT-S560	4-169	06/07/04	2.298	8.393	0.620	0.623	0%	
W170-S560-2 B-D	W170 DRIFT-S560	4-169	06/07/04	5.902	9.034	0.617	0.683	-10%	
W170-S700 A-C	W170 DRIFT-S700	4-170	06/07/04	17.205	17.205	0.655	0.674	-3%	
W170-S850-6 A-E	W170 DRIFT-S850	4-171	06/07/04	2.148	14.637	0.611	0.633	-3%	
W170-S850-5 B-D	W170 DRIFT-S850	4-172	06/07/04	1.856	10.855	0.474	0.493	-4%	
W170-S850-6 H-F	W170 DRIFT-S850	4-172	06/07/04	1.648	10.028	0.415	0.463	-10%	
W170-S850-3 C-G	W170 DRIFT-S850	4-173	06/07/04	5.871	16.684	0.650	0.686	-5%	
W170-S1000-2 A-C	W170 DRIFT-S1000	4-174	06/07/04	2.708	19.392	1.053	0.700	50%	
W170-S1150-3 A-E	W170 DRIFT-S1150	4-175	06/07/04	4.089	17.361	0.713	0.703	1%	
W170-S1150-3 B-D	W170 DRIFT-S1150	4-175	06/07/04	2.921	12.159	0.487	0.520	-6%	
W170-S1150-2 C-G	W170 DRIFT-S1150	4-175	06/07/04	6.404	17.981	0.703	0.727	-3%	
W170-S1150 H-F	W170 DRIFT-S1150	4-175	06/07/04	11.444	11.444	0.509	0.530	-4%	
W170-S1300-3 A-C	W170 DRIFT-S1300	4-176	06/07/04	12.631	15.711	1.325	1.098	21%	
W170-S1445-3 A-C	W170 DRIFT-S1445	4-177	06/07/04	3.942	8.677	0.764	0.674	13%	
W170-S1445-2 B-D	W170 DRIFT-S1445	4-177	06/07/04	5.686	8.344	0.606	0.636	-5%	
W170-S1600-2 A-C	W170 DRIFT-S1600	4-178	06/07/04	4.888	10.686	0.832	0.834	0%	
W170-S1779-2 A-C	W170 DRIFT-S1779	4-179	06/07/04	5.062	11.293	0.908	0.987	-8%	
W170-S1779-2 B-D	W170 DRIFT-S1779	4-179	06/07/04	6.687	9.822	0.766	0.786	-3%	
W170-S1950-2 A-C	W170 DRIFT-S1950	4-180	06/07/04	4.613	10.036	0.766	0.799	-4%	
W170-S2060-2 A-C	W170 DRIFT-S2060	4-181	06/07/04	4.781	10.339	0.822	0.868	-5%	
W170-S2060-2 B-D	W170 DRIFT-S2060	4-181	06/07/04	7.013	10.337	0.846	0.851	-1%	

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
W170-S2180-2 A-C	W170 DRIFT-S2180	4-182	06/07/04	6.144	12.159	1.036	1.051	-1%	
W170-S2275 A-C	W170 DRIFT-S2275	4-183	05/28/04	5.049	5.049	0.992	1.029	-4%	
W170-S2275 B-D	W170 DRIFT-S2275	4-183	05/28/04	5.318	5.318	1.070	1.086	-1%	
W170-S2350 A-C	W170 DRIFT-S2350	4-184	05/28/04	6.663	6.663	1.293	1.321	-2%	
W170-S2350 B-D	W170 DRIFT-S2350	4-184	05/28/04	5.658	5.658	1.092	1.124	-3%	
W170-S2425 A-C	W170 DRIFT-S2425	4-185	05/28/04	6.112	6.112	1.133	1.201	-6%	
W170-S2425 B-D	W170 DRIFT-S2425	4-185	05/28/04	6.180	6.180	1.136	1.246	-9%	
W170-S2520 A-C	W170 DRIFT-S2520	4-186	05/28/04	6.763	6.763	1.233	1.320	-7%	
W170-S2685-2 A-C	W170 DRIFT-S2685	4-187	05/20/04	4.255	6.121	1.669	1.769	-6%	
W170-S2685-2 B-D	W170 DRIFT-S2685	4-187	05/20/04	3.774	5.670	1.338	1.553	-14%	
W170-S2750 A-C	W170 DRIFT-S2750	4-188	05/20/04	2.406	2.406	1.518	1.681	-10%	
W170-S2833 A-C	W170 DRIFT-S2833	4-189	05/20/04	2.238	2.238	1.552	1.804	-14%	
W170-S2833 B-D	W170 DRIFT-S2833	4-189	05/20/04	2.034	2.034	1.368	1.727	-21%	
W170-S2916 A-C	W170 DRIFT-S2916	4-190	05/28/04	5.470	5.470	3.909	4.082	-4%	
W170-S2916 B-D	W170 DRIFT-S2916	4-190	05/20/04	1.843	1.843	1.588	1.938	-18%	
W170-S2998 A-C	W170 DRIFT-S2998	4-191	05/20/04	2.836	2.836	2.033	2.179	-7%	
W170-S2998 B-D	W170 DRIFT-S2998	4-191	05/20/04	2.348	2.348	1.537	2.045	-25%	
W170-S3080 A-C	W170 DRIFT-S3080	4-192	05/20/04	2.384	2.384	1.575	2.057	-23%	
W170-S3195 A-C	W170 DRIFT-S3195	4-193	05/20/04	2.809	2.809	1.684	2.838	-41%	
W170-S3195 B-D	W170 DRIFT-S3195	4-193	05/20/04	2.480	2.480	1.436	2.497	-42%	
W170-S3310 A-C	W170 DRIFT-S3310	4-194	05/20/04	2.214	2.214	1.452	2.482	-41%	
N780-E70 A-C	N780 DRIFT-E70	4-195	12/04/03	1.086	1.086	1.468	N/A	N/A	New installation 4/03.
N780-E70 B-D	N780 DRIFT-E70	4-195	12/04/03	1.065	1.065	1.207	N/A	N/A	New installation 4/03.
N460-E70-3 A-C	N460 DRIFT-E70	4-196	06/29/04	4.158	20.670	1.379	1.465	-6%	
N460-E70-2 B-D	N460 DRIFT-E70	4-196	06/29/04	4.774	16.522	1.462	1.632	-10%	
N250-E220 A-E	N250 DRIFT-E220	4-197	05/17/04	20.349	20.349	1.506	1.613	-7%	
N250-E220 B-D	N250 DRIFT-E220	4-197	05/17/04	21.015	21.015	1.628	1.708	-5%	
N250-E220 H-F	N250 DRIFT-E220	4-197	05/17/04	15.788	15.788	1.146	1.242	-8%	

<sup>A</sup> NA indicates insufficient data to compare annualized rates.

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
			Date	Inches					
N250-E220 C-G	N250 DRIFT-E220	4-197	05/17/04	15.244	15.244	1.051	1.107	-5%	
N300-W170-2 A-C	N300 DRIFT-W170	4-198	06/24/04	0.675	22.953	2.745	1.560	76%	Reinstalled 3/04.
N300-W170-1 B-D	N300 DRIFT-W170	4-198	06/24/04	6.530	14.775	1.408	1.154	22%	
N215-W500-2 A-C	N215 DRIFT-W500	4-199	06/24/04	0.544	18.891	2.226	1.343	66%	Reinstalled 3/04.
N215-W500-2 B-D	N215 DRIFT-W500	4-199	06/24/04	5.480	12.350	0.841	0.871	-3%	
N215-W620 A-C	N215 DRIFT-W620	4-200	04/21/04	16.238	16.238	0.797	1.025	-22%	
N140-E90 A-C	N140 DRIFT-E90	4-201	06/25/04	11.943	11.943	0.572	0.701	-18%	
N140-E90 B-D	N140 DRIFT-E90	4-201	06/25/04	12.400	12.400	0.725	0.760	-5%	
N140-W50-2 B-D	N140 DRIFT-W50	4-202	06/25/04	6.607	18.813	1.008	1.167	-14%	
S90-W120 A-C	S90 DRIFT-W120	4-203	06/16/04	2.922	2.922	0.619	0.650	-5%	
S90-W120 B-D	S90 DRIFT-W120	4-203	06/16/04	3.069	3.069	0.689	0.680	1%	
S90-W400 A-C	S90 DRIFT-W400	4-204	06/16/04	12.970	12.970	0.663	0.765	-13%	
S90-W400-2 B-D	S90 DRIFT-W400	4-204	06/16/04	4.554	12.477	0.648	0.630	3%	
S90-W590 A-C	S90 DRIFT-W590	4-205	06/16/04	8.991	8.991	0.603	0.610	-1%	
S90-W590-2 B-D	S90 DRIFT-W590	4-205	06/16/04	4.374	8.211	0.533	0.528	1%	
S90-W620 A-C	S90 DRIFT-W620	4-206	06/16/04	16.584	16.584	1.076	1.016	6%	
S90-W770 A-C	S90 DRIFT-W770	4-207	06/16/04	11.188	11.188	0.817	0.772	6%	
S90-W770-2 B-D	S90 DRIFT-W770	4-207	06/16/04	4.425	10.112	0.756	0.716	6%	
CORE-W10 A-C	CORE STORAGE W10	4-208	06/24/04	15.828	15.828	0.833	0.828	1%	
CORE-W20 A-C	CORE STORAGE W20	4-208	06/24/04	14.703	14.703	0.805	0.828	-3%	
CORE-W30 A-C	CORE STORAGE W30	4-208	06/24/04	15.288	15.288	0.847	0.876	-3%	
CORE-W51 A-C	CORE STORAGE W51	4-208	06/24/04	17.048	17.048	0.996	1.000	0%	
CORE-W62 A-C	CORE STORAGE W62	4-208	06/24/04	17.697	17.697	1.059	1.033	3%	
CORE-W73 A-C	CORE STORAGE W73	4-208	06/24/04	17.831	17.831	1.083	1.068	1%	
CORE-W101 A-C	CORE STORAGE W101	4-208	06/24/04	17.535	17.535	1.036	1.010	3%	

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
			Date	Inches					
CORE-W117 A-C	CORE STORAGE W117	4-208	06/24/04	15.972	15.972	0.879	0.902	-3%	
CORE-W133 A-C	CORE STORAGE W133	4-208	06/24/04	13.751	13.751	0.734	0.740	-1%	
S700-E205-2 A-C	S700 DRIFT-E205	4-209	06/16/04	14.511	17.453	1.325	1.351	-2%	
S700-E205 B-D	S700 DRIFT-E205	4-209	06/16/04	25.533	25.533	0.994	1.023	-3%	
S700-W98 A-C	S700 DRIFT-W98	4-210	06/16/04	13.650	13.650	1.236	1.222	1%	
S1000-E160 A-C	S1000 DRIFT-E160	4-211	06/29/04	5.931	5.931	0.692	0.695	0%	
S1000-E120-2 A-C	S1000 DRIFT-E120	4-212	06/14/04	2.645	7.722	1.116	1.108	1%	
S1000-E58-3 A-C	S1000 DRIFT-E58	4-213	06/14/04	11.955	14.917	1.036	1.080	-4%	
S1000-E58-2 B-D	S1000 DRIFT-E58	4-213	06/14/04	10.217	11.761	0.768	0.900	-15%	
S1000-W98-2 A-C	S1000 DRIFT-W98	4-214	06/16/04	0.557	19.326	2.460	1.468	68%	
S1000-W98-2 B-D	S1000 DRIFT-W98	4-214	06/16/04	0.469	13.321	1.889	1.056	79%	
S1300-E160 A-C	S1300 DRIFT-E160	4-215	06/29/04	10.348	10.348	1.159	1.177	-2%	
S1300-E120 A-C	S1300 DRIFT-E120	4-216	06/29/04	7.590	7.590	0.811	0.863	-6%	
S1300-E24 A-C	S1300 DRIFT-E24	4-217	06/16/04	13.598	13.598	0.957	0.985	-3%	
S1300-W55 A-C	S1300 DRIFT-W55	4-218	06/16/04	10.564	10.564	1.059	1.065	-1%	
S1300-W100-2 A-C	S1300 DRIFT-W100	4-219	06/16/04	15.417	21.937	1.566	1.503	4%	
S1600-E170 A-C	S1600 DRIFT-E170	4-220	06/29/04	8.968	8.968	0.920	0.948	-3%	
S1600-E110 A-C	S1600 DRIFT-E110	4-221	06/29/04	8.139	8.139	0.835	0.871	-4%	
S1950-E113-4 A-C	S1950 DRIFT-E113	4-222	06/14/04	2.614	6.541	0.665	0.712	-7%	
S1950-E281-3 A-C	S1950 DRIFT-E281	4-223	05/12/04	6.214	12.783	1.006	0.904	11%	
S1950-E284-3 A-C	S1950 DRIFT-E284	4-224	05/12/04	6.236	12.875	1.046	0.926	13%	
S2180-E55-2 A-C	S2180 DRIFT-E55	4-225	05/17/04	4.647	4.967	1.284	1.306	-2%	
S2180-E55 B-D	S2180 DRIFT-E55	4-225	05/17/04	3.949	3.949	1.031	0.993	4%	
S2180-E220 A-C	S2180 DRIFT-E220	4-226	05/17/04	4.901	4.901	1.294	1.284	1%	
S2180-E220 B-D	S2180 DRIFT-E220	4-226	05/17/04	5.005	5.005	1.329	1.303	2%	

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
			Date	Inches					
S2180-W100-2 A-C	S2180 DRIFT-W100	4-227	05/28/04	5.976	6.125	1.571	1.507	4%	
S2180-W100-2 B-D	S2180 DRIFT-W100	4-227	05/28/04	3.930	4.116	0.968	0.966	0%	
S2520-E55 A-C	S2520 DRIFT-E55	4-228	05/04/04	8.525	8.525	1.563	1.692	-8%	
S2520-E55 B-D	S2520 DRIFT-E55	4-228	05/04/04	8.369	8.369	1.491	1.954	-24%	
S2520-E220 A-C	S2520 DRIFT-E220	4-229	06/07/04	8.021	8.021	1.626	1.605	1%	
S2520-E220 B-D	S2520 DRIFT-E220	4-229	06/07/04	7.828	7.828	1.629	1.568	4%	
S2520-W100 A-C	S2520 DRIFT-W100	4-230	05/28/04	7.440	7.440	1.352	1.394	-3%	
S2520-W100 B-D	S2520 DRIFT-W100	4-230	05/28/04	7.130	7.130	1.308	1.327	-1%	
S2750-E55 A-C	S2750 DRIFT-E55	4-231	05/20/04	2.582	2.582	1.763	1.824	-3%	
S2750-E55 B-D	S2750 DRIFT-E55	4-231	05/20/04	2.342	2.342	1.536	1.686	-9%	
S2750-E220 A-C	S2750 DRIFT-E220	4-232	05/20/04	2.787	2.787	2.048	2.261	-9%	
S2750-E220 B-D	S2750 DRIFT-E220	4-232	05/20/04	2.580	2.580	1.822	2.247	-19%	
S2750-W93 A-C	S2750 DRIFT-W93	4-233	05/20/04	2.441	2.441	1.738	1.819	-4%	
S2750-W93 B-D	S2750 DRIFT-W93	4-233	05/20/04	1.880	1.880	1.260	1.377	-8%	
S3080-E55 A-C	S3080 DRIFT-E55	4-234	06/23/04	3.326	3.326	2.270	2.445	-7%	
S3080-E55-2 B-D	S3080 DRIFT-E55	4-234	06/23/04	0.783	2.483	1.651	2.485	-34%	
S3080-E220 A-C	S3080 DRIFT-E220	4-235	05/20/04	2.734	2.734	1.979	2.686	-26%	
S3080-E220 B-D	S3080 DRIFT-E220	4-235	05/20/04	2.731	2.731	1.894	2.892	-35%	
S3080-W100 A-C	S3080 DRIFT-W100	4-236	04/05/04	2.385	2.385	1.769	2.050	-14%	
S3080-W100 B-D	S3080 DRIFT-W100	4-236	04/05/04	2.136	2.136	1.509	2.124	-29%	
S3310-E55 A-C	S3310 DRIFT-E55	4-237	05/20/04	2.763	2.763	1.965	3.056	-36%	
S3310-E55 B-D	S3310 DRIFT-E55	4-237	05/20/04	2.535	2.535	1.717	2.847	-40%	
S3310-E220 A-C	S3310 DRIFT-E220	4-238	05/20/04	2.940	2.940	1.968	3.115	-37%	
S3310-E220 B-D	S3310 DRIFT-E220	4-238	05/20/04	2.930	2.930	1.858	3.380	-45%	
S3310-W100 A-C	S3310 DRIFT-W100	4-239	05/20/04	2.517	2.517	1.772	2.806	-37%	
S3310-W100 B-D	S3310 DRIFT-W100	4-239	05/20/04	1.742	1.742	1.462	2.206	-34%	

**Table 4-1 (Continued)**  
**Access Drifts Data Analysis**

**JOINT METERS**

Field Tag	Location	Figure Number	Date of Last Reading	Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent	Comments
51X-CG-02703	S1950-E300 Overcast-NE	4-240	06/14/04	0.549	0.027	0.023	17%	
51X-CG-02706	S1950-E300 Overcast-SW	4-240	06/14/04	1.070	0.076	0.069	10%	
51X-CG-02707	S1950-E300 Overcast-NW	4-240	06/14/04	1.089	0.076	0.070	9%	
51X-CG-02708	S1950-E300 Overcast-SE	4-240	06/14/04	0.609	0.033	0.035	-6%	

**ROCKBOLT LOAD CELLS**

Field Tag	Location	Figure Number	Date of Initial Reading	Date of Last Reading	Load (kips)	Comments
51X-WG-00293	E140 DRIFT-S1550	4-241	03/17/04	06/24/04	36.000	
51X-WG-00294	E140 DRIFT-S1775	4-242	03/17/04	06/24/04	38.400	
51X-WG-00295	E140 DRIFT-S2900	4-243	03/31/04	06/25/04	36.900	
51X-WG-00296	E140 DRIFT-S2900	4-243	03/31/04	06/25/04	37.800	




Figure 4-1 Extensometer 51X-GE-00265  
S700 Drift at E220 – Roof




Figure 4-2 Extensometer 51X-GE-00364  
E140 Drift at N1266 – Roof




Figure 4-3 Extensometer 51X-GE-00365  
E140 Drift at N940 – Roof






Figure 4-4 Extensometer 41X-GE-00106  
E140 Drift at N250 – Roof



**Figure 4-5 Extensometer 51X-GE-00105-3  
E140 Drift at N150 – Roof**



**Figure 4-6 Extensometer 51X-GE-00276  
E140 Drift at S700 Drift Intersection – Roof**




Figure 4-7 Extensometer 51X-GE-00474  
E120 at S1000 – Roof




Figure 4-8 Extensometer 51X-GE-00472  
E140 Drift at S1000 – Roof




Figure 4-9 Extensometer 51X-GE-00473  
E160 Drift at S1000 – Roof




Figure 4-10 Extensometer 51X-GE-00464  
E140 Drift at S1025 – Roof




Figure 4-11 Extensometer 51X-GE-00333  
E140 Drift at S1075 – Roof




Figure 4-12 Extensometer 51X-GE-00460-2  
E140 Drift at S1150 – Roof




Figure 4-13 Extensometer 41X-GE-00103  
E140 Drift at S1150 – Roof




Figure 4-14 Extensometer 51X-GE-00461  
E140 Drift at S1225 – Roof




Figure 4-15 Extensometer 51X-GE-00334  
E140 Drift at S1225 – Roof




Figure 4-16 Extensometer 51X-GE-00462  
E120 at S1300 – Roof




Figure 4-17 Extensometer 51X-GE-00465  
E140 Drift at S1300 – Roof




Figure 4-18 Extensometer 51X-GE-00335  
E140 Drift at S1300 Drift Intersection – Roof




Figure 4-19 Extensometer 51X-GE-00463  
E160 at S1300 – Roof




Figure 4-20 Extensometer 51X-GE-00336  
E140 Drift at S1375 – Roof




Figure 4-21 Extensometer 41X-GE-00102-2  
E140 Drift at S1450 – Roof







Figure 4-22 Extensometer 51X-GE-00411  
E140 Drift at S1525 – Roof




**Figure 4-23 Extensometer 51X-GE-00442  
E120 at S1600 – Roof**



**Figure 4-24 Extensometer 51X-GE-00446  
E140 Drift at S1600 – Roof**



**Figure 4-25 Extensometer 51X-GE-00338-2  
E140 Drift at S1600 Drift Intersection – Roof**



**Figure 4-26 Extensometer 51X-GE-00441  
E160 at S1600 – Roof**




Figure 4-27 Extensometer 51X-GE-00443  
E140 Drift at S1685 – Roof




Figure 4-28 Extensometer 51X-GE-00339-2  
E140 Drift at S1685 – Roof




Figure 4-29 Extensometer 51X-GE-00492  
E140 Drift at S2750 Drift Intersection – Roof




Figure 4-30 Extensometer 51X-GE-00367  
E140 Drift at S2916 – Roof




Figure 4-31 Extensometer 51X-GE-00493  
E140 Drift at S2916 – Roof






Figure 4-32 Extensometer 51X-GE-00361  
E0 Drift at N1266 – Roof



**Figure 4-33 Extensometer 51X-GE-00352  
E0 Drift at N940 – Roof**



**Figure 4-34 Extensometer 51X-GE-00353  
E0 Drift at N626 – Roof**




Figure 4-35 Extensometer 51X-GE-00355  
E0 Drift at N300 – Roof




Figure 4-36 Extensometer 51X-GE-00481  
N300 Drift at W10 – Roof




Figure 4-37 Extensometer 41X-GE-00127  
N300 Drift at W110 – Roof




Figure 4-38 Extensometer 41X-GE-00126  
N300 Drift at W212 – Roof




Figure 4-39 Extensometer 41X-GE-00125  
N215 Drift at W417 – Roof




Figure 4-40 Extensometer 41X-GE-00124  
N215 Drift at W519 – Roof




Figure 4-41 Extensometer 41X-GE-00123  
W620 Drift at N93 – Roof




Figure 4-42 Extensometer 41X-GE-00122  
W620 Drift at S65 – Roof




Figure 4-43 Extensometer 51X-GE-00494  
E300 Drift at S2892 – Roof




Figure 4-44 Extensometer 51X-GE-00490  
W30 Drift at S2750 Drift Intersection – Roof




Figure 4-45 Extensometer 51X-GE-00491  
W30 Drift at S2916 – Roof




Figure 4-46 Extensometer 51X-GE-00489  
W30 Drift at S3080 Drift Intersection – Roof




Figure 4-47 Extensometer 51X-GE-00495  
W170 Drift at S2634 – Roof







Figure 4-48 Convergence Point Array  
E300 Shop – E300 Drift at N250 – Roof to Floor




**Figure 4-49 Convergence Point Array  
E300 Shop – E300 Drift at N170 – All Chords**




**Figure 4-50 Convergence Point Array  
E300 Shop – E300 Drift at N45 – All Chords**




**Figure 4-51 Convergence Point Array  
E300 Shop – E300 Drift at S45 – All Chords**




**Figure 4-52 Convergence Point Array  
E300 Drift at S90 Drift Intersection – Roof to Floor**




**Figure 4-53 Convergence Point Array  
E300 Drift at S250 – All Chords**




**Figure 4-54 Convergence Point Array  
E300 Drift at S700 Drift Intersection – Roof to Floor**




**Figure 4-55 Convergence Point Array  
E300 Drift at S850 – All Chords**




**Figure 4-56 Convergence Point Array  
E300 Drift at S1000 Drift Intersection – Roof to Floor**




**Figure 4-57 Convergence Point Array  
E300 Drift at S1150 – Roof to Floor**




**Figure 4-58 Convergence Point Array  
E300 Drift at S1150 – Rib to Rib**




**Figure 4-59 Convergence Point Array  
E300 Drift at S1300 Drift Intersection – Roof to Floor**




**Figure 4-60 Convergence Point Array  
E300 Drift at S1450 – All Chords**




**Figure 4-61 Convergence Point Array  
E300 Drift at S1687 – All Chords**




**Figure 4-62 Convergence Point Array  
E300 Drift at S1775 – All Chords**




**Figure 4-63 Convergence Point Array  
E300 Drift at S1862 – All Chords**



**Figure 4-64 Convergence Point Array  
E300 Drift at S2065 – All Chords**



**Figure 4-65 Convergence Point Array  
E300 Drift at S2275 – All Chords**



**Figure 4-66 Convergence Point Array  
E300 Drift at S2350 – All Chords**




Figure 4-67 Convergence Point Array  
E300 Drift at S2425 – All Chords







Figure 4-68 Convergence Point Array  
E300 Drift at S2634 – All Chords




**Figure 4-69 Convergence Point Array  
E300 Drift at S2833 – All Chords**




**Figure 4-70 Convergence Point Array  
E300 Drift at S2916 – All Chords**




**Figure 4-71 Convergence Point Array  
E300 Drift at S2998 – All Chords**




**Figure 4-72 Convergence Point Array  
E300 Drift at S3195 – All Chords**




**Figure 4-73 Convergence Point Array  
E140 Drift at N780 Drift Intersection – Roof to Floor**




**Figure 4-74 Convergence Point Array  
E140 Drift at N686 – All Chords**




**Figure 4-75 Convergence Point Array  
E140 Drift at N626 – All Chords**




**Figure 4-76 Convergence Point Array  
E140 Drift at N562 – All Chords**




**Figure 4-77 Convergence Point Array  
E140 Drift at N460 Drift Intersection – Roof to Floor**




**Figure 4-78 Convergence Point Array  
E140 Drift at N355 – All Chords**




**Figure 4-79 Convergence Point Array  
E140 Drift at N220 – Roof to Floor**




**Figure 4-80 Convergence Point Array  
E140 Drift at N150 Drift Intersection – Roof to Floor**




**Figure 4-81 Convergence Point Array  
E140 Drift at N5 – All Chords**




**Figure 4-82 Convergence Point Array  
E140 Drift at S90 Drift Intersection – Roof to Floor**




**Figure 4-83 Convergence Point Array  
E140 Drift at S262 – All Chords**




**Figure 4-84 Convergence Point Array  
E140 Drift at S460 – All Chords**




**Figure 4-85 Convergence Point Array  
E140 Drift at S550 – All Chords**




**Figure 4-86 Convergence Point Array  
E140 Drift at S700 Drift Intersection – Roof to Floor Centerline**




**Figure 4-87 Convergence Point Array  
E140 Drift at S700 Drift Intersection – Roof to Floor Quarter Points**




**Figure 4-88 Convergence Point Array  
E140 Drift at S850 – Roof to Floor**




**Figure 4-89 Convergence Point Array  
E140 Drift at S850 – Rib to Rib**




**Figure 4-90 Convergence Point Array  
E140 Drift at S1000 Drift Intersection – Roof to Floor**




**Figure 4-91 Convergence Point Array**  
E140 Drift at S1025 – Roof to Floor




**Figure 4-92 Convergence Point Array**  
E140 Drift at S1075 – All Chords




**Figure 4-93 Convergence Point Array  
E140 Drift at S1150 – Roof to Floor**




**Figure 4-94 Convergence Point Array  
E140 Drift at S1150 – Rib to Rib**




**Figure 4-95 Convergence Point Array  
E140 Drift at S1225 – All Chords**




**Figure 4-96 Convergence Point Array  
E140 Drift at S1300 Drift Intersection – Roof to Floor**




**Figure 4-97 Convergence Point Array  
E140 Drift at S1378 – Roof to Floor**




**Figure 4-98 Convergence Point Array  
E140 Drift at S1378 – Rib to Rib**




**Figure 4-99 Convergence Point Array  
E140 Drift at S1450/S1456 – Roof to Floor – Centerline**




**Figure 4-100 Convergence Point Array  
E140 Drift at S1450/S1456 – Roof to Floor – Quarter Points**




**Figure 4-101 Convergence Point Array  
E140 Drift at S1450/S1456 – Rib to Rib – Midheight**




**Figure 4-102 Convergence Point Array  
E140 Drift at S1450/S1456 – Rib to Rib – Quarter Points**




**Figure 4-103 Convergence Point Array  
E140 Drift at S1534 – All Chords**




**Figure 4-104 Convergence Point Array  
E140 Drift at S1600 Drift Intersection – Roof to Floor**




**Figure 4-105 Convergence Point Array  
E140 Drift at S1687 – All Chords**




**Figure 4-106 Convergence Point Array  
E140 Drift at S1775 – Roof to Floor**




**Figure 4-107 Convergence Point Array  
E140 Drift at S1775 – Rib to Rib**




**Figure 4-108 Convergence Point Array  
E140 Drift at S1862 – All Chords**




**Figure 4-109 Convergence Point Array  
E140 Drift at S1950 – Roof to Floor**




**Figure 4-110 Convergence Point Array  
E140 Drift at S2007 – Roof to Floor**




**Figure 4-111 Convergence Point Array  
E140 Drift at S2065 – All Chords**




**Figure 4-112 Convergence Point Array  
E140 Drift at S2122 – Roof to Floor**




**Figure 4-113 Convergence Point Array  
E140 Drift at S2180 Drift Intersection – Roof to Floor**




**Figure 4-114 Convergence Point Array  
E140 Drift at S2275 – All Chords**




**Figure 4-115 Convergence Point Array  
E140 Drift at S2350 – All Chords**




**Figure 4-116 Convergence Point Array  
E140 Drift at S2425 – All Chords**




**Figure 4-117 Convergence Point Array  
E140 Drift at S2520 Drift Intersection – Roof to Floor**




**Figure 4-118 Convergence Point Array  
E140 Drift at S2634 – All Chords**




**Figure 4-119 Convergence Point Array  
E140 Drift at S2750 Drift Intersection – Roof to Floor**




**Figure 4-120 Convergence Point Array  
E140 Drift at S2833 – All Chords**




**Figure 4-121 Convergence Point Array  
E140 Drift at S2915 – All Chords**




**Figure 4-122 Convergence Point Array  
E140 Drift at S2998 – All Chords**




**Figure 4-123 Convergence Point Array  
E140 Drift at S3080 Drift Intersection – Roof to Floor**




**Figure 4-124 Convergence Point Array  
E140 Drift at S3195 – All Chords**




**Figure 4-125 Convergence Point Array  
E140 Drift at S3310 Drift Intersection – Roof to Floor**




**Figure 4-126 Convergence Point Array  
E0 Drift at N1266 – All Chords**




**Figure 4-127 Convergence Point Array  
E0 Drift at N940 – All Chords**




**Figure 4-128 Convergence Point Array  
E0 Drift at N780 – Roof to Floor**




**Figure 4-129 Convergence Point Array  
E0 Drift at N686 – All Chords**




**Figure 4-130 Convergence Point Array  
E0 Drift at N626 – All Chords**




**Figure 4-131 Convergence Point Array  
E0 Drift at N562 – All Chords**




**Figure 4-132 Convergence Point Array  
E0 Drift at N460 Drift Intersection – Roof to Floor**




**Figure 4-133 Convergence Point Array  
E0 Drift at N300 – All Chords**




**Figure 4-134 Convergence Point Array  
E0 Drift at N225 – All Chords**




**Figure 4-135 Convergence Point Array  
E0 Drift at N75 – All Chords**




**Figure 4-136 Convergence Point Array  
W30 Drift at S120 – Roof to Floor**




**Figure 4-137 Convergence Point Array  
W30 Drift at S250 – All Chords**




**Figure 4-138 Convergence Point Array  
W30 Drift at S400 Drift Intersection – Roof to Floor**




**Figure 4-139 Convergence Point Array  
W30 Drift at S500 – All Chords**




**Figure 4-140 Convergence Point Array  
W30 Drift at S700 Drift Intersection – Roof to Floor**




**Figure 4-141 Convergence Point Array  
W30 Drift at S850 – All Chords**




**Figure 4-142 Convergence Point Array  
W30 Drift at S1000 Drift Intersection – Roof to Floor**




**Figure 4-143 Convergence Point Array  
W30 Drift at S1100 – Roof to Floor**




**Figure 4-144 Convergence Point Array  
W30 Drift at S1200 – Roof to Floor**




**Figure 4-145 Convergence Point Array  
W30 Drift at S1300 Drift Intersection – Roof to Floor**




**Figure 4-146 Convergence Point Array  
W30 Drift at S1453 – All Chords**




**Figure 4-147 Convergence Point Array  
W30 Drift at S1600 Drift Intersection – Roof to Floor**




**Figure 4-148 Convergence Point Array  
W30 Drift at S1775 – All Chords**




**Figure 4-149 Convergence Point Array  
W30 Drift at S1950 Drift Intersection – Roof to Floor**




**Figure 4-150 Convergence Point Array  
W30 Drift at S2067 – All Chords**




**Figure 4-151 Convergence Point Array  
W30 Drift at S2180 Drift Intersection – Roof to Floor**




**Figure 4-152 Convergence Point Array  
W30 Drift at S2275 – All Chords**




**Figure 4-153 Convergence Point Array  
W30 Drift at S2350 – All Chords**




**Figure 4-154 Convergence Point Array  
W30 Drift at S2425 – All Chords**




**Figure 4-155 Convergence Point Array  
W30 Drift at S2520 Drift Intersection – Roof to Floor**




**Figure 4-156 Convergence Point Array  
W30 Drift at S2685 – All Chords**




**Figure 4-157 Convergence Point Array  
W30 Drift at S2750 Drift Intersection – Roof to Floor**




**Figure 4-158 Convergence Point Array  
W30 Drift at S2833 – All Chords**




**Figure 4-159 Convergence Point Array  
W30 Drift at S2916 – All Chords**




**Figure 4-160 Convergence Point Array  
W30 Drift at S2998 – All Chords**




**Figure 4-161 Convergence Point Array  
W30 Drift at S3080 Drift Intersection – Roof to Floor**




**Figure 4-162 Convergence Point Array  
W30 Drift at S3195 – All Chords**




**Figure 4-163 Convergence Point Array  
W30 Drift at S3310 Drift Intersection – Roof to Floor**




**Figure 4-164 Convergence Point Array  
W170 Drift at N150 Drift Intersection – Roof to Floor**




**Figure 4-165 Convergence Point Array  
W170 Drift at S5 – All Chords**




**Figure 4-166 Convergence Point Array  
W170 Drift at S90 – Roof to Floor**




**Figure 4-167 Convergence Point Array  
W170 Drift at S232 – All Chords**




**Figure 4-168 Convergence Point Array  
W170 Drift at S400 Drift Intersection – Roof to Floor**




**Figure 4-169 Convergence Point Array  
W170 Drift at S560 – All Chords**




**Figure 4-170 Convergence Point Array  
W170 Drift at S700 Drift Intersection – Roof to Floor**




**Figure 4-171 Convergence Point Array  
W170 Drift at S850 – Roof to Floor – Centerline**




**Figure 4-172 Convergence Point Array  
W170 Drift at S850 – Roof to Floor – Quarter Points**




**Figure 4-173 Convergence Point Array  
W170 Drift at S850 – Rib to Rib**




**Figure 4-174 Convergence Point Array  
W170 Drift at S1000 – Roof to Floor**




**Figure 4-175 Convergence Point Array  
W170 Drift at S1150 – All Chords**




**Figure 4-176 Convergence Point Array  
W170 Drift at S1300 Drift Intersection – Roof to Floor**




**Figure 4-177 Convergence Point Array  
W170 Drift at S1445 – All Chords**




**Figure 4-178 Convergence Point Array  
W170 Drift at S1600 Drift Intersection – Roof to Floor**




**Figure 4-179 Convergence Point Array**  
W170 Drift at S1779 – All Chords




**Figure 4-180 Convergence Point Array**  
W170 Drift at S1950 Drift Intersection – Roof to Floor




**Figure 4-181 Convergence Point Array  
W170 Drift at S2060 – All Chords**




**Figure 4-182 Convergence Point Array  
W170 Drift at S2180 Drift Intersection – Roof to Floor**




**Figure 4-183 Convergence Point Array  
W170 Drift at S2275 – All Chords**




**Figure 4-184 Convergence Point Array  
W170 Drift at S2350 – All Chords**




**Figure 4-185 Convergence Point Array  
W170 Drift at S2425 – All Chords**




**Figure 4-186 Convergence Point Array  
W170 Drift at S2520 Drift Intersection – Roof to Floor**




**Figure 4-187 Convergence Point Array  
W170 Drift at S2685 – All Chords**




**Figure 4-188 Convergence Point Array  
W170 Drift at S2750 Drift Intersection – Roof to Floor**




**Figure 4-189 Convergence Point Array  
W170 Drift at S2833 – All Chords**




**Figure 4-190 Convergence Point Array  
W170 Drift at S2916 – All Chords**




**Figure 4-191 Convergence Point Array  
W170 Drift at S2998 – All Chords**




**Figure 4-192 Convergence Point Array  
W170 Drift at S3080 Drift Intersection – Roof to Floor**




**Figure 4-193 Convergence Point Array  
W170 Drift at S3195 – All Chords**




**Figure 4-194 Convergence Point Array  
W170 Drift at S3310 Drift Intersection – Roof to Floor**




**Figure 4-195 Convergence Point Array  
N780 Drift at E70 – All Chords**




**Figure 4-196 Convergence Point Array  
N460 Drift at E70 – All Chords**




**Figure 4-197 Convergence Point Array  
N250 Drift at E220 – All Chords**




**Figure 4-198 Convergence Point Array  
N300 Drift at W170 – All Chords**




**Figure 4-199 Convergence Point Array  
N215 Drift at W500 – All Chords**




**Figure 4-200 Convergence Point Array  
N215 Drift at W620 at Air Intake Shaft – Roof to Floor**




**Figure 4-201 Convergence Point Array  
N140 Drift at E90 – All Chords**




**Figure 4-202 Convergence Point Array  
N140 Drift at W50 – Rib to Rib**




**Figure 4-203 Convergence Point Array  
S90 Drift at W120 – All Chords**




**Figure 4-204 Convergence Point Array  
S90 Drift at W400 – All Chords**




**Figure 4-205 Convergence Point Array  
S90 Drift at W590 – All Chords**




**Figure 4-206 Convergence Point Array  
S90 Drift at W620 – Roof to Floor**




**Figure 4-207 Convergence Point Array  
S90 Drift at W770 – All Chords**




**Figure 4-208 Convergence Point Array  
S400 Core Storage Library – All Chords**




**Figure 4-209 Convergence Point Array  
S700 Drift at E205 – All Chords**




**Figure 4-210 Convergence Point Array  
S700 Drift at W98 – Roof to Floor**




**Figure 4-211 Convergence Point Array  
S1000 Drift at E160 – Roof to Floor**




**Figure 4-212 Convergence Point Array  
S1000 Drift at E120 – Roof to Floor**




**Figure 4-213 Convergence Point Array  
S1000 Drift at E58 – Roof to Floor**




**Figure 4-214 Convergence Point Array  
S1000 Drift at W98 – All Chords**




**Figure 4-215 Convergence Point Array  
S1300 Drift at E160 – Roof to Floor**




**Figure 4-216 Convergence Point Array  
S1300 Drift at E120 – Roof to Floor**




**Figure 4-217 Convergence Point Array  
S1300 Drift at E24 – Roof to Floor**




**Figure 4-218 Convergence Point Array  
S1300 Drift at W55 – Roof to Floor**




**Figure 4-219 Convergence Point Array  
S1300 Drift at W100 – Roof to Floor**




**Figure 4-220 Convergence Point Array  
S1600 Drift at E170 – Roof to Floor**




**Figure 4-221 Convergence Point Array  
S1600 Drift at E110 – Roof to Floor**




**Figure 4-222 Convergence Point Array  
S1950 Drift at E113 – Roof to Floor**




**Figure 4-223 Convergence Point Array  
S1950 Drift at E281 – Roof to Floor**




**Figure 4-224 Convergence Point Array  
S1950 Drift at E284 – Roof to Floor**




**Figure 4-225 Convergence Point Array  
S2180 Drift at E55 – All Chords**




**Figure 4-226 Convergence Point Array  
S2180 Drift at E220 – All Chords**




**Figure 4-227 Convergence Point Array  
S2180 Drift at W100 – All Chords**




**Figure 4-228 Convergence Point Array  
S2520 Drift at E55 – All Chords**




**Figure 4-229 Convergence Point Array  
S2520 Drift at E220 – All Chords**




**Figure 4-230 Convergence Point Array  
S2520 Drift at W100 – All Chords**




**Figure 4-231 Convergence Point Array  
S2750 Drift at E55 – All Chords**




**Figure 4-232 Convergence Point Array  
S2750 Drift at E220 – All Chords**




**Figure 4-233 Convergence Point Array  
S2750 Drift at W93 – All Chords**




**Figure 4-234 Convergence Point Array  
S3080 Drift at E55 – All Chords**




**Figure 4-235 Convergence Point Array  
S3080 Drift at E220 – All Chords**




**Figure 4-236 Convergence Point Array  
S3080 Drift at W100 – All Chords**




**Figure 4-237 Convergence Point Array  
S3310 Drift at E55 – All Chords**




**Figure 4-238 Convergence Point Array  
S3310 Drift at E220 – All Chords**




**Figure 4-239 Convergence Point Array  
S3310 Drift at W100 – All Chords**



**Figure 4-240 Joint Meters  
S1950 Drift at E300 – Drift Overcast**



**Figure 4-241 Rock Bolt Load Cells  
E140 Drift at S1550**



**Figure 4-242 Rock Bolt Load Cells  
E140 Drift at S1775**




Figure 4-243 Rock Bolt Load Cells  
E140 Drift at S2900

## **5.0 *Instrumentation Summary for the Northern Experimental Area***

---

The northeast and northwest sections of the former WIPP Experimental Areas are no longer accessible and readings were discontinued in June 2002. Instrumentation data for this area has been presented in previous Geotechnical Annual Reports. However, current plans are to utilize E300 for future WIPP-based science experiments. Consequently, East 0, East 140, and E300 from North 1100 to North 1400 drifts have been renovated and reopened. Accordingly instrumentation was reinstalled and the data are now presented in Chapter 4.0 (access drifts).

Remote monitoring of instrumentation east of E300 was discontinued due to mining activities in N1100 drift that required removal of the data logger. Access to this instrumentation is currently not available and there are no plans to reactivate remote monitoring in this area.

A re-entry into previously closed sections of N1100 and N1420 drifts was performed on March 13, 2003. The purpose of the re-entry was to evaluate this area for future operational use. This re-entry documented the condition of installed ground support, opening geometry, and observed geotechnical conditions.

This Page Intentionally  
Left Blank

## ***6.0 Instrumentation Summary for the Waste Disposal Area***

---

This chapter presents a summary of the data collected from instruments located in the Waste Disposal Area at the WIPP. Waste disposal activities in Panel 1 are complete and panel closures have been installed. Geomechanical monitoring of the disposal rooms is no longer performed, however, monitoring continues in the accessible portions of S1600 and S1950 access drifts. Table 6-1 presents data and analysis of the access drifts associated with Panel 1. Plots of the instrument data are presented as Figures 6-1 through 6-15. Panel 2 was the active disposal area during this reporting period. Remote monitoring continued to instrumentation tied into the Geotechnical Instrumentation System throughout the reporting period. Manually read instrumentation data was collected in areas not blocked by emplaced waste. Table 6-2 presents data and analysis of Panel 2. Plots of the instrument data are presented as Figures 6-16 through 6-60. Panel 3 was mined to final dimensions during this reporting period. Instrumentation was installed and in some cases reinstalled during the mining process. Table 6-3 presents data and analysis of Panel 3. Plots of the instrument data are presented as Figures 6-61 through 6-111.


This Page Intentionally  
Left Blank

**Table 6-1**  
**Panel 1 Access Drifts Data Analysis**


**CONVERGENCE POINTS**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
S1600-E311-2 A-C	S1600 DRIFT-E311	6-1	06/25/04	10.564	16.011	0.789	0.765	3%	
S1600-E311-5 B-D	S1600 DRIFT-E311	6-1	06/25/04	5.144	14.387	0.718	0.595	21%	
S1600-E332-3 A-C	S1600 DRIFT-E332	6-2	06/25/04	9.481	13.908	0.835	0.676	24%	
S1600-E357-2 A-C	S1600 DRIFT-E357	6-3	06/25/04	10.862	16.260	0.961	0.745	29%	
S1600-E382-2 A-C	S1600 DRIFT-E382	6-4	06/25/04	10.985	16.365	0.941	0.722	30%	
S1600-E407-2 A-G	S1600 DRIFT-E407	6-5	06/25/04	11.773	17.215	1.017	0.739	38%	
S1600-E407-2 B-F	S1600 DRIFT-E407	6-5	06/25/04	10.809	15.815	0.951	0.684	39%	
S1600-E407-2 H-L	S1600 DRIFT-E407	6-5	06/25/04	11.450	16.515	1.004	0.757	33%	
S1600-E432-2 A-C	S1600 DRIFT-E432	6-6	06/25/04	13.543	20.302	1.107	0.931	19%	
S1600-E453 A-C	S1600 DRIFT-E453	6-7	06/25/04	0.540	0.540	0.561	N/A	N/A	New installation 7/03.
S1600-E453 B-D	S1600 DRIFT-E453	6-7	06/25/04	0.527	0.527	0.561	N/A	N/A	New installation 7/03.
S1950-E311-6 A-C	S1950 DRIFT-E311	6-8	06/29/04	0.769	22.730	1.057	N/A	N/A	Reinstalled 10/03.
S1950-E311-3 B-D	S1950 DRIFT-E311	6-8	06/29/04	7.162	20.205	1.122	0.866	30%	
S1950-E332-4 A-C	S1950 DRIFT-E332	6-9	06/29/04	8.440	27.099	1.408	1.281	10%	
S1950-E332-4 B-D	S1950 DRIFT-E332	6-9	06/29/04	4.408	22.395	1.230	0.983	25%	
S1950-E357-7 A-C	S1950 DRIFT-E357	6-10	06/29/04	10.590	30.832	1.739	1.598	9%	
S1950-E357-4 B-D	S1950 DRIFT-E357	6-10	06/29/04	4.743	23.243	1.314	1.140	15%	
S1950-E382-5 A-C	S1950 DRIFT-E382	6-11	06/29/04	12.754	31.439	1.977	1.739	14%	
S1950-E382-3 B-D	S1950 DRIFT-E382	6-11	06/29/04	10.815	25.197	1.398	1.207	16%	
S1950-E407-4 A-G	S1950 DRIFT-E407	6-12	06/29/04	12.181	34.057	2.121	1.951	9%	
S1950-E407-3 H-L	S1950 DRIFT-E407	6-12	06/29/04	13.642	34.399	2.152	1.796	20%	
S1950-E407-3 C-K	S1950 DRIFT-E407	6-13	04/27/04	10.180	23.157	1.297	1.207	7%	
S1950-E407-3 D-J	S1950 DRIFT-E407	6-13	06/29/04	11.477	25.654	1.483	1.336	11%	
S1950-E432-3 A-C	S1950 DRIFT-E432	6-14	06/29/04	12.589	34.410	2.040	2.004	2%	
S1950-E432-3 B-D	S1950 DRIFT-E432	6-14	06/29/04	10.916	25.317	1.407	1.257	12%	
S1950-E457-5 A-C	S1950 DRIFT-E457	6-15	06/29/04	0.710	33.056	0.744	N/A	N/A	Reinstalled 7/03.
S1950-E457-4 B-D	S1950 DRIFT-E457	6-15	06/29/04	9.584	24.876	0.634	1.178	-46%	


<sup>A</sup> NA indicates insufficient data to compare annualized rates.




**Figure 6-1 Convergence Point Array  
S1600 Drift at E311 – All Chords**




**Figure 6-2 Convergence Point Array  
S1600 Drift at E332 – All Chords**




**Figure 6-3 Convergence Point Array  
S1600 Drift at E357 – All Chords**




**Figure 6-4 Convergence Point Array  
S1600 Drift at E382 – All Chords**




**Figure 6-5 Convergence Point Array  
S1600 Drift at E407 – Roof to Floor**




**Figure 6-6 Convergence Point Array  
S1600 Drift at E432 – All Chords**




**Figure 6-7 Convergence Point Array  
S1600 Drift at E453 – All Chords**




**Figure 6-8 Convergence Point Array  
S1950 Drift at E311 – All Chords**




**Figure 6-9 Convergence Point Array  
S1950 Drift at E332 – All Chords**




**Figure 6-10 Convergence Point Array  
S1950 Drift at E357 – All Chords**




**Figure 6-11 Convergence Point Array  
S1950 Drift at E382 – All Chords**




**Figure 6-12 Convergence Point Array  
S1950 Drift at E407 – Roof to Floor**



**Figure 6-13 Convergence Point Array  
S1950 Drift at E407 – Rib to Rib**



**Figure 6-14 Convergence Point Array  
S1950 Drift at E432 – All Chords**



**Figure 6-15 Convergence Point Array  
S1950 Drift at E457 – All Chords**

**Table 6-2**  
**Panel 2 Data Analysis**

**EXTENSOMETERS**

Field Tag	Location		Figure Number	Date of Last Reading	Collar Displacement Relative to Deepest Anchor (inches)	Displacement Rate 2003 to 2004 in/year	Displacement Rate 2002 to 2003 in/year	Rate Change Percent	Comments
51X-GE-00341	PANEL 2 ROOM 1	CENTER ROOF	6-16	06/29/04	4.707	1.389	1.072	30%	
51X-GE-00342	PANEL 2 ROOM 2	CENTER ROOF	6-17	06/29/04	3.511	0.942	0.829	14%	
51X-GE-00343	PANEL 2 ROOM 3	CENTER ROOF	6-18	06/29/04	4.737	1.364	1.059	29%	
51X-GE-00344	PANEL 2 ROOM 4	CENTER ROOF	6-19	06/29/04	4.026	1.014	0.804	26%	
51X-GE-00345	PANEL 2 ROOM 5	CENTER ROOF	6-20	06/29/04	4.075	1.033	0.820	26%	
51X-GE-00346	PANEL 2 ROOM 6	CENTER ROOF	6-21	06/29/04	-1.966	-4.541	0.725	-726%	Broken anchor "C".
51X-GE-00347	PANEL 2 ROOM 7	CENTER ROOF	6-22	06/29/04	4.086	1.064	0.790	35%	
51X-GE-00348	S2180 DRIFT - E725	ROOF	6-23	06/29/04	5.609	2.136	1.003	113%	
51X-GE-00351	S2180 DRIFT - E1120	ROOF	6-24	07/14/03	2.589	0.815	0.714	14%	Instrument disconnected.
51X-GE-00350	S2520 DRIFT - E735	ROOF	6-25	06/29/04	5.220	1.835	1.156	59%	
51X-GE-00349	S2520 DRIFT - E1120	ROOF	6-26	06/29/04	6.216	2.758	1.020	170%	

**Table 6-2 (Continued)**  
**Panel 2 Data Analysis**

**CONVERGENCE POINTS**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
S2180-E410-2 A-C	S2180 DRIFT-E410	6-27	06/15/04	0.381	5.201	1.545	1.217	27%	Reinstalled 3/04.
S2180-E410 B-D	S2180 DRIFT-E410	6-27	06/15/04	6.112	6.112	1.537	1.374	12%	
S2180-E520-2 A-C	S2180 DRIFT-E520	6-28	06/15/04	0.641	9.557	2.566	2.161	19%	Reinstalled 3/04.
S2180-E586-2 A-C	S2180 DRIFT-E586	6-29	06/15/04	0.793	12.429	3.177	2.887	10%	Reinstalled 3/04.
S2180-E586-2 B-D	S2180 DRIFT-E586	6-29	06/15/04	4.781	8.262	1.902	1.840	3%	
S2180-E660-2 A-C	S2180 DRIFT-E660	6-30	06/15/04	0.789	12.179	3.182	2.824	13%	Reinstalled 3/04.
S2180-E790 A-C	S2180 DRIFT-E790	6-31	12/02/03	12.714	12.714	3.487	3.066	14%	
S2180-E920 A-C	S2180 DRIFT-E920	6-32	09/23/03	13.245	13.245	3.639	3.362	8%	
S2180-E986 A-C	S2180 DRIFT-E986	6-33	09/23/03	12.121	12.121	3.320	3.079	8%	
S2180-E986 B-D	S2180 DRIFT-E986	6-33	10/21/03	8.259	8.259	2.231	1.973	13%	
S2180-E1050-2 A-C	S2180 DRIFT-E1050	6-34	09/23/03	10.833	10.833	3.418	2.911	17%	
S2520-E410-3 A-C	S2520 DRIFT-E410	6-35	06/07/04	1.080	9.273	2.519	2.139	18%	Reinstalled 1/04.
S2520-E410 B-D	S2520 DRIFT-E410	6-35	06/07/04	9.762	9.762	2.437	1.995	22%	
S2520-E520-3 A-C	S2520 DRIFT-E520	6-36	06/07/04	2.663	16.543	6.444	3.493	84%	Reinstalled 1/04.
S2520-E586-2 A-C	S2520 DRIFT-E586	6-37	06/07/04	1.771	15.984	4.212	3.489	21%	Reinstalled 1/04.
S2520-E586 B-D	S2520 DRIFT-E586	6-37	06/07/04	10.243	10.243	2.456	2.027	21%	
S2520-E660-3 A-C	S2520 DRIFT-E660	6-38	06/07/04	2.227	17.659	4.716	3.626	30%	Reinstalled 12/03.
S2520-E790-2 A-C	S2520 DRIFT-E790	6-39	06/07/04	2.110	15.329	4.442	3.177	40%	Reinstalled 12/03.
S2520-E920-2 A-C	S2520 DRIFT-E920	6-40	04/20/04	1.142	13.334	3.899	2.900	34%	Reinstalled 1/04.
S2520-E985-2 A-C	S2520 DRIFT-E985	6-41	02/19/04	0.523	13.274	4.200	2.968	42%	Reinstalled 1/04.
S2520-E985 B-D	S2520 DRIFT-E985	6-41	02/19/04	9.733	9.733	3.036	1.951	56%	
S2520-E1050-2 A-C	S2520 DRIFT-E1050	6-42	01/22/04	1.118	13.127	N/A	2.800	N/A	Reinstalled 10/03.
S2520-E1190-2 A-C	S2520 DRIFT-E1190	6-43	08/26/03	11.303	12.800	4.044	3.213	26%	
E520-S2275-2 A-C	E520 DRIFT-S2275	6-44	06/29/04	2.092	15.659	3.844	3.044	26%	Reinstalled 12/03.
E520-S2275 B-D	E520 DRIFT-S2275	6-44	06/29/04	9.559	9.559	2.156	1.840	17%	
E520-S2350-3 A-C	E520 DRIFT-S2350	6-45	06/29/04	2.461	17.567	4.742	3.384	40%	Reinstalled 12/03.
E520-S2350 B-D	E520 DRIFT-S2350	6-45	06/29/04	11.422	11.422	2.686	2.287	17%	
E520-S2425-2 A-C	E520 DRIFT-S2425	6-46	06/29/04	2.213	15.487	4.068	3.055	33%	Reinstalled 12/03.

<sup>A</sup> NA Indicates insufficient data to compare annualized rates.

**Table 6-2 (Continued)**  
**Panel 2 Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
E520-S2425 B-D	E520 DRIFT-S2425	6-46	06/29/04	10.598	10.598	2.512	2.126	18%	
E660-S2275-3 A-C	E660 DRIFT-S2275	6-47	06/29/04	6.384	12.524	3.272	3.049	7%	
E660-S2275 B-D	E660 DRIFT-S2275	6-47	06/29/04	10.505	10.505	2.068	1.929	7%	
E660-S2350-4 A-C	E660 DRIFT-S2350	6-48	06/29/04	7.226	17.512	3.963	3.309	20%	
E660-S2350 B-D	E660 DRIFT-S2350	6-48	12/02/03	9.780	9.780	2.151	2.100	2%	
E660-S2425-3 A-C	E660 DRIFT-S2425	6-49	06/29/04	8.244	17.484	4.296	3.844	12%	
E660-S2425 B-D	E660 DRIFT-S2425	6-49	06/29/04	11.141	11.141	2.323	2.096	11%	
E790-S2275-2 A-C	E790 DRIFT-S2275	6-50	06/07/04	1.301	12.051	2.687	2.441	10%	Reinstalled 12/03.
E790-S2275 B-D	E790 DRIFT-S2275	6-50	06/07/04	9.141	9.141	1.900	1.752	8%	
E790-S2350-3 A-C	E790 DRIFT-S2350	6-51	06/07/04	1.787	15.691	3.716	2.920	27%	Reinstalled 12/03.
E790-S2350 B-D	E790 DRIFT-S2350	6-51	06/07/04	10.059	10.059	2.271	1.985	14%	
E790-S2425-2 A-C	E790 DRIFT-S2425	6-52	06/07/04	1.749	13.892	3.655	2.786	31%	Reinstalled 12/03.
E790-S2425 B-D	E790 DRIFT-S2425	6-52	06/07/04	10.469	10.469	2.492	2.075	20%	
E920-S2275-2 A-C	E920 DRIFT-S2275	6-53	04/20/04	0.992	13.316	3.406	2.800	22%	Reinstalled 1/04.
E920-S2275 B-D	E920 DRIFT-S2275	6-53	04/20/04	10.107	10.107	2.264	1.998	13%	
E920-S2350-3 A-C	E920 DRIFT-S2350	6-54	04/20/04	1.068	17.811	3.644	3.195	14%	Reinstalled 1/04.
E920-S2350 B-D	E920 DRIFT-S2350	6-54	04/20/04	10.588	10.588	2.377	2.083	14%	
E920-S2425-2 A-C	E920 DRIFT-S2425	6-55	04/20/04	1.117	14.355	3.784	3.102	22%	Reinstalled 1/04.
E920-S2425 B-D	E920 DRIFT-S2425	6-55	04/20/04	9.790	9.790	2.252	1.887	19%	
E1050-S2275 A-C	E1050 DRIFT-S2275	6-56	09/23/03	10.713	10.713	2.557	2.505	2%	
E1050-S2275 B-D	E1050 DRIFT-S2275	6-56	09/23/03	7.713	7.713	1.572	1.744	-10%	
E1050-S2350-2 A-C	E1050 DRIFT-S2350	6-57	09/23/03	12.408	15.825	3.222	2.923	10%	
E1050-S2350 B-D	E1050 DRIFT-S2350	6-57	10/22/03	8.092	8.092	2.256	1.785	26%	
E1050-S2425-2 A-C	E1050 DRIFT-S2425	6-58	01/22/04	0.883	11.594	N/A	2.449	N/A	Reinstalled 10/03.
E1050-S2425 B-D	E1050 DRIFT-S2425	6-58	01/22/04	8.866	8.866	2.509	1.811	39%	
E1190-S2350-3 A-C	E1190 DRIFT-S2350	6-59	08/26/03	10.618	14.041	2.987	2.872	4%	
E1190-S2350 B-D	E1190 DRIFT-S2350	6-59	08/26/03	7.511	7.511	1.304	1.654	-21%	
E1190-S2425-2 A-C	E1190 DRIFT-S2425	6-60	08/26/03	10.419	11.548	2.922	2.788	5%	
E1190-S2425 B-D	E1190 DRIFT-S2425	6-60	08/26/03	7.902	7.902	1.618	1.725	-6%	

<sup>A</sup> NA Indicates insufficient data to compare annualized rates.




Figure 6-16 Extensometer 51X-GE-00341  
Room 1, Panel 2 – Room Center – Roof




Figure 6-17 Extensometer 51X-GE-00342  
Room 2, Panel 2 – Room Center – Roof




Figure 6-18 Extensometer 51X-GE-00343  
Room 3, Panel 2 – Room Center – Roof




Figure 6-19 Extensometer 51X-GE-00344  
Room 4, Panel 2 – Room Center – Roof




Figure 6-20 Extensometer 51X-GE-00345  
Room 5, Panel 2 – Room Center – Roof







Figure 6-21 Extensometer 51X-GE-00346  
Room 6, Panel 2 – Room Center – Roof




**Figure 6-22 Extensometer 51X-GE-00347  
Room 7, Panel 2 – Room Center – Roof**



**Figure 6-23 Extensometer 51X-GE-00348  
S2180 Drift at E725 – Roof**



**Figure 6-24 Extensometer 51X-GE-00351  
S2180 Drift at E1120 – Roof**



**Figure 6-25 Extensometer 51X-GE-00350  
S2520 Drift at E735 – Roof**




Figure 6-26 Extensometer 51X-GE-00349  
S2520 Drift at E1120 – Roof







Figure 6-27 Convergence Point Array  
S2180 Drift at E410 – All Chords




**Figure 6-28 Convergence Point Array  
S2180 Drift at E520 Drift Intersection (Room 1, Panel 2) – Roof to Floor**




**Figure 6-29 Convergence Point Array  
S2180 Drift at E586 – All Chords**




**Figure 6-30 Convergence Point Array  
S2180 Drift at E660 Drift Intersection (Room 2, Panel 2) – Roof to Floor**




**Figure 6-31 Convergence Point Array  
S2180 Drift at E790 Drift Intersection (Room 3, Panel 2) – Roof to Floor**




**Figure 6-32 Convergence Point Array  
S2180 Drift at E920 Drift Intersection (Room 4, Panel 2) – Roof to Floor**




**Figure 6-33 Convergence Point Array  
S2180 Drift at E986 – All Chords**




**Figure 6-34 Convergence Point Array  
S2180 Drift at E1050 Drift Intersection (Room 5, Panel 2) – Roof to Floor**




**Figure 6-35 Convergence Point Array  
S2520 Drift at E410 – All Chords**




**Figure 6-36 Convergence Point Array  
S2520 Drift at E520 Drift Intersection (Room 1, Panel 2) – Roof to Floor**




**Figure 6-37 Convergence Point Array  
S2520 Drift at E586 – All Chords**




**Figure 6-38 Convergence Point Array  
S2520 Drift at E660 Drift Intersection (Room 2, Panel 2) – Roof to Floor**



**Figure 6-39 Convergence Point Array  
S2520 Drift at E790 Drift Intersection (Room 3, Panel 2) – Roof to Floor**



**Figure 6-40 Convergence Point Array  
S2520 Drift at E920 Drift Intersection (Room 4, Panel 2) – Roof to Floor**



**Figure 6-41 Convergence Point Array  
S2520 Drift at E985 – All Chords**




Figure 6-42 Convergence Point Array  
S2520 Drift at E1050 Drift Intersection (Room 5, Panel 2) – Roof to Floor




Figure 6-43 Convergence Point Array  
S2520 Drift at E1190 Drift Intersection (Room 6, Panel 2) – Roof to Floor




Figure 6-44 Convergence Point Array  
Room 1, Panel 2 at S2275 – All Chords







Figure 6-45 Convergence Point Array  
Room 1, Panel 2 at S2350 – Room Center – All Chords




**Figure 6-46 Convergence Point Array  
Room 1, Panel 2 at S2425 – All Chords**



**Figure 6-47 Convergence Point Array  
Room 2, Panel 2 at S2275 – All Chords**



**Figure 6-48 Convergence Point Array  
Room 2, Panel 2 at S2350 – Room Center – All Chords**



**Figure 6-49 Convergence Point Array  
Room 2, Panel 2 at S2425 – All Chords**




Figure 6-50 Convergence Point Array  
Room 3, Panel 2 at S2275 – All Chords




Figure 6-51 Convergence Point Array  
Room 3, Panel 2 at S2350 – Room Center – All Chords




Figure 6-52 Convergence Point Array  
Room 3, Panel 2 at S2425 – All Chords







Figure 6-53 Convergence Point Array  
Room 4, Panel 2 at S2275 – All Chords




**Figure 6-54 Convergence Point Array  
Room 4, Panel 2 at S2350 – Room Center – All Chords**




**Figure 6-55 Convergence Point Array  
Room 4, Panel 2 at S2425 – All Chords**




**Figure 6-56 Convergence Point Array  
Room 5, Panel 2 at S2275 – All Chords**




**Figure 6-57 Convergence Point Array  
Room 5, Panel 2 at S2350 – Room Center – All Chords**



**Figure 6-58 Convergence Point Array  
Room 5, Panel 2 at S2425 – All Chords**



**Figure 6-59 Convergence Point Array  
Room 6, Panel 2 at S2350 – Room Center – All Chords**



**Figure 6-60 Convergence Point Array  
 Room 6, Panel 2 at S2425 – All Chords**

**Table 6-3**  
**Panel 3 Data Analysis**

**EXTENSOMETERS**

Field Tag	Location	Figure Number	Date of Last Reading	Collar Displacement Relative to Deepest Anchor (inches)	Displacement Rate 2003 to 2004 in/year	Displacement Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
51X-GE-00354	PANEL 3 ROOM 1	CENTER ROOF	6-61	08/07/03	0.543	3.908	N/A	N/A
51X-GE-00354-2	PANEL 3 ROOM 1	CENTER ROOF	6-62	06/28/04	2.990	3.409	N/A	N/A
51X-GE-00358	PANEL 3 ROOM 2	CENTER ROOF	6-63	06/28/04	1.137	2.315	N/A	N/A
51X-GE-00359	PANEL 3 ROOM 3	CENTER ROOF	6-64	06/28/04	2.090	4.255	N/A	N/A
51X-GE-00360	PANEL 3 ROOM 4	CENTER ROOF	6-65	06/28/04	1.224	2.709	N/A	N/A
51X-GE-00362	PANEL 3 ROOM 5	CENTER ROOF	6-66	06/28/04	1.359	3.115	N/A	N/A
51X-GE-00363	PANEL 3 ROOM 6	CENTER ROOF	6-67	06/28/04	2.262	5.225	N/A	N/A
51X-GE-00366	PANEL 3 ROOM 7	CENTER ROOF	6-68	06/28/04	0.674	2.121	N/A	N/A

<sup>A</sup>NA Indicates insufficient data to compare annualized rates.

**ROCKBOLT LOAD CELLS**

Field Tag	Location	Figure Number	Date of Initial Reading	Date of Last Reading	Load (kips)	Comments
51X-WG-00289	S2750 DRIFT-E950	6-69	02/09/04	06/28/04	17.050	
51X-WG-00290	S2750 DRIFT-E950	6-69	02/09/04	06/28/04	20.400	
51X-WG-00291	S2750 DRIFT-E950	6-69	02/09/04	06/28/04	19.650	
51X-WG-00292	S2750 DRIFT-E1050	6-69	02/09/04	06/28/04	19.700	
51X-WG-00297	S2750 DRIFT-E958	6-69	06/22/04	06/28/04	4.350	
51X-WG-00298	S2750 DRIFT-E1020	6-69	02/09/04	06/28/04	17.850	
51X-WG-00299	S2750 DRIFT-E980	6-69	02/09/04	06/28/04	19.350	

**Table 6-3 (Continued)**  
**Panel 3 Data Analysis**

**CONVERGENCE POINTS**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
S2750-E410 A-C	S2750 DRIFT-E410	6-70	05/20/04	2.450	2.450	2.765	N/A	N/A	
S2750-E410 B-D	S2750 DRIFT-E410	6-70	05/20/04	2.226	2.226	2.510	N/A	N/A	
S2750-E520-2 A-C	S2750 DRIFT-E520	6-71	06/28/04	0.102	2.960	N/A	N/A	N/A	
S2750-E586-2 A-C	S2750 DRIFT-E586	6-72	06/28/04	0.115	2.245	N/A	N/A	N/A	
S2750-E660-2 A-C	S2750 DRIFT-E660	6-73	06/28/04	0.092	1.784	N/A	N/A	N/A	
S2750-E790-2 A-C	S2750 DRIFT-E790	6-74	06/28/04	0.112	2.732	N/A	N/A	N/A	
S2750-E920-2 A-C	S2750 DRIFT-E920	6-75	06/28/04	0.104	3.270	N/A	N/A	N/A	
S2750-E986-2 A-C	S2750 DRIFT-E986	6-76	06/28/04	0.082	3.347	N/A	N/A	N/A	
S2750-E1050-2 A-C	S2750 DRIFT-E1050	6-77	06/28/04	0.116	3.765	N/A	N/A	N/A	
S2750-E1190-3 A-C	S2750 DRIFT-E1190	6-78	06/28/04	0.118	2.200	N/A	N/A	N/A	
S2750-E1255-2 A-C	S2750 DRIFT-E1255	6-79	06/28/04	0.087	2.505	N/A	N/A	N/A	
S2750-E1320-2 A-C	S2750 DRIFT-E1320	6-80	06/28/04	0.079	1.905	N/A	N/A	N/A	
S3080-E410 A-C	S3080 DRIFT-E410	6-81	06/02/04	2.538	2.538	2.677	N/A	N/A	
S3080-E410 B-D	S3080 DRIFT-E410	6-81	06/28/04	2.600	2.600	2.557	N/A	N/A	
S3080-E520-2 A-C	S3080 DRIFT-E520	6-82	06/28/04	0.089	3.343	N/A	N/A	N/A	
S3080-E586-2 A-C	S3080 DRIFT-E586	6-83	06/28/04	0.483	3.868	9.253	N/A	N/A	
S3080-E586 B-D	S3080 DRIFT-E586	6-83	06/28/04	0.164	0.164	2.983	N/A	N/A	
S3080-E660-2 A-C	S3080 DRIFT-E660	6-84	06/28/04	0.208	2.327	6.331	N/A	N/A	
S3080-E790-2 A-C	S3080 DRIFT-E790	6-85	06/28/04	0.248	3.130	6.514	N/A	N/A	
S3080-E920-2 A-C	S3080 DRIFT-E920	6-86	06/28/04	0.166	4.807	N/A	N/A	N/A	
S3080-E1050-2 A-C	S3080 DRIFT-E1050	6-87	06/28/04	0.291	2.397	10.410	N/A	N/A	
S3080-E1190 A-C	S3080 DRIFT-E1190	6-88	05/03/04	2.363	2.363	7.251	N/A	N/A	
S3080-E1255-2 A-C	S3080 DRIFT-E1255	6-89	06/28/04	0.212	3.234	5.418	N/A	N/A	

<sup>A</sup> NA Indicates insufficient data to compare annualized rates.

**Table 6-3 (Continued)**  
**Panel 3 Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
S3080-E1255 B-D	S3080 DRIFT-E1255	6-89	06/28/04	2.078	2.078	5.135	N/A	N/A	
S3080-E1320-2 A-C	S3080 DRIFT-E1320	6-90	06/28/04	0.267	2.031	4.917	N/A	N/A	
E520-S2833-2 A-C	E520 DRIFT-S2833	6-91	06/28/04	0.114	5.071	3.196	N/A	N/A	
E520-S2833 B-D	E520 DRIFT-S2833	6-91	06/28/04	3.926	3.926	3.916	N/A	N/A	
E520-S2916-2 A-C	E520 DRIFT-S2916	6-92	06/28/04	0.221	6.904	8.857	N/A	N/A	
E520-S2916 B-D	E520 DRIFT-S2916	6-92	06/28/04	3.870	3.870	3.863	N/A	N/A	
E520-S2998-2 A-C	E520 DRIFT-S2998	6-93	06/28/04	0.125	7.251	4.474	N/A	N/A	
E520-S2998 B-D	E520 DRIFT-S2998	6-93	06/28/04	0.820	0.820	3.757	N/A	N/A	
E660-S2833-2 A-C	E660 DRIFT-S2833	6-94	06/28/04	1.350	4.672	6.616	N/A	N/A	
E660-S2916-2 A-C	E660 DRIFT-S2916	6-95	06/28/04	1.164	4.460	5.630	N/A	N/A	
E660-S2916 B-D	E660 DRIFT-S2916	6-95	06/28/04	0.942	0.942	4.086	N/A	N/A	
E660-S2998-2 A-C	E660 DRIFT-S2998	6-96	06/28/04	1.572	5.080	7.712	N/A	N/A	
E660-S2998 B-D	E660 DRIFT-S2998	6-96	06/22/04	0.921	0.921	4.600	N/A	N/A	
E790-S2833-2 A-C	E790 DRIFT-S2833	6-97	06/28/04	1.350	5.708	6.590	N/A	N/A	
E790-S2833 B-D	E790 DRIFT-S2833	6-97	06/28/04	1.138	1.138	5.244	N/A	N/A	
E790-S2916-2 A-E	E790 DRIFT-S2916	6-98	06/28/04	1.711	6.749	8.448	N/A	N/A	
E790-S2916 B-D	E790 DRIFT-S2916	6-98	03/16/04	4.065	4.065	6.976	N/A	N/A	
E790-S2916 F-H	E790 DRIFT-S2916	6-98	03/16/04	3.498	3.498	5.748	N/A	N/A	
E790-S2916 C-G	E790 DRIFT-S2916	6-98	06/15/04	2.302	2.302	8.250	N/A	N/A	
E790-S2998-2 A-C	E790 DRIFT-S2998	6-99	06/28/04	1.258	4.667	6.147	N/A	N/A	
E790-S2998 B-D	E790 DRIFT-S2998	6-99	06/02/04	2.183	2.183	8.962	N/A	N/A	
E920-S2833-2 A-C	E920 DRIFT-S2833	6-100	06/28/04	1.205	5.812	5.809	N/A	N/A	
E920-S2833 B-D	E920 DRIFT-S2833	6-100	06/28/04	1.155	1.155	5.779	N/A	N/A	
E920-S2916-2 A-C	E920 DRIFT-S2916	6-101	06/28/04	1.361	6.206	7.211	N/A	N/A	

<sup>A</sup> NA Indicates insufficient data to compare annualized rates.

**Table 6-3 (Continued)**  
**Panel 3 Data Analysis**

**CONVERGENCE POINTS (Continued)**

Field Tag	Location	Figure Number	Last Reading 2003 to 2004		Cumulative Displacement Inches	Closure Rate 2003 to 2004 in/year	Closure Rate 2002 to 2003 in/year	Rate Change Percent <sup>A</sup>	Comments
			Date	Inches					
E920-S2916 B-D	E920 DRIFT-S2916	6-101	06/15/04	1.055	1.055	6.746	N/A	N/A	
E920-S2998-2 A-C	E920 DRIFT-S2998	6-102	06/28/04	1.320	5.753	7.034	N/A	N/A	
E920-S2998 B-D	E920 DRIFT-S2998	6-102	06/15/04	1.023	1.023	6.485	N/A	N/A	
E1050-S2833 A-C	E1050 DRIFT-S2833	6-103	06/28/04	0.192	0.192	4.627	N/A	N/A	
E1050-S2833 B-D	E1050 DRIFT-S2833	6-103	06/28/04	1.908	1.908	5.947	N/A	N/A	
E1050-S2916-2 A-C	E1050 DRIFT-S2916	6-104	06/28/04	0.229	2.167	6.270	N/A	N/A	
E1050-S2916 B-D	E1050 DRIFT-S2916	6-104	06/28/04	2.040	2.040	6.375	N/A	N/A	
E1050-S2998 A-C	E1050 DRIFT-S2998	6-105	06/28/04	0.253	0.253	7.001	N/A	N/A	
E1050-S2998 B-D	E1050 DRIFT-S2998	6-105	06/28/04	2.251	2.251	7.036	N/A	N/A	
E1190-S2833 A-C	E1190 DRIFT-S2833	6-106	06/28/04	0.338	0.338	5.900	N/A	N/A	
E1190-S2833 B-D	E1190 DRIFT-S2833	6-106	06/28/04	2.258	2.258	5.630	N/A	N/A	
E1190-S2916-2 A-C	E1190 DRIFT-S2916	6-107	06/28/04	0.592	2.981	11.407	N/A	N/A	
E1190-S2916 B-D	E1190 DRIFT-S2916	6-107	06/28/04	2.294	2.294	5.744	N/A	N/A	
E1190-S2998 A-C	E1190 DRIFT-S2998	6-108	06/28/04	0.427	0.427	7.923	N/A	N/A	
E1190-S2998 B-D	E1190 DRIFT-S2998	6-108	06/28/04	2.431	2.431	6.086	N/A	N/A	
E1320-S2833 A-C	E1320 DRIFT-S2833	6-109	06/28/04	0.345	0.345	6.518	N/A	N/A	
E1320-S2833 B-D	E1320 DRIFT-S2833	6-109	06/28/04	2.011	2.011	7.931	N/A	N/A	
E1320-S2916-2 A-C	E1320 DRIFT-S2916	6-110	06/28/04	0.345	2.553	6.490	N/A	N/A	
E1320-S2916 B-D	E1320 DRIFT-E2916	6-110	06/28/04	2.056	2.056	5.108	N/A	N/A	
E1320-S2998 A-C	E1320 DRIFT-S2998	6-111	06/28/04	0.319	0.319	5.928	N/A	N/A	
E1320-S2998 B-D	E1320 DRIFT-S2998	6-111	06/28/04	2.036	2.036	5.045	N/A	N/A	

<sup>A</sup> NA Indicates insufficient data to compare annualized rates.




Figure 6-61 Extensometer 51X-GE-00354  
Room 1, Panel 3 – Room Center – Roof




Figure 6-62 Extensometer 51X-GE-00354-2  
Room 1, Panel 3 – Room Center – Roof




Figure 6-63 Extensometer 51X-GE-00358  
Room 2, Panel 3 – Room Center – Roof




Figure 6-64 Extensometer 51X-GE-00359  
Room 3, Panel 3 – Room Center – Roof




Figure 6-65 Extensometer 51X-GE-00360  
Room 4, Panel 3 – Room Center – Roof




Figure 6-66 Extensometer 51X-GE-00362  
Room 5, Panel 3 – Room Center – Roof




Figure 6-67 Extensometer 51X-GE-00363  
Room 6, Panel 3 – Room Center – Roof







Figure 6-68 Extensometer 51X-GE-00366  
Room 7, Panel 3 – Room Center – Roof




**Figure 6-69 Rock Bolt Load Cells  
S2750 Drift at E950/E1050 – Roof**




**Figure 6-70 Convergence Point Array  
S2750 Drift at E410 – All Chords**




**Figure 6-71 Convergence Point Array  
S2750 Drift at E520 Drift Intersection (Room 1, Panel 3) – Roof to Floor**




**Figure 6-72 Convergence Point Array  
S2750 Drift at E586 – Roof to Floor**




**Figure 6-73 Convergence Point Array  
S2750 Drift at E660 Drift Intersection (Room 2, Panel 3) – Roof to Floor**




**Figure 6-74 Convergence Point Array  
S2750 Drift at E790 Drift Intersection (Room 3, Panel 3) – Roof to Floor**




**Figure 6-75 Convergence Point Array  
S2750 Drift at E920 Drift Intersection (Room 4, Panel 3) – Roof to Floor**




**Figure 6-76 Convergence Point Array  
S2750 Drift at E986 – Roof to Floor**




**Figure 6-77 Convergence Point Array  
S2750 Drift at E1050 Drift Intersection (Room 5, Panel 3) – Roof to Floor**




**Figure 6-78 Convergence Point Array  
S2750 Drift at E1190 Drift Intersection (Room 6, Panel 3) – Roof to Floor**




**Figure 6-79 Convergence Point Array  
S2750 Drift at E1255 – Roof to Floor**




**Figure 6-80 Convergence Point Array  
S2750 Drift at E1320 Drift Intersection (Room 7, Panel 3) – Roof to Floor**




**Figure 6-81 Convergence Point Array  
S3080 Drift at E410 – All Chords**




**Figure 6-82 Convergence Point Array  
S3080 Drift at E520 Drift Intersection (Room 1, Panel 3) – Roof to Floor**




**Figure 6-83 Convergence Point Array  
S3080 Drift at E586 – All Chords**




**Figure 6-84 Convergence Point Array  
S3080 Drift at E660 Drift Intersection (Room 2, Panel 3) – Roof to Floor**




**Figure 6-85 Convergence Point Array  
S3080 Drift at E790 Drift Intersection (Room 3, Panel 3) – Roof to Floor**




**Figure 6-86 Convergence Point Array  
S3080 Drift at E920 Drift Intersection (Room 4, Panel 3) – Roof to Floor**




**Figure 6-87 Convergence Point Array  
S3080 Drift at E1050 Drift Intersection (Room 5, Panel 3) – Roof to Floor**



**Figure 6-88 Convergence Point Array  
S3080 Drift at E1190 Drift Intersection (Room 6, Panel 3) – Roof to Floor**



**Figure 6-89 Convergence Point Array  
S3080 Drift at E1255 – All Chords**



**Figure 6-90 Convergence Point Array  
S3080 Drift at E1320 Drift Intersection (Room 7, Panel 3) – Roof to Floor**




Figure 6-91 Convergence Point Array  
Room 1, Panel 3 at S2833 – All Chords




Figure 6-92 Convergence Point Array  
Room 1, Panel 3 at S2916 – Room Center – All Chords




Figure 6-93 Convergence Point Array  
Room 1, Panel 3 at S2998 – All Chords






Figure 6-94 Convergence Point Array  
Room 2, Panel 3 at S2833 – Roof to Floor



**Figure 6-95 Convergence Point Array**  
Room 2, Panel 3 at S2916 – Room Center – All Chords



**Figure 6-96 Convergence Point Array**  
Room 2, Panel 3 at S2998 – All Chords




Figure 6-97 Convergence Point Array  
Room 3, Panel 3 at S2833 – All Chords




Figure 6-98 Convergence Point Array  
Room 3, Panel 3 at S2916 – Room Center – All Chords




Figure 6-99 Convergence Point Array  
Room 3, Panel 3 at S2998 – All Chords







Figure 6-100 Convergence Point Array  
Room 4, Panel 3 at S2833 – All Chords




**Figure 6-101 Convergence Point Array  
Room 4, Panel 3 at S2916 – Room Center – All Chords**




**Figure 6-102 Convergence Point Array  
Room 4, Panel 3 at S2998 – All Chords**




**Figure 6-103 Convergence Point Array  
Room 5, Panel 3 at S2833 – All Chords**




**Figure 6-104 Convergence Point Array  
Room 5, Panel 3 at S2916 – Room Center – All Chords**




**Figure 6-105 Convergence Point Array  
Room 5, Panel 3 at S2998 – All Chords**




**Figure 6-106 Convergence Point Array  
Room 6, Panel 3 at s2833 – All Chords**




**Figure 6-107 Convergence Point Array  
Room 6, Panel 3 at S2916 – Room Center – All Chords**



**Figure 6-108 Convergence Point Array  
Room 6, Panel 3 at S2998 – All Chords**



**Figure 6-109 Convergence Point Array  
Room 7, Panel 3 at S2833 – All Chords**



**Figure 6-110 Convergence Point Array  
Room 7, Panel 3 at S2916 – Room Center – All Chords**




Figure 6-111 Convergence Point Array  
Room 7, Panel 3 at S2998 – All Chords

This Page Intentionally

Left Blank

## ***7.0 Geoscience Program Supporting Data***

---

This chapter presents supporting data acquired as part of the Geoscience Program. It includes observations of clay seam displacements and other features in vertical observation holes, and fracture maps of excavation surfaces.

### ***7.1 Borehole Inspections***

This section presents a summary of the clay seam displacements (offsets) and fracture densities measured in observation boreholes located through the WIPP underground facility. Relative lateral displacement of rock strata above and below a clay layer is measured as offset within a borehole. Fracture density is a calculated parameter based on the number of fractures (separations) and fracture zones observed in an observation borehole. Fracture density is equal to the number of fractures plus twice the number of fracture zones in a roof beam divided by the thickness of the beam (in feet). Table 7-1 presents the observed offset data for boreholes, the observed fractures and fracture zones, and the calculated fracture densities. Table 7-2 is a summary of new boreholes drilled during this reporting period.

### ***7.2 Fracture Mapping***

This section presents graphical results of the fracture mapping done in Panels 2 and 3 of the Waste Disposal Area. Figures 7-1 through 7-21 are plan view fracture maps for the roof in these panels.

**Table 7-1**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>Panel 3 Room 1</b>													
OH 401	S 2832 E 521	08/06/03	06/09/04	0	0	6.0	Offset	0.00	6.0	0.25	3.00	8	0.30
						6.0	Separation		6.0	0.25		N/A	N/A
OH 402	S 2910 E 520	08/06/03	06/09/04	4	0	7.3	Separation	0.55	7.3	0.13	3.00	N/A	N/A
						6.8	Rough spot		6.8	N/A		N/A	N/A
						6.1	Separation		6.1	0.13		N/A	N/A
						5.8	Separation		5.8	0.50		N/A	N/A
						5.5	Separation		5.5	0.13		N/A	N/A
						1.5	Separation		1.5	0.38		N/A	N/A
OH 402-1	S 2910 E 515	06/09/04	06/09/04	2	0	6.1	Separation	0.33	6.1	0.25	3.00	N/A	N/A
						1.6	Separation		1.6	0.25		N/A	N/A
						0.4	Separation		0.4	0.50		N/A	N/A
OH 402-2	S 2910 E 525	06/09/04	06/09/04	2	0	7.3	Separation	0.27	7.3	0.25	3.00	N/A	N/A
						6.0	Separation		6.0	0.25		N/A	N/A
						1.5	Separation		1.5	1.25		N/A	N/A
OH 403	S 2998 E 520	06/09/04	06/09/04	2	0	6.6	Separation	0.30	6.6	0.18	3.00	N/A	N/A
						6.0	Separation		6.0	0.25		N/A	N/A
						1.8	Separation		1.8	0.06		N/A	N/A
<b>Panel 3 Room 2</b>													
OH 404	S 2833 E 656	08/06/03	06/29/04			5.9	Offset		5.9	0.50	3.00	17	0.56
				1	0	5.9	Separation	0.17	5.9	0.25		N/A	N/A
						5.3	Separation		5.3	0.13		N/A	N/A
OH 405	S 2916 E 657	08/06/03	04/13/04	0	0	5.7	Offset	0.00	5.7	0.50	3.00	17	0.73
						5.7	Separation		5.7	0.25		N/A	N/A
OH 406	S 2998 E 656	08/06/03	06/29/04			9.0	Rough spot		9.0	N/A	3.00	N/A	N/A
				2	0	6.9	Separation	0.29	6.9	0.38		N/A	N/A
						6.4	Offset		6.4	0.38		13	0.42
						6.4	Separation		6.4	0.25		N/A	N/A
						2.0	Offset		2.0	0.13		4	0.14
						2.0	Separation		2.0	0.38		N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>Panel 3 Room 3</b>													
OH 407	S 2830 E 790	08/06/03	04/13/04	0	0	6.5 6.1 5.9 4.4	Separation Rough spot Rough spot Rough spot	0.00	6.5	0.13	3.00	N/A	N/A
OH 408	S 2910 E 790	08/06/03	04/13/04	2	0	6.8 5.8 5.7 5.7	Separation Separation Offset Separation	0.29	6.8 5.8 5.7 5.7	0.75 0.13 0.13 0.13	3.00	N/A	N/A
OH 409	S 2990 E 790	08/06/03	06/29/04			6.6 6.0 6.0	Hangup Offset Separation	0.00	6.6 6.0 6.0	0.00 0.13 0.13	3.00 4 N/A	N/A	N/A
<b>Panel 3 Room 4</b>													
OH 410	S 2835 E 924	09/04/03	04/13/04	2	0	6.5 6.4 6.1 6.1	Separation Separation Offset Separation	0.31	6.5 6.4 6.1 6.1	0.13 0.13 0.25 0.25	3.00	N/A	N/A
OH 411	S 2910 E 920	09/04/03	04/13/04	0	0	5.9 5.9	Offset Separation	0.00	5.9 5.9	0.25 0.50	3.00	8	0.41
OH 412	S 3014 E 923	09/04/03	06/29/04	0	0	6.0	Separation	0.00	6.0	0.25	3.00	N/A	N/A
<b>Panel 3 Room 5</b>													
OH 413	S 2830 E 1060	11/19/03	04/13/04	0	0	6.4 6.4 6.1	Offset Separation Rough spot	0.00	6.4 6.4 6.1	0.13 0.13 N/A	3.00	4	0.31
OH 414	S 2910 E 1060	11/05/03	04/13/04	1	0	7.5 6.3 6.3	Separation Offset Separation	0.13	7.5 6.3 6.3	0.13 0.13 0.13	3.00	N/A	N/A
OH 415	S 2990 E 1060	11/05/03	06/29/04			7.6 7.6 6.0 1.9	Offset Separation Separation Separation	0.26	7.6 7.6 6.0 1.9	0.13 0.38 0.13 0.13	3.00	4	0.19
<b>Panel 3 Room 6</b>													
OH 416	S 2830 E 1190	11/19/03	04/13/04	0	0	6.0	Separation	0.00	6.0	0.13	3.00	N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>Panel 3 Room 6 - Continued</b>													
OH 417	S 2910 E 1190	11/19/03	04/13/04	2	0	7.2	Separation	0.28	7.2	0.25	3.00	N/A	N/A
						6.3	Separation		6.3	0.13		N/A	N/A
						5.7	Rough spot		5.7	N/A		N/A	N/A
						1.5	Separation		1.5	0.13		N/A	N/A
OH 418	S 2990 E 1190	11/19/13	04/13/04			6.5	Hangup		6.5	0.00	3.00	N/A	N/A
						0	0	0.00	5.8	0.13		N/A	N/A
<b>Panel 3 Room 7</b>													
OH 419	S 2832 E 1320	12/18/03	04/13/04	0	0	6.4	Separation	0.00	6.4	0.13	3.00	N/A	N/A
OH 420	S 2922 E 1321	12/18/03	04/13/04	0	0	6.6	Separation	0.00	6.6	0.13	3.00	N/A	N/A
OH 421	S 2998 E 1321	12/18/03	06/29/04	0	0	5.0	Separation	0.00	5.0	0.13	3.00	N/A	N/A
<b>Panel 3 South 2750</b>													
OH 438	S 2748 E 526	08/08/03	05/26/04			6.5	Offset		6.5	1.00	3.00	33	1.25
				4	0	6.5	Separation	0.62	6.5	0.13		N/A	N/A
						5.4	Offset		5.4	0.75		25	0.94
						5.4	Separation		5.4	0.25		N/A	N/A
						5.3	Separation		5.3	0.25		N/A	N/A
						5.0	Offset		5.0	0.13		4	0.16
						5.0	Separation		5.0	0.25		N/A	N/A
						0.8	Separation		0.8	0.38		N/A	N/A
OH 428	S 2748 E 654	08/06/03	05/26/04			6.0	Offset		6.0	1.13	3.00	38	1.40
				2	0	6.0	Separation	0.33	6.0	0.25		N/A	N/A
						5.9	Offset		5.9	0.75		25	0.93
						5.9	Separation		5.9	0.25		N/A	N/A
						5.6	Offset		5.6	0.13		4	0.16
						5.6	Separation		5.6	0.25		N/A	N/A
OH 439	S 2750 E 789	08/08/03	05/26/04			6.7	Separation		6.7	0.13	3.00	N/A	N/A
				3	0	6.3	Separation	0.48	6.3	1.00		N/A	N/A
						6.1	Offset		6.1	1.25		42	1.56
						6.1	Separation		6.1	0.25		N/A	N/A
						5.8	Separation		5.8	0.25		N/A	N/A
						1.5	Offset		1.5	0.13		4	0.16
						1.5	Separation		1.5	1.00		N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>Panel 3 South 2750 - Continued</b>													
OH 429	S 2748 E 924	08/09/03	05/26/04	5	0	7.5 6.5 6.5 5.9 5.9 5.3 2.4 1.0	Separation Offset Separation Offset Separation Separation Separation Separation	0.67	7.5 6.5 6.5 5.9 5.9 5.3 2.4 1.0	1.00 0.13 0.25 0.13 0.38 0.13 0.50 0.13	3.00	N/A	N/A
OH 497	S 2740 E 977	02/05/04	02/05/04	1	0	1.6 1.4	Separation Separation	0.63	1.6 1.4	0.18 2.00	3.00	N/A	N/A
OH 496	S 2750 E 977	02/05/04	05/26/04	4	0	7.1 6.9 6.8 6.5 1.1	Separation Separation Separation Separation Separation	0.56	7.1 6.9 6.8 6.5 1.1	0.50 0.13 0.25 0.25 7.00	3.00	N/A	N/A
OH 494	S 2750 E 990	01/13/04	05/26/04	5	0	7.5 6.4 6.3 5.9 5.9 1.4 0.9	Separation Separation Separation Offset Separation Separation Separation	0.67	7.5 6.4 6.3 5.9 5.9 1.4 0.9	0.75 0.13 0.13 0.13 0.13 2.00 0.25	3.00	N/A	N/A
OH 430	S 2746 E 1060	09/25/03	05/26/04	3	0	7.4 6.4 5.8 5.8 1.5	Separation Separation Offset Separation Separation	0.41	7.4 6.4 5.8 5.8 1.5	0.13 0.13 1.00 0.50 0.13	3.00	N/A	N/A
OH 495	S 2748 E 1119	01/13/04	05/26/04			6.8 6.1 1    0    6.1 0.6	Hangup Offset Separation Separation	0.16	6.8 6.1 6.1 0.6	0.00 0.25 0.50 0.25	3.00	N/A	N/A
OH 480	S 2746 E 1195	09/25/03	05/26/04	1	0	6.6 6.0 6.0	Separation Offset Separation	0.15	6.6 6.0 6.0	0.25 1.00 0.50	3.00	N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>Panel 3 South 2750 - Continued</b>													
OH 481	S 2747 E 1316	09/25/03	05/26/04	0	0	5.7 5.7	Offset Separation	0.00	5.7 5.7	0.75 0.13	3.00	25 N/A	1.12 N/A
<b>Panel 3 South 3080</b>													
OH 440	S 3082 E 523	08/08/03	04/13/04			7.3 6.0 3    0    6.0 5.9 5.9 5.7 5.7 0.5	Hangup Offset Separation Offset Separation Offset Separation Separation	0.50	7.3 6.0 6.0 5.9 5.9 5.7 5.7 0.5	0.00 0.50 0.75 1.25 0.25 1.00 0.13 0.38	3.00	N/A	N/A
OH 431	S 3082 E 654	08/06/03	04/13/04		1    0	6.2 6.2 5.3	Offset Separation Separation	0.16	6.2 6.2 5.3	0.50 0.38 0.13	3.00	17 N/A N/A	0.73 N/A N/A
OH 461	S 3082 E 789	09/03/03	04/13/04	3	0	7.2 6.3 5.8 5.8 2.3	Separation Separation Offset Separation Separation	0.42	7.2 6.3 5.8 5.8 2.3	1.00 0.13 0.13 0.07 0.13	3.00	N/A	N/A
OH 432	S 3081 E 921	09/03/03	04/22/04		4    0	11.3 7.6 6.1 4.0 2.7 1.7	Rough spot Separation Separation Separation Separation Separation	0.53	11.3 7.6 6.1 4.0 2.7 1.7	N/A 1.00 0.50 0.13 0.25 1.00	3.00	N/A	N/A
OH 504	S 3080 E 955	04/22/04	04/22/04	1	0	6.4 1.4 1.4	Separation Offset Separation	0.16	6.4 1.4 1.4	0.50 0.25 2.75	3.00	N/A	N/A
OH 466	S 3080 E 981	09/08/03	05/26/04		3    0	6.6 6.4 6.0 6.0 5.8 1.6 1.6	Hangup Separation Offset Separation Separation Offset Separation	0.47	6.6 6.4 6.0 6.0 5.8 1.6 1.6	0.00 0.25 0.25 0.50 0.13 0.25 1.50	3.00	N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>Panel 3 South 3080 - Continued</b>													
OH 505	S 3080 E 1005	04/22/04	04/22/04	1	0	5.8 1.6	Separation Separation	0.17	5.8 1.6	0.50 1.50	3.00	N/A	N/A
OH 506	S 3080 E 1055	04/22/04	04/22/04	1	0	6.3 1.5	Separation Separation	0.16	6.3 1.5	0.38 1.50	3.00	N/A	N/A
OH 467	S 3082 E 1055	09/08/03	05/26/04			7.6 5 7.6 6.1 6.0 6.0 5.6 5.1 5.1 1.5 1.0	Offset Separation Separation Offset Separation Hangup Offset Separation Separation Separation	0.66	7.6 7.6 6.1 6.0 6.0 5.6 5.1 5.1 1.5 1.0	0.25 0.75 0.13 0.50 0.13 0.00 0.13 0.13 1.25 0.13	3.00	8	0.35
OH 433	S 3079 E 1102	09/08/03	05/26/04	1	0	6.1 5.8 5.8 1.5	Separation Offset Separation Hangup	0.16	6.1 5.8 5.8 1.5	0.13 0.50 0.13 0.00	3.00	N/A	N/A
OH 426	S 3081 E 1320	12/18/03	05/26/04	0	0	5.7 5.7	Offset Separation	0.00	5.7 5.7	0.13 0.25	3.00	4	0.29
<b>Panel 2 Room 1</b>													
OH 359	S 2271 E 523	07/24/00	05/20/04			7.5 6.4 6 0 0	Top of Anhydrite Hangup Hangup Separation	7.5 6.4 6 0.00	N/A 6.4 6 1.7	3.00	N/A	N/A	
OH 360	S 2350 E 523	07/24/00	05/20/04		1	0	7.7 7.5 6.4	Top of Anhydrite Separation Separation	7.7 7.5 6.4	N/A 0.50 0.50	3.00	N/A	N/A
OH 361	S 2422 E 523	07/24/00	05/20/04		1	0	7.5 7.3 6.9 5.0 2.6	Top of Anhydrite Separation Hangup Separation Hangup	7.5 7.3 6.9 5.0 2.6	N/A 0.75 0.00 0.13 0.00	3.00	N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>Panel 2 Room 2</b>													
OH 362	S 2275 E 655	07/24/00	05/20/04			7.9	Top of Anhydrite		7.9	N/A	3.00	N/A	N/A
						7.0	Hangup		7.0	0.00		N/A	N/A
						6.7	Hangup		6.7	0.00		N/A	N/A
				0	0	6.6	Separation	0.00	6.6	0.25		N/A	N/A
						6.5	Hangup		6.5	0.00		N/A	N/A
						5.9	Hangup		5.9	0.00		N/A	N/A
						5.5	Hangup		5.5	0.00		N/A	N/A
OH 363	S 2347 E 656	07/24/00	05/20/04			8.3	Top of Anhydrite		8.3	N/A	3.00	N/A	N/A
						7.6	Hangup		7.6	0.00		N/A	N/A
						6.6	Hangup		6.6	0.00		N/A	N/A
						5.9	Hangup		5.9	0.00		N/A	N/A
						4.2	Hangup		4.2	0.00		N/A	N/A
						3.4	Hangup		3.4	0.00		N/A	N/A
OH 364	S 2422 E 656	07/24/00	05/20/04			7.1	Top of Anhydrite		7.1	N/A	3.00	N/A	N/A
				2	0	7.0	Separation	0.29	7.0	0.50		N/A	N/A
						6.5	Separation		6.5	0.13		N/A	N/A
						6.0	Separation		6.0	0.13		N/A	N/A
						4.9	Hangup		4.9	0.00		N/A	N/A
<b>Panel 2 Room 3</b>													
OH 365	S 2277 E 789	07/24/00	05/20/04			7.2	Hangup		7.2	0.00	3.00	N/A	N/A
				3	0	7.0	Separation	0.43	7.0	0.13		N/A	N/A
						6.7	Rough spot		6.7	N/A		N/A	N/A
						6.6	Separation		6.6	0.25		N/A	N/A
						6.4	Hangup		6.4	0.00		N/A	N/A
						5.5	Separation		5.5	0.13		N/A	N/A
						2.4	Separation		2.4	0.06		N/A	N/A
OH 366	S 2351 E 790	07/24/00	05/20/04			7.2	Top of Anhydrite		7.2	N/A	3.00	N/A	N/A
				2	0	7.1	Separation	0.28	7.1	0.38		N/A	N/A
						6.9	Separation		6.9	0.38		N/A	N/A
						6.0	Separation		6.0	0.38		N/A	N/A
						5.6	Hangup		5.6	0.00		N/A	N/A
						5.5	Hangup		5.5	0.00		N/A	N/A
						5.4	Hangup		5.4	0.00		N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>Panel 2 Room 3 - Continued</b>													
OH 367	S 2421 E 789	07/24/00	05/20/04			7.0	Top of Anhydrite Separation Separation Hangup Separation Separation	0.45	7.0 6.7 6.4 5.9 5.6 5.4	0.25 0.25 0.00 0.13 0.06	3.00	N/A N/A N/A N/A N/A N/A	N/A N/A
				3	0	6.7							
						6.4							
						5.9							
						5.6							
						5.4							
<b>Panel 2 Room 4</b>													
OH 368	S 2270 E 922	07/24/00	01/06/04			14.2	Hangup Rough spot		14.2 5.8	0.00 N/A	3.00	N/A N/A	N/A N/A
						14.2							
						5.8							
OH 369	S 2344 E 922	07/24/00	01/06/04			6.4	Hangup Separation	0.00	6.4 6.0	0.00 0.13	3.00	N/A N/A	N/A N/A
						6.4							
						0							
						0							
OH 370	S 2426 E 922	07/24/00	01/06/04			14.1	Hangup Offset Hangup Separation	0.14	14.1 7.3 5.3 0.6	0.00 0.25 0.00 0.50	3.00	N/A N/A N/A N/A	N/A N/A 0.07
						14.1							
						7.3							
						5.3							
						0.6							
<b>Panel 2 Room 5</b>													
OH 371	S 2276 E 1054	01/17/01	11/04/03	3	0	6.7	Separation Separation Separation Separation	0.45	6.7 5.6 5.2 5.0	0.13 0.63 0.63 0.63	3.00	N/A N/A N/A N/A	N/A N/A
						6.7							
						5.6							
						5.2							
						5.0							
OH 372	S 2351 E 1055	01/17/01	11/04/03	1	0	6.3	Separation Offset Separation	0.16	6.3 5.6 5.6	0.25 0.25 0.06	3.00	N/A N/A	N/A N/A 0.09
						6.3							
						5.6							
						5.6							
OH 373	S 2426 E 1055	01/17/01	01/06/04	0	0	6.7	Hangup	0.00	6.7	0.00	3.00	N/A N/A	N/A N/A
<b>Panel 2 South 2180</b>													
OH 380	S 2180 E 726	01/18/01	05/20/04	4	0	6.0	Separation Separation Separation Separation Separation	0.67	6.0 5.9 5.5 3.0 1.5	0.13 0.13 0.13 0.13 0.13	3.00	N/A N/A N/A N/A N/A	N/A N/A
						6.0							
						5.9							
						5.5							
						3.0							
						1.5							
OH 381	S 2181 E 921	01/17/01	01/06/04			14.3	Offset Offset Separation Hangup	0.00	14.3 7.4 7.4 6.0	3.00 2.50 0.25 0.00	3.00 100 83 N/A	1.01 0.84 N/A N/A	N/A N/A
						14.3							
						7.4							
						7.4							
						6.0							

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>Panel 2 South 2520</b>													
OH 383	S 2515 E 718	01/11/01	05/20/04			6.5 6.4 2 0 6.4 5.4 5.4 3.8 2.8	Top of Anhydrite Offset Separation Offset Separation Rough spot Separation		6.5 6.4 0.31	N/A 1.00 0.50 0.25 0.25 N/A N/A	3.00	N/A	N/A
												33	0.30
												N/A	N/A
												8	0.07
												N/A	N/A
												N/A	N/A
												N/A	N/A
OH 384	S 2517 E 921	01/11/01	01/06/04		1 0	13.0 13.0 6.4 5.7 5.1	Offset Separation Separation Hangup Hangup	0.08	13.0 13.0 6.4 5.7 5.1	1.25 0.50 0.13 0.00 0.00	3.00	42	0.42
												N/A	N/A
												N/A	N/A
												N/A	N/A
<b>Panel 1 Closure - South 1950 &amp; South 1600</b>													
OH391	S 1951 E 456	07/22/03	01/22/04	1 0		6.3 4.1 4.1	Separation Offset Separation	0.16	6.3 4.1 4.1	0.50 0.50 4.00	3.00	N/A	N/A
												17	0.99
												N/A	N/A
OH392	S 1953 E 448	07/22/03	01/22/04	0 0		3.7 3.7	Offset Separation	0.00	3.7 3.7	0.75 4.00	3.00	25	1.49
												N/A	N/A
OH393	S 1614 E 451	07/22/03	01/22/04			10.0	Rough spot		10.0	N/A	3.00	N/A	N/A
OH394	S 1613 E 434	07/22/03	01/22/04			---	No features	N/A	---	---	3.00	N/A	N/A
<b>East 300</b>													
OH422	S 2825 E 300	08/06/03	08/06/03	0 0		6.1 6.1	Offset Separation	0.00	6.1 6.1	0.06 0.06	3.00	2	N/A
												N/A	N/A
OH423	S 2890 E 300	08/06/03	08/06/03	0 0		5.7	Hangup	0.00	5.7	0.00	3.00	N/A	N/A
OH424	S 2950 E 300	08/06/03	08/06/03	0 0		5.4	Separation	0.00	5.4	0.06	3.00	N/A	N/A
OH425	S 3020 E 300	08/06/03	08/06/03	1 0		5.7 0.3	Separation Separation	0.18	5.7 0.3	0.25 0.13	3.00	N/A	N/A
												N/A	N/A
OH453	S 3310 E 300	08/18/03	08/18/03		0 0	6.0 6.0 2.0	Offset Separation Rough spot	0.00	6.0 6.0 2.0	0.13 0.18 N/A	3.00	4	N/A
												N/A	N/A
OH457	S 3260 E 300	08/28/03	08/28/03		0 0	9.3 5.8 0.6	Hangup Separation/clay Hangup	0.00	9.3 5.8 0.6	0.00 0.50 0.00	3.00	N/A	N/A
												N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density =  $(Fr + 2 FZ) / \text{Beam Height}$

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>East 300 - Continued</b>													
OH458	S 3200 E 300	08/28/03	08/28/03	1	0	5.9 5.7 3.4	Separation Separation Hangup	0.17	5.9 5.7 3.4	0.25 0.38 0.00	3.00	N/A	N/A
OH459	S 3140 E 300	08/28/03	08/29/03	0	0	5.6	Separation	0.00	5.6	0.25	3.00	N/A	N/A
<b>East 140</b>													
OH498	S 415 E 140	02/17/04	02/17/04	3	1	5.5 4.8 4.0 3.6 2.7 1.5	Clay G Separation Hangup FZ Top FZ Bottom Hangup	0.91	5.5 4.8 4.0 3.6 2.7 1.5	0.50 2.00 0.00 9.00 N/A 0.00	3.00	N/A	N/A
OH499	S 510 E 140	02/17/04	02/17/04	1	0	5.5 4.3	Clay G Separation	0.18	5.5 4.3	3.00 3.00	3.00	N/A	N/A
OH482	S 1782 E 140	10/08/03	10/14/03	5	1	15.6 7.3 7.0 6.2 5.7 2.7 2.1 1.6 1.0	Clay I? FZ Top FZ Bottom FZ Top FZ Bottom Separation Separation Separation Separation	0.00	15.6 7.3 7.0 6.2 5.7 2.7 2.1 1.6 1.0	2.50	3.00	N/A	N/A
OH144-1	S 1780 E 140	10/31/01	05/25/04			6.8 5.9 2.8 1.8 1.3	Offset Separation Separation Separation Separation	0.59	6.8 5.9 2.8 1.8 1.3	3.00 1.50 2.00 0.75 1.00	3.00	100	1.17
OH146-2	S 1832 E 140	06/15/04	06/15/04			7.4 5.9 5.7 4.4 3.5 2.2 1.3 0.7	Separation Separation Separation Separation Separation Separation Separation Separation	0.95	7.4 5.9 5.7 4.4 3.5 2.2 1.3 0.7	0.38 2.00 0.50 4.00 1.00 2.00 1.00 0.38	3.00	N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)	
<b>East 140 - Continued</b>														
OH147-2	S 1832 E 140	06/15/04	06/15/04	4	0	6.3 3.7 3.3 2.9 2.3 1.3	Separation Hangup Separation Separation Separation Separation	0.63	6.3 3.7 3.3 2.9 2.3 1.3	2.25 0.00 0.50 1.00 3.00 0.75	3.00	N/A	N/A	
OH454	S 2275 E 140	08/27/03	08/27/03		1	0	6.5 6.1 5.9 5.6 5.1 4.1 3.9 1.6 0.6	Separation Separation/clay Hairline fracture Hairline fracture Hairline fracture Hairline to vertical Hairline fracture Separation Vertical crack to 7"	0.16	6.5 6.1 5.9 5.6 5.1 4.1 3.9 1.6 0.6	0.25 0.38 N/A N/A N/A N/A N/A 3.00 N/A	N/A	N/A	
OH468	S 2640 E 140	03/29/04	03/29/04	4	0	7.0 5.9 5.7 5.6 4.9 4.6 0.9 0.9	Separation Separation Separation Hangup Separation Hangup Offset Separation	0.57	7.0 5.9 5.7 5.6 4.9 4.6 0.9 0.9	0.13 0.13 0.13 0.00 0.13 0.00 0.50 2.50	3.00	N/A	N/A	
OH502	S 2639 E 140	03/29/04	03/29/04	3	0	7.0 5.9 5.5 0.9	Separation Separation Separation Separation	0.43	7.0 5.9 5.5 0.9	0.75 0.50 0.38 3.00	3.00	N/A	N/A	
OH500	S 2850 E 140	02/20/04	02/20/04		2	0	6.5 5.5 2.1 1.0	FZ Top FZ Bottom Separation Separation	0.36	6.5 5.5 2.1 1.0	12.00 2.00 3.00	N/A N/A N/A N/A	N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>East 140 - Continued</b>													
OH501	S 3000 E 140	02/20/04	02/20/04	2	0	5.8 3.10 2.25 0.8	Separation Hangup Separation Separation	0.35	5.8 3.10 2.25 0.8	5.00 0.00 2.50 2.00	3.00	N/A	N/A
OH493	S 3180 E 140	01/13/04	05/27/04		2	0 5.3 4.8 0.6	Hangup Separation Separation Separation	0.40	5.3 5.0 4.8 0.6	0.00 0.50 0.25 1.00	3.00	N/A	N/A
OH451	S 3310 E 140	08/28/03	08/28/03	0	0	5.5	Separation	0.00	5.5	0.13	3.00	N/A	N/A
<b>West 30</b>													
OH455	S 2913 W 17	08/28/03	08/28/03	0	0	6.0	Separation	0.00	6.0	0.25	3.00	N/A	N/A
OH456	S 2950 W 30	08/28/03	08/28/03		1	0 5.5 5.5 1.0	Offset Separation Separation	0.18	5.5 5.5 1.0	0.13 0.25 0.25	3.00	4	N/A
OH463	S 3079 W 17	09/03/03	09/03/03		2	0 10.7 7.1 5.8 1.4	Separation Separation Separation Separation	0.28	10.7 7.1 5.8 1.4	0.25 0.25 0.50 1.00	3.00	N/A	N/A
OH465	S 3200 W 30	09/03/03	09/03/03			6.0 5.5	Rough spot Rough spot		6.0 5.5	N/A N/A	3.00	N/A	N/A
OH449	S 3314 W 18	08/28/03	08/28/03	0	0	5.6	Separation	0.00	5.6	0.13	3.00	N/A	N/A
<b>West 170</b>													
OH441	S 2750 W 170	08/18/03	09/18/03	2	0	5.8 5.5 4.5	Separation Separation Separation	0.34	5.8 5.5 4.5	0.50 1.00 0.25	3.00	N/A	N/A
OH442	S 2820 W 170	08/18/03	08/18/03		0	0 6.8	Rough spot Separation	0.00	6.8 5.5	N/A 0.25	3.00	N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>West 170 - Continued</b>													
OH443	S 2914 W 170	08/18/03	04/12/04			12.8 6.8 6.2 3.7 3.0 2.8 2.2 0.4	Rough spot Rough spot Rough spot Separation Separation FZ Top FZ Bottom Separation	1.35	12.8 6.8 6.2 3.7 3.0 2.8 2.2 0.4	0.60 1.00 5.00 2.00	3.00	N/A	N/A
				3	1								
OH444	S 3000 W 170	08/18/03	08/18/03			5.5 0	Offset Separation	0.00	5.5	0.08 0.25	3.00	3	N/A
OH445	S 3079 W 170	08/18/03	08/18/03	2	0	5.3 5.1 0.3	Separation Offset Separation	0.38	5.3 5.1 0.3	0.06 0.50 0.50	3.00	N/A 17 N/A	N/A
OH446	S 3198 W 170	08/28/03	08/28/03	0	0	5.5	Hangup	0.00	5.5	0.00	3.00	N/A	N/A
OH447	S 3314 W 170	08/28/03	08/28/03	0	0	5.6	Separation	0.00	5.6	0.25	3.00	N/A	N/A
<b>South 2750</b>													
OH460	S 2750 W 100	09/03/03	09/03/03			6.0 1 0	Offset Separation Separation	0.17	6.0 6.0 0.6	0.13 0.38 0.50	3.00	4	N/A
<b>South 3080</b>													
OH462	S 3082 W 91	09/03/03	09/03/03	0	0	6.0	Separation	0.00	6.0	0.50	3.00	N/A	N/A
OH464	S 3080 E 65	09/03/03	09/03/03	1	0	5.3 4.1	Separation Separation	0.19	5.3 4.1	0.25 0.25	3.00	N/A	N/A
OH503	S 3080 E 230	04/12/04	04/12/04			---	No features	N/A	---	---	3.00	N/A	N/A
<b>South 3310</b>													
OH448	S 3316 W 95	08/28/03	08/28/03	0	0	5.7	Hangup	0.00	5.7	0.00	3.00	N/A	N/A
OH450	S 3310 E 65	08/28/03	08/28/03			5.7 0 0	Hangup Offset Hangup	0.00	5.7 5.4 5.0	0.00 0.06 0.00	3.00	N/A 2 N/A	N/A
						4.0	Rough spot		4.0	N/A	N/A	N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-1 (Continued)**  
**Observation Borehole Fractures and Offset Data Summary**

Hole	Location	Initial Inspection Date	Recent Inspection Date	Fr <sup>1</sup>	FZ <sup>2</sup>	Beam Height (ft)	Feature	Fracture Density <sup>3</sup>	Feature Depth (ft)	Feature Magnitude (in)	Hole Diameter (in)	Hole Closure (%)	Offset Rate (in/yr)
<b>South 3310 - Continued</b>													
OH452	S 3310 E 230	08/28/03	08/28/03			5.9	Hangup		5.9	0.00	3.00	N/A	N/A
						5.7	Offset/Clay H		5.7	0.13		4	N/A
				1	0	5.7	Separation	0.18	5.7	0.50		N/A	N/A
						5.4	Rough spot		5.4	N/A		N/A	N/A
						5.2	Hangup		5.2	0.00		N/A	N/A
						5.0	Rough spot		5.0	N/A		N/A	N/A
						4.2	Hangup		4.2	0.00		N/A	N/A
						2.0	Rough spot		2.0	N/A		N/A	N/A
						0.7	Hangup		0.7	0.00		N/A	N/A
						0.4	Hangup		0.4	0.00		N/A	N/A
<b>North End</b>													
OH492	N 780 E 140	01/09/04	01/09/04			6.0	Hangup		6.0	0.00	3.00	N/A	N/A
OH483	N 940 E 140	01/07/04	02/04/04	0	0	6.5	Separation	0.00	6.5	0.25	3.00	N/A	N/A
OH484	N 1265 E 140	01/07/04	02/04/04			---	No features	N/A	---	---	3.00	N/A	N/A
OH485	N 1400 E 140	01/07/04	01/07/04	0	0	6.5	Offset	0.00	6.5	0.25	3.00	8	N/A
OH491	N 620 E 0	01/09/04	01/09/04			6.0	Offset		6.0	0.25	3.00	8	N/A
						0	0	6.0	Separation	0.00	6.0	0.38	N/A
OH490	N 780 E 0	01/09/04	05/27/04			7.6	Top of Anhydrite		7.6	N/A	3.00	N/A	N/A
						7.1	Bottom of Anhydrite		7.1	N/A		N/A	N/A
						6.5	Hangup		6.5	0.00		N/A	N/A
				0	0	6.0	Offset Clay H	0.00	6.0	0.25		8	0.66
						5.8	Hangup		5.8	0.00		N/A	N/A
						1.2	Stringer		1.2	N/A		N/A	N/A
						0.8	Stringer		0.8	N/A		N/A	N/A
						0.5	Stringer		0.5	N/A		N/A	N/A
OH489	N 940 E 0	01/09/04	01/09/04	0	0	6.0	Offset	0.00	6.0	0.25	3.00	8	N/A
OH488	N 1100 E 0	01/07/04	01/07/04			6.3	Rough spot		6.3	N/A	3.00	N/A	N/A
OH487	N 1266 E 0	01/07/04	01/07/04	0	0	4.8	Hangup	0.00	4.8	0.00	3.00	N/A	N/A
OH486	N 1400 E 0	01/07/04	05/27/04			6.9	Top of Anhydrite		6.9	N/A	3.00	N/A	N/A
						0	0	6.5	Separation	0.00	6.5	0.25	N/A
						6.2	Bottom of Anhydrite		6.2	N/A		N/A	N/A
						6.1	Hangup		6.1	0.00		N/A	N/A
						5.6	Rough spot		5.6	N/A		N/A	N/A

<sup>1</sup> Fr = Number of fractures in immediate roof beam

<sup>2</sup> Number of fracture zones in immediate roof beam

<sup>3</sup> Fracture Density = (Fr + 2 FZ) / Beam Height

**Table 7-2**  
**Summary of New Boreholes**

Hole	Northing	Easting	Location	Drill Date	Depth (feet)	Diameter (inches)	Purpose of Hole
OH146-2	7858	7048	S1829-E153	6/15/04	17.70	3	Observation
OH147-2	7858	7053	S1829-E158	6/15/04	17.60	3	Observation
OH 391	7736	7351	S1951-E456	7/22/03	20.0	3	Observation
OH 392	7734	7343	S1953-E448	7/22/03	21.3	3	Observation
OH 393	8073	7346	S1614-E451	7/22/03	20.3	3	Observation
OH 394	8074	7329	S1613-E434	7/22/03	23.3	3	Observation
OH 401	6855	7416	S2832-E521	8/6/03	17.60	3	Observation
OH 402	6777	7415	S2910-E520	8/6/03	17.40	3	Observation
OH 402-1	6777	7410	S2910-E515	6/9/04	10.2	3	Observation
OH 402-2	6777	7420	S2910-E525	6/9/04	10.2	3	Observation
OH 403	6689	7415	S2998-E520	6/9/04	20.10	3	Observation
OH 404	6854	7551	S2833-E656	8/6/03	17.70	3	Observation
OH 405	6771	7552	S2916-E657	8/6/03	19.00	3	Observation
OH 406	6689	7551	S2998-E656	8/6/03	19.10	3	Observation
OH 407	6857	7685	S2830-E790	8/6/03	20.80	3	Observation
OH 408	6777	7685	S2910-E790	8/6/03	16.60	3	Observation
OH 409	6697	7685	S2990-E790	9/3/03	20.90	3	Observation
OH 410	6852	7819	S2835-E924	9/4/03	21.20	3	Observation
OH 411	6777	7815	S2910-E920	9/4/03	21.20	3	Observation
OH 412	6673	7818	S3014-E923	9/4/03	26.20	3	Observation
OH 413	6857	7955	S2830-E1060	11/19/03	25.00	3	Observation
OH 414	6777	7955	S2910-E1060	11/5/03	25.00	3	Observation
OH 415	6697	7955	S2990-E1060	11/5/03	25.00	3	Observation
OH 416	6857	8085	S2830-E1190	11/19/03	20.00	3	Observation
OH 417	6777	8085	S2910-E1190	11/19/03	20.00	3	Observation
OH 418	6697	8085	S2990-E1190	11/19/03	20.00	3	Observation
OH 419	6855	8215	S2832-E1320	12/18/03	20.00	3	Observation
OH 420	6765	8216	S2922-E1321	12/18/03	20.00	3	Observation
OH 421	6689	8216	S2998-E1321	12/18/03	20.00	3	Observation
OH 422	6862	7195	S2825-E300	8/6/03	20.8	3	Observation
OH 423	6797	7195	S2890-E300	8/6/03	17.7	3	Observation
OH 424	6737	7195	S2950-E300	8/6/03	16.0	3	Observation
OH 425	6667	7195	S3020-E300	8/6/03	19.5	3	Observation
OH 426	6606	8215	S3081-E1320	12/18/03	20.0	3	Observation
OH 428	6939	7549	S2748-E654	8/6/03	20.20	3	Observation
OH 429	6939	7819	S2748-E924	9/18/03	21.30	3	Observation
OH 430	6941	7955	S2746-E1060	9/18/03	20.30	3	Observation
OH 431	6605	7549	S3082-E654	8/6/03	22.00	3	Observation
OH 432	6606	7816	S3081-E921	9/3/03	25.70	3	Observation
OH 433	6608	7997	S3079-E1102	9/8/03	21.00	3	Observation
OH 438	6939	7421	S2748-E526	7/30/03	19.70	3	Observation
OH 439	6937	7684	S2750-E789	9/3/03	9.00	3	Observation
OH 440	6605	7418	S3082-E523	7/30/03	20.30	3	Observation
OH 441	6937	6725	S2750-W170	7/15/03	21.80	3	Observation
OH 442	6867	6725	S2820-W170	7/15/03	12.50	3	Observation
OH 443	6773	6725	S2914-W170	7/15/03	22.80	3	Observation
OH 444	6687	6725	S3000-W170	7/15/03	15.20	3	Observation
OH 445	6608	6725	S3079-W170	7/15/03	19.60	3	Observation
OH 446	6489	6725	S3198-W170	7/15/03	23.50	3	Observation

**Table 7-2 (Continued)**  
**Summary of New Boreholes**

Hole	Northing	Easting	Location	Drill Date	Depth (feet)	Diameter (inches)	Purpose of Hole
OH 447	6373	6725	S3314-W170	7/15/03	26.00	3	Observation
OH 448	6371	6800	S3316-W95	7/15/03	21.60	3	Observation
OH 449	6373	6877	S3314-W18	7/15/03	21.20	3	Observation
OH 450	6377	6960	S3310-E65	7/15/03	20.40	3	Observation
OH 451	6377	7035	S3310-E140	7/15/03	20.30	3	Observation
OH 452	6377	7125	S3310-E230	7/15/03	19.70	3	Observation
OH 453	6377	7195	S3310-E300	7/15/03	20.50	3	Observation
OH 454	7412	7035	S2275-E140	8/1/03	14.60	3	Observation
OH 455	6774	6878	S2913-W17	7/21/03	18.50	3	Observation
OH 456	6737	6865	S2950-W30	7/23/03	22.20	3	Observation
OH 457	6427	7195	S3260-E300	8/1/03	20.60	3	Observation
OH 458	6487	7195	S3200-E300	8/1/03	20.00	3	Observation
OH 459	6547	7195	S3140-E300	8/1/03	20.00	3	Observation
OH 460	6937	6795	S2750-W100	9/2/03	21.60	3	Observation
OH 461	6605	7684	S3082-E789	9/3/03	25.70	3	Observation
OH 462	6605	6804	S3082-W91	9/2/03	21.80	3	Observation
OH 463	6608	6878	S3079-W17	9/2/03	20.60	3	Observation
OH 464	6607	6960	S3080-E65	9/2/03	22.10	3	Observation
OH 465	6487	6865	S3200-W30	9/2/03	21.60	3	Observation
OH 466	6607	7876	S3080-E981	9/8/03	20.80	3	Observation
OH 467	6605	7950	S3082-E1055	9/8/03	20.60	3	Observation
OH 468	7047	7035	S2640-E140	3/29/04	19.90	3	Observation
OH 480	6941	8090	S2746-E1195	9/18/03	20.50	3	Observation
OH 481	6940	8211	S2747-E1316	9/19/03	20.40	3	Observation
OH 482	7905	7035	S1782-E140	10/2/03	20.00	3	Observation
OH 483	10627	7035	N940-E140	1/7/04	20.00	3	Observation
OH 484	10952	7035	N1265-E140	1/7/04	20.10	3	Observation
OH 485	11087	7035	N1400-E140	1/7/04	20.10	3	Observation
OH 486	11087	6895	N1400-E0	1/7/04	20.00	3	Observation
OH 487	10953	6895	N1266-E0	1/7/04	20.10	3	Observation
OH 488	10787	6895	N1100-E0	1/7/04	20.10	3	Observation
OH 489	10627	6895	N940-E0	1/9/04	19.90	3	Observation
OH 490	10467	6895	N780-E0	1/9/04	20.10	3	Observation
OH 491	10307	6895	N620-E0	1/9/04	19.90	3	Observation
OH 492	10467	7035	N780-E140	1/9/04	20.00	3	Observation
OH 493	6507	7035	S3180-E140	1/12/04	20.10	3	Observation
OH 494	6937	7885	S2750-E990	1/13/04	21.30	3	Observation
OH 495	6939	8014	S2748-E1119	1/13/04	25.70	3	Observation
OH 496	6937	7872	S2750-E977	2/5/04	20.00	3	Observation
OH 497	6947	7872	S2740-E977	2/5/04	6.00	3	Observation
OH 498	9272	7035	S415-E140	2/16/04	19.30	3	Observation
OH 499	9177	7035	S510-E140	2/16/04	19.00	3	Observation
OH 500	6837	7035	S2850-E140	2/20/04	19.00	3	Observation
OH 501	6687	7035	S3000-E140	2/20/04	18.10	3	Observation
OH 502	7048	7035	S2639-E140	3/29/04	7.80	3	Observation
OH 503	6607	7125	S3080-E230	4/12/04	19.10	3	Observation
OH 504	6607	7850	S3080-E955	4/22/04	10.0	3	Observation
OH 505	6607	7900	S3080-E1005	4/22/04	10.0	3	Observation
OH 506	6607	7950	S3080-E1055	4/22/04	10.0	3	Observation




Figure 7-1  
Panel 2 Room 1 Roof Fractures




Figure 7-2  
Panel 2 Room 2 Roof Fractures




Figure 7-3  
Panel 2 Room 3 Roof Fractures




Figure 7-4  
Panel 2 Room 4 Roof Fractures




Figure 7-5  
Panel 2 S2180, E500-E790, Roof Fractures




Figure 7-6  
Panel 2 S2180, E790-E1075, Roof Fractures




Figure 7-7  
Panel 2 S2520, E505-E795, Roof Fractures




Figure 7-8  
Panel 2 S2520, E795-E1080, Roof Fractures




Figure 7-9  
Panel 3 Room 1 Roof Fractures




Figure 7-10  
Panel 3 Room 2 Roof Fractures




Figure 7-11  
Panel 3 Room 3 Roof Fractures




Figure 7-12  
Panel 3 Room 4 Roof Fractures




Figure 7-13  
Panel 3 Room 5 Roof Fractures




Figure 7-14  
Panel 3 Room 6 Roof Fractures




Figure 7-15  
Panel 3 Room 7 Roof Fractures




Figure 7-16  
Panel 3 S2750, E500-E772, Roof Fractures




Figure 7-17  
Panel 3 S2750, E772-E1062, Roof Fractures




Figure 7-18  
Panel 3 S2750, E1062-E1335, Roof Fractures




Figure 7-19  
Panel 3 S3080, E500-E770, Roof Fractures




Figure 7-20  
Panel 3 S3080, E770-E1060, Roof Fractures




Figure 7-21  
Panel 3 S3080, E1060-E1335, Roof Fractures